

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007578/AGA3Q2

Date: 01/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100453619

Claimant
Vehicle No : SMR6079K **Insured Vehicle No :** SCV8000X

Date of Loss: 21/07/2020 Nature of Claim: TP Claim No: 0249532237SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR6079K	Engine No:	2ZR2F87790
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU40J052689
Reg. Date:	15/01/2020 (Man. Year: 2019)	Odometer:	6707 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,552.21	1,616.20	4,936.01	75.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	960.00	3,320.00	77.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	10,832.21	2,576.20	8,256.01	76.22
Approved Total (Overridden) (\$)		2,000.00		
(S\$)	10,832.21	2,000.00	8,832.21	81.54
+ GST 7.00/7.00% (S\$)	758.25	140.00	618.25	81.54
Nett Amount (S\$)	11,590.46	2,140.00	9,450.46	81.54
+ Car Rental (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		2,416.45		

INSPECTION

Date of Assignment: 22/07/2020

Date Inspected: 28/07/2020 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Not Necessary	1,211.40 FL	*- FL
2	1		*TAILGATE EMBLEM PRIUS-C	Not Necessary	58.35 FL	*- FL
3	1		*TAILGATE EMBLEM HYBRID	Not Necessary	65.20 FL	*- FL
4	1		*TAILGATE WEATHER STRIP	Not Necessary	298.40 FL	*- FL
5	1		*REAR BUMPER	Deformed	968.70 FL	*524.00 FL
6	1		*REAR BUMPER REFLECTOR LH	Cracked	85.20 FL	*85.20 FL
7	1		*REAR BUMPER DIFFUSER	Cut	694.30 FL	*694.30 FL
8	1		*REAR BUMPER CENTER BOTTOM GARNISH	Not Necessary	646.90 FL	*- FL
9	2		*REAR BUMPER SIDE RETAINER	Necessary	139.60 FL	*139.60 FL
10	1		*TAILLAMP LH	Cracked	596.80 FL	*596.80 FL
11	1		*TAILLAMP LOWER BRACKET LH	Not Necessary	69.30 FL	*- FL
12	1		*REAR FENDER LH	Repair	1,432.50 FL	*- FL
13	1		*REAR FENDER GLASS LH	Not Necessary	546.40 FL	*- FL
14	2		*REAR FENDER INNER COWLING	Not Necessary	248.20 FL	*- FL
15	1		*REAR FENDER AIR VENT LH	Cracked	61.70 FL	*61.70 FL
16	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
17	1		*SET REAR BUMPER CENTER BOTTOM GARNISH CLIP	Not Necessary	50.00 FS	*- FS
18	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
19	1		*SET TAILGATE INNER BOARD CLIP	Not Necessary	60.00 FS	*- FS
20	1		*SET TAILLAMP CLIP	Necessary	40.00 FS	*10.00 FS
21	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	60.00 FS	*- FS
22	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
23	1		*REAR FENDER GLASS SEALANT LH	Not Necessary	80.00 FS	*- FS
24	1		*REAR FENDER GLASS INNER SHIELD LH	Not Necessary	60.00 FS	*- FS
25	1		*REAR FENDER GLASS SOLAR FILM	Not Necessary	180.00 FS	*- FS
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*REAR WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
28	1		*SET REAR END PANEL TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
29	1		*REVERSE SENSOR	Not Necessary	220.00 FS	*- FS
					Sub Total (\$\$)	8,332.95 2,141.60
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,780.74 525.40
					Total Parts (\$\$)	6,552.21 1,616.20

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,400.00	400.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	400.00
3	TUFF COAT	New	250.00	30.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	250.00	50.00
6	REMOVE AND REFIX REAR FENDER GLASS LH	New	100.00	0.00
7	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	New	120.00	0.00
8	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
9	TRANSFER TAILGATE MECHANISM	New	80.00	0.00
10	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
11	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	0.00
12	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			4,280.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >