

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20007580/KBA3Q2

**Date:** 08/09/2020

### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D18MCV0001290_01
<b>Claimant Vehicle No :</b>	SKQ3928J	<b>Insured Vehicle No :</b>	GBA8235H
Date of Loss:	21/07/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0001342

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKQ3928J		
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Engine No:	1NZX546751
Reg. Date:	04/06/2007 (Man. Year: 2007)	Chassis No:	MR053HY9305001899
Colour:	Metallic Black	Odometer:	150342 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Kumho 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,558.14	2,248.16	309.98	12.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,800.00	1,550.00	250.00	13.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,358.14</b>	<b>3,798.16</b>	<b>559.98</b>	<b>12.85</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,358.14</b>	<b>3,000.00</b>	<b>1,358.14</b>	<b>31.16</b>
<b>+ Loss of Use (6.0 x S\$80.00/day) (S\$)</b>		480.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>3,487.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,450.00</b>		

### INSPECTION

Date of Assignment:	22/07/2020	
Date Inspected:	22/07/2020 Inspected At:	Sin Motor Repairs (HQ) BLK 176 Sin Ming Drive,, Sin Ming Auto Care #05-07 Singapore 575721
Estimated Period of Repair:	6.0 days	

---

**Adjuster:** KENNETH KONG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**SPECIAL REMARKS**

Market value (estimate) \$15K less LTA Rebate (estimate) \$9,446 = Net value \$5,554 (estimate)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Aug 2020)
<b>Parts:</b>	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKQ3928J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	496.04 FL	*496.04 FL
2	1		*REAR BOOT	Bent	653.91 FL	*653.91 FL
3	2		*REAR TAILLAMP	Cracked	485.16 FL	*485.16 FL
4	1		*EMBLEM E	Necessary	44.53 FL	*44.53 FL
5	1		*EMBLEM G	Necessary	54.16 FL	*54.16 FL
6	1		*TOYOTA LOGO	Necessary	48.31 FL	*48.31 FL
7	1		*OUTER HANDLE	Cracked	159.21 FL	*159.21 FL
8	1		*INNER LOCK TOP	Dented	86.48 FL	*86.48 FL
9	1		*INNER LOCK LOWER	Distorted	28.99 FL	*28.99 FL
10	1		*REAR BUMPER REFLECTOR	Not Necessary	163.26 FL	*- FL
11	2		*REAR SIDE RETAINER	Distorted	145.68 FL	*145.68 FL
12	1		*REAR END PANEL	Bent	421.62 FL	*421.62 FL
13	1		*REAR BOOT RUBBER (50%)	Distorted / Dented	120.13 FS	*80.09 FS
14	1		*REAR BUMPER SENSOR	Not Necessary	90.00 FL	*- FL
15	1		*REAR BUMPER SENSOR ASSY	Necessary	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,277.48</b>	<b>2,904.18</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	719.34	656.02
<b>Total Parts (\$\$)</b>	<b>2,558.14</b>	<b>2,248.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGE FOR KNOCKING ,DISMANTLING AND REINSTALLATION OF REAR BUMPER /BOOT COVER /END PANEL /SENSOR /INNER LOCK /HANDLE AND ETC	New	800.00	700.00
2	LABOUR CHARGES FOR SPRAY PAINTING ON REAR BUMPER /BOOT /END PANEL AND TOUCH UP/POLISH ON NECESSART PARTS	New	850.00	800.00
3	LABOUR CHARGES TO DETECH BUMPER SENSOR	New	150.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,800.00</b>	<b>1,550.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >