

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20007581/R1DA3Q2

**Date:** 09/10/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900159583

**Claimant**  
**Vehicle No :** SFF8028R **Insured Vehicle No :** SMP1754M

**Date of Loss:** 19/07/2020 **Nature of Claim:** TP **Claim No:** 1438616663SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFF8028R</b>		
Make & Model:	VOLVO XC60, 2.0 T5 (A)	Engine No:	B4204T111141200
Reg. Date:	19/06/2015 (Man. Year: 2014)	Chassis No:	YV1DZ40LDF2704729
Colour:	Gold	Odometer:	78166 km
Engine Capacity:	1969 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,654.55	3,570.29	84.26	2.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	730.00	550.00	42.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>4,934.55</b>	<b>4,300.29</b>	<b>634.26</b>	<b>12.85</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,400.00</b>		
<b>Nett Amount (\$\$)</b>	<b>4,934.55</b>	<b>3,400.00</b>	<b>1,534.55</b>	<b>31.10</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 22/07/2020

Date Inspected: 24/07/2020 Inspected At: Xinya Auto Services Pte Ltd (HQ)  
Blk 1002, #01-75, Bukit Merah Lane 3  
Singapore 159719

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,624.00 FL	*1,624.00 FL
2	1		*FRONT BUMPER RETAINER LH	*Check	88.70 FL	*- FL
3	1		*HEADLAMP LH	Scratched	1,669.20 FL	*1,669.20 FL
4	1		*FOG LAMP	Scratched	465.00 FL	*465.00 FL
					<b>Sub Total (S\$)</b>	<b>3,846.90</b>
					<b>- List Item Discount on L Items 5.00/5.00% (S\$)</b>	<b>192.35</b>
					<b>Total Parts (S\$)</b>	<b>3,654.55</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REPLACE FRONT BUMPER ,HEADLAMP AND TO PANEL BEAT & ALIGN	New	800.00	300.00
2	TO PUTTY & SPRAY PAINT FRONT BUMPER	New	400.00	400.00
3	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,280.00</b>	<b>730.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >