

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007582/GEA3Q2

Date: 02/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800115093

Claimant
Vehicle No : SKR5302X **Insured Vehicle No :** SME3646L

Date of Loss: 19/07/2020 Nature of Claim: TP Claim No: 4239373183SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR5302X		
Make & Model:	HYUNDAI ACCENT, 1.4 (A)	Engine No:	G4LCFU340364
Reg. Date:	13/02/2015 (Man. Year: 2015)	Chassis No:	KMHCT41BTFU860159
Colour:	Silver	Odometer:	131232 km
Engine Capacity:	1368 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	417.40	252.40	165.00	39.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	590.00	760.00	56.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,767.40	842.40	925.00	52.34
+ GST 7.00/7.00% (\$\$)	123.72	58.97	64.75	52.34
Nett Amount (\$\$)	1,891.12	901.37	989.75	52.34
+ Car Rental (1.0 x S\$90.00/day) (\$\$)		90.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		998.82		

INSPECTION

Date of Assignment: 21/07/2020

Date Inspected: 23/07/2020 Inspected At:

VAG Singapore Pte Ltd (HQ)
48 Toh Guan Road East, #05-155
Enterprise Hub
Singapore 608586

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Buckled	315.50 FL	*315.50 FL
2	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	113.75 FL	*- FL
3	10		*FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FL	*- FL
4	1		*SUNDERIES	Not Necessary	50.00 FS	*- FS
					Sub Total (S\$)	509.25 315.50
					- List Item Discount on L Items 20.00/20.00% (S\$)	91.85 63.10
					Total Parts (S\$)	417.40 252.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TUFF KOTE	New	50.00	40.00
2	REMOVE AND REFIT FRONT FENDER RH AND OTHER ASSOCIATED COMPONENTS	New	600.00	200.00
3	SURFACE PREPARATION,SPRAY PAINT AND POLISH FRONT FENDER RH (INTERIOR & EXTERIOR) FRONT DOOR RH (INTERIOR & EXTERIOR) AND OTHER ASSOCIATED COMPONENTS	New	600.00	350.00
4	PERFORM DIAGNOSTIC FULL WHEEL ALIGNMENT	New	100.00	0.00
Gross Labour Cost (\$\$)			1,350.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >