

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20007583/GDA3Q2**Date:** 09/09/2020**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900106588

**Claimant**  
**Vehicle No :** SLK6851X **Insured Vehicle No :** SMM1249X

Date of Loss: 20/07/2020 Nature of Claim: TP Claim No: 7558066107SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLK6851X**  
 Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGGU014353  
 Reg. Date: 24/01/2017 (Man. Year: 2016) Chassis No: KMHD841CMHU331936  
 Colour: Silver Odometer: 41370 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55Z R16 Rear Tyre Size: 205/55Z R16  
 Front Left Side: Kumho 6 mm Rear Left Side: Kumho 6 mm  
 Front Right Side: Kumho 6 mm Rear Right Side: Kumho 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,305.68	7,000.08	1,305.60	15.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,660.00	1,050.00	610.00	36.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>9,965.68</b>	<b>8,050.08</b>	<b>1,915.60</b>	<b>19.22</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	697.60	563.51	134.09	19.22
<b>Nett Amount (\$\$)</b>	<b>10,663.28</b>	<b>8,613.59</b>	<b>2,049.69</b>	<b>19.22</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment: 22/07/2020

Date Inspected: 22/07/2020 Inspected At: Vin's Motor Pte Ltd (Sin Ming)  
 160 Sin Ming Drive, #03-03, Sin Ming  
 AutoCity  
 Singapore 575722

Estimated Period of Repair: 4.0 days

**Adjuster:** XING GUO QIANG**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Bent	1,910.00 FL	*1,910.00 FL
2	1		*FRONT RH BONNET HINGE	Not Necessary	49.10 FL	*- FL
3	1		*FRONT LH BONNET HINGE	Not Necessary	49.10 FL	*- FL
4	1		*FRONT BONNET LOCK	Not Necessary	129.90 FL	*- FL
5	1		*FRONT RH HEADLAMP	Cracked	1,750.40 FL	*1,750.40 FL
6	1		*FRONT LH HEADLAMP	Cracked	1,750.40 FL	*1,750.40 FL
7	1		*FRONT GRILLE WITH OUTER CHROME MOULDING	Cut	1,082.90 FL	*1,082.90 FL
8	1		*FRONT BUMPER	Deformed	474.00 FL	*474.00 FL
9	1		*FRONT BUMPER TOP RUBBER	Cut	32.40 FL	*32.40 FL
10	1		*FRONT BUMPER NO.PLATE GARNISH	Cut	21.40 FL	*21.40 FL
11	1		*FRONT BUMPER TOWING COVER	Not Necessary	18.10 FL	*- FL
12	1		*FRONT BUMPER LOWER LIP	Scratched	48.90 FL	*48.90 FL
13	1		*FRONT RH BUMPER FLOG LAMP	Not Necessary	265.10 FL	*- FL
14	1		*FRONT RH BUMPER FLOG LAMP COVER	Not Necessary	115.40 FL	*- FL
15	1		*FRONT RH BUMPER SIDE RETAINER	Not Necessary	28.00 FL	*- FL
16	1		*FRONT LH BUMPER SIDE RETAINER	Not Necessary	28.00 FL	*- FL
17	1		*FRONT BUMPER SPONGE	Cracked	110.70 FL	*110.70 FL
18	1		*FRONT BUMPER REINFORCEMENT	Bent	695.80 FL	*695.80 FL
19	1		*FRONT SUPPORT PANEL	*Check	949.30 FL	*- FL
20	1		*FRONT SUPPORT PANEL TOP COVER	Deformed	78.10 FL	*78.10 FL
21	1		*AIRCON CONDENSOR	Cut	745.10 FL	*745.10 FL
22	1		*FRONT NO PLATE	Missing	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,372.10</b>	<b>8,740.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	2,066.42	1,740.02
<b>Total Parts (\$\$)</b>	<b>8,305.68</b>	<b>7,000.08</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REFILL AIRCOND GAS	New	120.00	120.00
2	TO REPLACE AND RESET HEADLAMP SYSTEM	New	180.00	30.00
3	TO REPAIR FRONT DAMAGE	New	580.00	450.00
4	TO SPRAY PAINTING	New	780.00	450.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,660.00</b>	<b>1,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >