



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 6293J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SET SIDE MIRROR	SCRATCHED	85.00	85.00
1	HANDLE BAR	BENT	120.00	120.00
1	BRAKE LEVER (RIGHT)	SERVICEABLE	55.00	-
1	BRAKE LEVER (LEFT)	SCRATCHED	55.00	55.00
2	RIGHT BALANCER	SCRATCHED	45.00	45.00
2	STEERING CONE	SERVICEABLE	220.00	-
1	STEERING UNDER BARCKET	SERVICEABLE	180.00	-
1	FRONT FORK ASSY	BENT	680.00	600.00
1	FRONT FENDER	CRUSHED	128.00	128.00
2	FRONT FENDER REAR COVER	CRUSHED	108.00	108.00
2	FRONT WHEEL SHAFT	SERVICEABLE	180.00	-
2	FRONT RIM	SERVICEABLE	580.00	-
1	LEFT FOOT UNDER COVER	SCRATCHED	120.00	120.00
1	RIGHT FOOT UNDER COVER	SERVICEABLE	120.00	-
2	RIGHT PILLION FOOT REST	SERVICEABLE	120.00	-
1	MUFFLER COVER	SERVICEABLE	110.00	-
1	LEFT SIGNAL ASSY FRONT	BROKEN	85.00	85.00
2	LEFT REAR SIGNAL ASSY	MISSING	85.00	85.00
2	CLUTCH OUTER COVER	SERVICEABLE	145.00	-
1	MAIN STAND	SERVICEABLE	180.00	-
1	SET SIDE STAND	SERVICEABLE	120.00	-
1	FRONT CENTRAL INNER COVER	SERVICEABLE	140.00	-
1	LEFT OUTER LOWER COVER	BROKEN	120.00	120.00
1	RIGHT OUTER LOWER COVER	BROKEN	120.00	120.00
1	FUEL TANK UNDER COVER	SERVICEABLE	140.00	-
2	HEADLIGHT ASSY	CRACKED	650.00	250.00
1	HEADLIGHT LEFT COVER	SCRATCHED	120.00	120.00
2	HEADLIGHT RIGHT COVER	SERVICEABLE	120.00	-
2	FRONT HEAD OUTER BRACKET	SERVICEABLE	140.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-507.10	-204.10
			4,563.90	1,836.90
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT TYRE (SN)	SERVICEABLE	220.00	-
1	SET BODY STICKER (SN)	NECESSARY	400.00	100.00
1	NO. PLATE (FRONT) (SN)	SERVICEABLE	25.00	-
1	NO. PLATE (REAR)	BENT	25.00	25.00
			670.00	125.00
	<u>LABOUR</u>			
	TOWING.		80.00	50.00
	FRONT RIM ALIGNMENT.		120.00	60.00
	TO ALIGN BODY FRAME.	NOT NECESSARY	300.00	-
	WORKMANSHIP.		550.00	200.00
	TO RESPRAY ON FRONT FENDER, HEADLAMP CROWING, SIDE FAIRING AND ACCIDENT AFFECTED AREA.		500.00	100.00
			1,550.00	410.00
	GRAND TOTAL		6,783.90	2,371.90
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS1/ASM20007589/Qsf3s2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.