

LBS AUTOMOTIVE APPRAISAL PTE. LTD.

Co. Reg. No. 201408536E

Block 8 Kensington Park Drive #01-07

Singapore 557323

Telephone: 62832866, 62816690 Facsimile: 62818748, 62832166

AUTOMOBILE INSPECTION REPORT

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

OUR REFERENCE: LBS/AXA/TP/PRI/20/02/P019

REFERENCE: THIRD PARTY CLAIM- PRE-REPAIR INSPECTION

VEHICLE NUMBER : FBN 6293J POLICY NUMBER : N.A.
ACCIDENT DATE : 30.12.2019 CLAIM NUMBER : S0M02FNV - SJY 4246G

PARTICULARS OF DAMAGED VEHICLE:

MAKE : YAMAHA AEROX GDR155 MODEL : 2018
COLOUR : BLACK MILEAGE KM : -
ENGINE CAPACITY : 155CC V.I.N. : MH3SG4610JJ154038

STATIC CHECKS: GENERAL CONDITION: GOOD

STEERING: SERVICEABLE

BRAKES: SERVICEABLE

TYRE CONDITIONS: SIZE: FRONT-140/70R14 REAR-110/80R14

FRONT : 40%

REAR : 30%

Percentages denote the remaining estimated life of the tyre threads

ESTIMATED NORMAL PERIOD FOR REPAIR: 04 WORKING DAYS
IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORIZED REPAIRS.

GENERAL DAMAGES

The impacts were confined to the front and near side rear broadside portions of the motorbike.

REMARKS

No estimate provided by workshop.

Economical Repair Value \$6,799.00 (Estimated Market Value \$9,000.00 less LTA rebate \$2,201.00)

Basing on visual inspection of the damage during the pre-repair survey, we opined the estimated repair cost to be in the region of \$2,000.00.

This pre-repair inspection was conducted on a "WITHOUT PREJUDICE" basis.

Vehicle inspected by : Mr Stan See Chew Seng

Date of Inspection : 10.02.2020

Surveyed at : E Motoring Pte Ltd

Date of Report : 09.04.2020