

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007590/AKS3Q2

Date: 30/12/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900255228

**Claimant**  
**Vehicle No :** SKA250J **Insured Vehicle No :** SJR8458Y

Date of Loss: 19/07/2020 Nature of Claim: TP Claim No: 0878923204SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA250J**

Make & Model: NISSAN GTR, 3.8 (A) Engine No: VR38003951A

Reg. Date: 20/05/2008 (Man. Year: 2008) Chassis No: R35002844

Colour: White Odometer: 34090 km

Engine Capacity: 3799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 285/35 R20 Rear Tyre Size: 285/35 R20

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 20,264.20         | 8,157.60          | 12,106.60         | 59.74         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 4,940.00          | 1,380.00          | 3,560.00          | 72.06         |
| Paintwork Labour                         | 0.00              | 0.00              | 0.00              |               |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>25,204.20</b>  | <b>9,537.60</b>   | <b>15,666.60</b>  | <b>62.16</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>7,600.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                 | <b>25,204.20</b>  | <b>7,600.00</b>   | <b>17,604.20</b>  | <b>69.85</b>  |
| <b>Global Sum Settlement (S\$)</b>       |                   | <b>0.00</b>       |                   |               |

### INSPECTION

Date of Assignment: 23/07/2020

Date Inspected: 23/07/2020 Inspected At:

Polymath Garage Pte Ltd - Kaki Bukit (HQ)  
 10 KAKI BUKIT ROAD 2, #01-21  
 FIRST EAST CENTRE  
 Singapore 417868

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                           | Deformed      | 4,860.00 FL | *4,860.00 FL |
| 2   | 1   |          | *REAR BUMPER RH SIDE REFLECTOR         | Not Necessary | 285.00 FL   | *- FL        |
| 3   | 15  |          | *REAR BUMPER CLIPS                     | Necessary     | 120.00 FL   | *30.00 FL    |
| 4   | 1   |          | *REAR BUMPER RH SIDE RETAINER          | Not Necessary | 175.00 FL   | *- FL        |
| 5   | 1   |          | *REAR BUMPER LOWER SPOILER             | Cut           | 2,774.00 FL | *2,774.00 FL |
| 6   | 1   |          | *REAR WINDSCREEN GLASS RUBBER MOULDING | Not Necessary | 417.00 FL   | *- FL        |
| 7   | 1   |          | *REAR RH FENDER                        | Repair        | 3,200.00 FL | *- FL        |
| 8   | 1   |          | *REAR RH FENDER INNER SHIELD           | Not Necessary | 265.00 FL   | *- FL        |
| 9   | 10  |          | *REAR RH FENDER INNER SHIELD CLIPS     | Not Necessary | 100.00 FL   | *- FL        |
| 10  | 1   |          | *REAR RH FENDER PETROL COVER           | Not Necessary | 288.00 FL   | *- FL        |
| 11  | 1   |          | *REAR RH KNUCKLE ARM                   | Not Necessary | 1,886.00 FL | *- FL        |
| 12  | 1   |          | *REAR RH WHEEL BEARING                 | Not Necessary | 804.00 FL   | *- FL        |
| 13  | 1   |          | *REAR RH SHOCK ABSORBER                | Not Necessary | 1,354.00 FL | *- FL        |
| 14  | 1   |          | *REAR RH UPPER ARM                     | Not Necessary | 774.00 FL   | *- FL        |
| 15  | 1   |          | *REAR RH LOWER ARM                     | Not Necessary | 703.00 FL   | *- FL        |
| 16  | 1   |          | *REAR RH CONTROL ARM                   | Not Necessary | 633.00 FL   | *- FL        |
| 17  | 1   |          | *REAR WINDSCREEN GLASS SEALANT         | Not Necessary | 80.00 FS    | *- FS        |
| 18  | 1   |          | *REAR RH SPORT RIM                     | Cut           | 2,600.00 FS | *1,200.00 FS |
| 19  | 1   |          | *REAR RH TYRE                          | Not Necessary | 750.00 FS   | *- FS        |
| 20  | 1   |          | *REAR BUMPER PROTECTOR FILM            | Necessary     | 60.00 FS    | *60.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|  |                  |                 |
|--|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>22,128.00</b> | <b>8,924.00</b> |
| <b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b> | 1,863.80         | 766.40          |
| <b>Total Parts (\$\$)</b>                                  | <b>20,264.20</b> | <b>8,157.60</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|---|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>     |   |          |                 |                 |
| 1                              | REMOVE AND REPLACE THE ABOVE LISTED PARTS ,KNOCK STRAIGHTEN AND RESHAPE ,CUT AND WELD BODY PANEL PARTS WHERE NECESSARY ,RE-POSITION AND RE-ALIGN ,REPLACEMENT PARTS TO THE ORIGINAL POSITION INCLUDING ADJUSTMENT | New      | 1,800.00        | 500.00          |
| 2                              | PUTTY AND RESPRAY ON AFFECTED AREAS AND PANELS  | New      | 1,400.00        | 600.00          |
| 3                              | CHECK WIRING AND LIGHTING SYSTEM ON AFFECTED AREAS  | New      | 120.00          | 30.00           |
| 4                              | APPLY RUST PROOFING ON AFFECTED AREAS AND PANELS  | New      | 100.00          | 50.00           |
| 5                              | REMOVE AND REPLACE REAR INNER TRIMS AND GARNISH   | New      | 350.00          | 60.00           |
| 6                              | REMOVE AND REPLACE REAR REVERSE SENSORS   | New      | 80.00           | 60.00           |
| 7                              | REMOVE AND REFIT REAR WINDSCREEN GLASS AND SEALANT  | New      | 220.00          | 0.00            |
| 8                              | REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS   | New      | 500.00          | 0.00            |
| 9                              | ADJUST AND TEST DRIVE WHEEL ALIGNMENT SYSTEM  | New      | 150.00          | 80.00           |
| 10                             | REMOVE AND REFIT FUEL TANK AND PIPES  | New      | 220.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |   |          | <b>4,940.00</b> | <b>1,380.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >