



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2005879
INV Date 27/08/2020
Reference CS/SMO20007592/Uvf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SLG 5538D
Insured Veh. XD 9354P
Claim No. CMTD2002172/AGC
Policy No.
Accident Date 23/07/2020
Inspection Date 23/07/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20007592/Uvf3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 27-08-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 9354P	Veh. Inspected	SLG 5538D
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002172/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	23/07/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA CIVIC 1.5 TURBO (A)	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MRHFC1660GT000185	Colour	SILVER
Odometer	103938	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/50 R17	YOKOHAMA	6 mm
L/H Front Tyre	215/50 R17	YOKOHAMA	6 mm
R/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm
L/H Rear Tyre	215/50 R17	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	23/07/2020	Inspection Date	23/07/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 5538D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID	DENTED / BUCKLED	820.20	531.20
1	BOOTLID OUTER GARNISH	WARPED / CRACKED	655.20	382.30
2	BOOTLID HINGES @\$166.30	TWISTED / BENT	332.60	332.60
2	BOOTLID HINGE GARNISHS @\$82.50	N/S TORN	165.00	82.50
1	BOOTLID REAR LOGO	NECESSARY	50.00	38.50
1	BOOTLID CIVIC EMBLEM	NECESSARY	105.00	40.50
1	BOOTLID "VTEC" EMBLEM	NECESSARY	98.00	38.80
1	BOOTLID INNER LOCK	BENT	99.00	99.00
1	BOOTLID WEATHERSTRIP	TORN	218.00	166.20
2	BOOTLID REFLECTORS @\$340.50	N/S SCRATCHED	681.00	210.50
1	BOOTLID "TURBO" EMBLEM	NECESSARY	33.00	33.00
1	BOOTLID INNER TRIM	NOT NECESSARY	295.00	-
1	SET BOOTLID INNER TRIM CLIPS	NOT NECESSARY	50.00	-
1	REAR BUMPER	DISTORTED	688.00	617.20
2	REAR BUMPER SIDE RETAINERS @\$35.00	BENT	70.00	70.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER LOWER SIDE BLACK GARNISHS @\$85.00	SCRATCHED	170.00	170.00
1	REAR END PANEL	BADLY DENTED	380.00	371.20
1	REAR END PANEL TOP GARNISH	TWISTED	245.00	245.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	990.10	-
1	REAR FLOOR PANEL TOP BOARD	TORN	450.00	415.00
2	TAILLAMPS @\$385.10	CRACKED	770.20	614.80
2	TAILLAMP PANELS @\$245.00	BENT	490.00	490.00
2	REAR FENDERS @\$899.10	TO REPAIR SEE LABOUR	1,798.20	-
2	REAR FENDER INNER TRIMS @\$355.10	SERVICEABLE	710.20	-
1	REAR BUMPER CENTRE BLACK GARNISH	DEFORMED	311.20	266.30
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	121.00	-
1	REAR BUMPER REINFORCEMENT	BENT	388.50	245.50

Report Ref No. CS/SMO20007592/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-	-1,102.02
			11,234.40	4,408.08
	<u>SPECIAL NETT ITEMS</u>			
1	BOOTLID SPOILER W/THIRD BRAKE LIGHT (SN)	CRACKED	1,200.00	780.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR LICENCE PLATE (SN)	BENT	50.00	40.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	200.00	-
1	REAR EXHAUST (SN)	NOT NECESSARY	1,500.00	-
1	REAR ANTENNA SENSOR (SN)	CRACKED	180.00	180.00
			3,460.00	1,250.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHNISM.		100.00	60.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX EXHAUST.	NOT NECESSARY	100.00	-
	TO SPRAY RUST PROOFING.		120.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL AND REAR FENDERS.		1,800.00	900.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			3,870.00	2,400.00
GRAND TOTAL			18,564.40	8,058.08
RECOMMENDED COST OF REPAIR SUM				7,200.00

Report Ref No. CS/SMO20007592/Uvf3n2

***NOTE: NEW PARTS REPLACEMENT**

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.