

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007595/QGS3Q2

Date: 16/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMN3123G	Insured Vehicle No :	SHA3622K
Date of Loss: 19/07/2020	Nature of Claim: TP	Claim No: MCT20070247

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN3123G		
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Engine No:	LEB5617677
Reg. Date:	31/07/2019 (Man. Year: 2018)	Chassis No:	GB71081151
Colour:	Blue	Odometer:	44016 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,231.20	6,878.72	23,352.48	77.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,805.00	3,130.00	3,675.00	54.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	37,036.20	10,008.72	27,027.48	72.98
+ GST 7.00/7.00% (\$\$)	2,592.53	700.61	1,891.92	72.98
Nett Amount (\$\$)	39,628.73	10,709.33	28,919.40	72.98
+ Loss of Use (20.0 x S\$60.00/day) (\$\$)		1,200.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		11,916.78		

INSPECTION

Date of Assignment:	23/07/2020	
Date Inspected:	23/07/2020 Inspected At:	Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	11.0 days	

Adjuster: OI SUN PIN

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2021)
Parts:	M1-MPV	HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN3123G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Crumpled	925.80 FL	*925.80 FL
2	1		*REAR BUMPER TOWING COVER	Serviceable	21.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	24.90 FL	*- FL
4	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	24.90 FL	*- FL
5	1		*REAR BUMPER UNDER COVER	Serviceable	155.00 FL	*- FL
6	1		*REAR BUMPER BRACKET LH	Broken	24.90 FL	*24.90 FL
7	1		*REAR BUMPER BRACKET RH	Broken	24.90 FL	*24.90 FL
8	1		*REAR TAILGATE	Dented	1,393.60 FL	*1,290.00 FL
9	1		*REAR TAILGATE HINGE LH	Bent	50.60 FL	*50.60 FL
10	1		*REAR TAILGATE HINGE RH	Bent	50.60 FL	*50.60 FL
11	1		*REAR TAILGATE LOCK	Jammed	248.90 FL	*248.90 FL
12	1		*REAR TAILGATE LOCK CATCH	Serviceable	27.20 FL	*- FL
13	1		*REAR TAILGATE OUTER HANDLE	Serviceable	375.50 FL	*- FL
14	1		*REAR TAILGATE OUTER HANDLE CHROME MOULDING	Serviceable	320.90 FL	*- FL
15	1		*REAR TAILGATE LOGO	Necessary	58.70 FL	*58.70 FL
16	1		*REAR TAILGATE FREED EMBLEM	Necessary	55.00 FL	*55.00 FL
17	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.00 FL	*75.00 FL
18	1		*REAR TAILGATE RUBBER	Crumpled	168.50 FL	*168.50 FL
19	1		*REAR TAILGATE INNER BOARD	Scratched	288.00 FL	*288.00 FL
20	1		*REAR TAILGATE INNER BOARD HANDLE	Crumpled	88.00 FL	*88.00 FL
21	1		*REAR TAILGATE REFLECTOR LH	Serviceable	460.00 FL	*- FL
22	1		*REAR TAILGATE REFLECTOR RH	Serviceable	460.00 FL	*- FL
23	1		*REAR TAILGATE DAMPER LH	Serviceable	135.40 FL	*- FL
24	1		*REAR TAILGATE DAMPER RH	Serviceable	135.40 FL	*- FL
25	1		*REAR TAILLAMP LH	Serviceable	680.60 FL	*- FL
26	1		*REAR TAILLAMP RH	Cracked	680.60 FL	*613.00 FL
27	1		*REAR TAILLAMP LOWER PANEL LH	Serviceable	195.70 FL	*- FL
28	1		*REAR TAILLAMP LOWER PANEL RH	Serviceable	195.70 FL	*- FL
29	1		*REAR FENDER INNER TRIM BOARD LH	Cracked	586.00 FL	*300.00 FL
30	1		*REAR FENDER INNER TRIM BOARD RH	Cracked	586.00 FL	*300.00 FL
31	1		*REAR END PANEL	Dented	623.70 FL	*480.00 FL
32	1		*REAR END PANEL -INNER	Dented	577.00 FL	*175.00 FL
33	1		*REAR END PANEL TOP GARNISH	Crumpled	115.00 FL	*115.00 FL
34	1		*REAR END PANEL KEYLESS SENSOR (INNER)	Serviceable	185.40 FL	*- FL
35	1		*REAR END PANEL KEYLESS SENSOR (OUTER)	Serviceable	210.40 FL	*- FL
36	1		*REAR CHASSIS MEMBER LH	Bent	921.90 FL	*250.00 FL
37	1		*REAR CHASSIS MEMBER RH	Bent	921.90 FL	*250.00 FL
38	1		*REAR CHASSIS FRAME	Serviceable	3,790.00 FL	*- FL
39	1		*REAR EXHAUST PIPE	Serviceable	988.00 FL	*- FL
40	1		*REAR EXHAUST SILENCER	Serviceable	950.00 FL	*- FL
41	1		*REAR EXHAUST HEATSHIELD	Serviceable	55.00 FL	*- FL
42	1		*REAR HYBRID BATTERY	Serviceable	12,800.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*REAR SPARE TYRE PANEL	Serviceable	1,256.80 FL	*- FL
44	1		*REAR SPARE TYRE BOARD	Serviceable	950.60 FL	*- FL
45	1		*REAR SPARE TYRE TOOL SPONGE	Serviceable	330.00 FL	*- FL
46	1		*REAR BUMPER INNER ABSORBER LH	Cracked	58.00 FL	*58.00 FL
47	1		*REAR BUMPER INNER ABSORBER RH	Cracked	58.00 FL	*58.00 FL
48	1		*REAR FLOOR PANEL	Dented	1,356.90 FL	*1,200.00 FL
49	1		*REAR FLOOR PANEL BOARD	Crumpled	1,210.60 FL	*588.00 FL
50	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
51	1		*REAR BUMPER CLIPS	Necessary	45.00 FS	*30.00 FS
52	1		*SET REAR BUMPER SENSORS	Shorted	260.00 FS	*200.00 FS
53	1		*REAR BUMPER TOP CHROME MOULDING	Dented	180.00 FS	*100.00 FS
54	1		*REAR TAILGATE TOP CHROME MOULDING	Necessary	180.00 FS	*100.00 FS
55	1		*REAR TAILGATE OUTER HANDLE LOWER CHROME MOULDING	Necessary	180.00 FS	*180.00 FS
56	1		*REAR TAILLAMP CLIPS LH	Serviceable	35.00 FS	*- FS
57	1		*REAR TAILLAMP CLIPS RH	Necessary	35.00 FS	*20.00 FS
58	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
59	1		*REAR CAMERA	Serviceable	450.00 FS	*- FS
60	2		*REAR EXHAUST MOUNTING	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	37,406.50	8,425.90
- List Item Discount on L Items 20.00/20.00% (\$\$)	7,175.30	1,547.18
Total Parts (\$\$)	30,231.20	6,878.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT CARPET AND TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION	New	120.00	50.00
2	TO DO UP INTERIOR CLEANING AND CHEMICAL WASH	New	200.00	0.00
3	TO REMOVE AND REFIT REAR CUSHION FITTINGS	New	80.00	0.00
4	TO REMOVE AND REFIT ,STRAIGHTEN AND RE-ADJUST EXHAUST PIPE AND REAR EXHAUST SILENCER AND MOUNTINGS	New	180.00	0.00
5	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	80.00	30.00
6	TO TRANSFER REAR TAILGATE	New	80.00	60.00
7	TO DISMANTLE AND REFIT REAR WINDSCREEN GLASS	New	100.00	100.00
8	TO DISCONNECT AND RECONNECT ,CHECK ELECTRICAL WIRING HARNESS WIRE ,SOCKETS ,REPLACE DAMAGED PARTS	New	50.00	30.00
9	TO PULL ,STRAIGHTEN CHASSIS FRAME AND REALIGN	New	1,000.00	0.00
10	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS ,STRAIGHTEN ,KNOCK OUT ,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS .TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	3,300.00	1,600.00
11	TO CARRY OUT BODY CAVITY PRESERVATION	New	70.00	30.00
12	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS	New	45.00	30.00
13	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS ,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER ,CLEANING AND SANDING OF SURFACES ,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	1,500.00	1,200.00
Gross Labour Cost (\$)			6,805.00	3,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >