

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007612/R1QF3E2

Date: 11/09/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN18358119011
Claimant Vehicle No :	SLZ2654X	Insured Vehicle No :	YP9676K
Date of Loss:	20/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202509/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ2654X	Engine No:	4J11YB7230
Make & Model:	MITSUBISHI OUTLANDER, 2.0 (A)	Chassis No:	GF7W0401656
Reg. Date:	27/04/2018 (Man. Year: 2018)	Odometer:	36194 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,127.00	4,624.00	2,503.00	35.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,220.00	2,250.00	2,970.00	56.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,347.00	6,874.00	5,473.00	44.33
+ GST 7.00/7.00% (S\$)	864.29	481.18	383.11	44.33
Nett Amount (S\$)	13,211.29	7,355.18	5,856.11	44.33

INSPECTION

Date of Assignment:	24/07/2020	
Date Inspected:	17/08/2020 Inspected At:	Cycle & Carriage Automotive Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2020)
Parts:	M1-SUV	MITSUBISHI OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ2654X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HOOD	Bent	975.00 FS	*975.00 FS
2	7		*CLIP,HOOD INSULATOR	Necessary	21.00 FS	*21.00 FS
3	1		*HINGE,HOOD LH	Serviceable	68.00 FS	*- FS
4	4		*TAPE,TAILGATE	Serviceable	16.00 FS	*- FS
5	1		*HEADLAMP ASSY,LH	Broken	2,125.00 FS	*2,125.00 FS
6	1		*FACE,FR BUMPER	Torn	1,060.00 FS	*1,060.00 FS
7	1		*BRACKET,FR BUMPER SIDE,LH	Serviceable	18.00 FS	*- FS
8	1		*GARNISH,FR BUMPER,LH	Cracked	75.00 FS	*75.00 FS
9	1		*GARNISH,FR BUMPER SIDE LH CHROME TOP	Not Necessary	48.00 FS	*- FS
10	1		*GARNISH,FR BUMPER SIDE LH CHROME CTR	Not Necessary	220.00 FS	*- FS
11	1		*GARNISH,FR BUMPER SIDE LH CHROME LWR	Not Necessary	112.00 FS	*- FS
12	1		*COVER,FR BUMPER	Not Necessary	280.00 FS	*- FS
13	1		*REINFORCEMENT,FR BUMPER	Not Necessary	503.00 FS	*- FS
14	1		*BAR,FR BUMPER GUARD	Not Necessary	130.00 FS	*- FS
15	1		*REINFORCEMENT,FR BUMPER	Not Necessary	134.00 FS	*- FS
16	1		*REINF,FR BUMPER SIDE LH	Not Necessary	60.00 FS	*- FS
17	1		*GRILLE ASSY,RADIATOR	Not Necessary	569.00 FS	*- FS
18	1		*MOULDING,FR BUMPER LH	Not Necessary	116.00 FS	*- FS
19	1		*MOULDING,FR WHEEL ARCH,LH	Not Necessary	199.00 FS	*- FS
20	1		*LAMP ASSY,FOG,FR LH	Scratched	348.00 FS	*348.00 FS
21	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
					Total Parts (\$\$)	7,127.00 4,624.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER & BONNET.REPAIR FRT SUPPORT PNL & LHF FENDER	New	2,750.00	1,100.00
2	RESPRAY FRT BUMPER,BONNET,LHF FENDER & FRT SUPPORT PNL	New	2,100.00	840.00
3	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	50.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
5	APPLY ANTI CORROSION ON AFFECTED AREAS	New	120.00	80.00
Gross Labour Cost (S\$)			5,220.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >