

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 197701469G	Owner Name & Vehicle Info			
Invoice Name & Address	Cust No/Name	KCV08414/Chng Wei Long (Zhuang Weiliang)		
Chng Wei Long (zhuang Weiliang	Reg No/Reg Date			
Blk 293B Compassvale Crescent #07-61	Date In/Mileage			
	Chassis no	GF7W0401656		
Singapore 542293		4J11YB7230		
Contact No Mobile: 97777967	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE		
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK		

- Pote/Time Printed CSE Operator	WIP No	
Account No Terms Date/Time Printed	a 55083	
OCMODO(1) [35] 20/0//2020/ 10:11	Qty Unit Price Disc	% Amount
Description of Goods / Services		100 2750.00
E PNT88000		,
RENEW FRT BUMPER & BONNET REPAIR FRT SUPPORT PNL & LHF FENDER		84U 2100.00
		7 10 2/
RESPRAY FRT BUMPER , BONNET , LHF FENDER & FRT SUPPORT PNL		30 50.00
× 5400000		
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM		200.00
A 10028901		
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST		80 100/00
USING HI-SCAN PRO TEST	П	80 120.00
APPLY ANTI CORROSION ON AFFECTED AREAS	745	20 50.00
M SUNDRY		100 30.00
Sundries L OGUUUU	1.00 975.00 00	975.00
1 HOOD 51		0.00 21.00
CLIP HOOD INSULATOR NO.	7.00	0.00 68.00
HINGE HOOD, LH ? X30C	1.00	0.00 16.00
M TAPE TAILGATE X	7.00	0.00 2125.00
M HEADLAMP ASSY, LH DO	1.00 1060.00 0	
M FACE, FR BUMPER tom - 2 JSVC	1.00 18.00 0	0.00 18.00
BRACKET, FR BUMPER SIDE, LH		0.00 75.00
GARNISH, FR BUMPER, LH CHOME TOP ? *11	1.00 48.00 0	0.00 48.00
GARNISH, FR BUMPER SIDE LH CHROME TOP ? KAN GARNISH, FR BUMPER SIDE LH CHROME CTR ? KAN	1.00	0.00 220.00
GARNISH, FR BUMPER SIDE LH CHROME LWR 7 KAA		0.00 112.00
GARNISH, FR BUMPER SIDE LIT CHRONE LINE . 7		00.00
M COVER, FR BUMPER 7 KAN M REINFORCEMENT, FR BUMPER 7 KAN		00.00 503.00
BAR, FR BUMPER GUARD ?	1.00 130.00 (
DETNICODCEMENT ED RIMPER 7. KAN	1.00	00.00 134.0
REINFORCEMENT, R BONNER 7 100	1.00	00.00
100	1.00	00.00 569.0
M GRILLE ASSY, RADIATOR M MOULDING, FR BUMPER, LH	1.00	00.00
M MOULDING, FR WHEEL ARCH, LH 7 XAA	1.00 199.00	00.00 199.0

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renew the rubber seal or other repair requiring the removal of the windscreen.

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



RIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

: 197701469G Invoice Name & Address	Owner Name & Vehicle Info				
	Cust No/Name	KCV08414/Chng Wei Long (Zhuang Weiliang)			
Chng Wei Long (zhuang Weiliang	Reg No/Reg Date	te SLZ2654X / 27/04/201			
Blk 293B Compassvale Crescent	Date In/Mileage	/ 0			
#07-61	Chassis No	GF7W0401656			
Singapore 542293	Engine No	4J11YB7230			
Contact No Mobile: 97777967	Make/Model	MIT/OUTLANDER 2.0 2WD CVT ELEGANCE			
	Colour/Trim	DO1 COSMIC BLUE / BK BLACK			

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	Tall Inches	
	Cash	20/07/2020/ 18:14	QUE	261 / Edwin Caina		55083		
		Description of Good	s / Service	OS .	Qty 1.00	Unit Price 348.00		Amount 348.00
LAMP ASSY,	FUG,FK	Ln SCA-)	th •	KK Auto Consultants hence not be Repairer of the following: To resurvey before/after spray painting To display damaged part(s) during restarts prices are subject to confirmation. Third party survey is on a "Without Pro-	lify g urvey n			
			Si	No illegal modification(s) is allowed Supplementary item(s) must be resun is subject to final approval from Insura cknowledged by Repairer ignature:	veyed and			
		CONVETOR SIGNATU	RASUL RE: 1	Hp 900/1068				
		DATE: 17/08/2 REMARKS:	day	1710				
nfirm & accep	pted by	hery	20 for	- pint				
				1081 (7007)	7% GST on		ett .00	12,347. 864.
					1	otal Paya	able	13,211

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

0 - 5 0