

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Koh Ming Shao

Date: 25 Aug 2020

**Preliminary Advice**

|                    |                                                                                                                                  |                         |              |
|--------------------|----------------------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLQ8155C                                                                                                                       | Accident Date           | : 22/07/2020 |
| TP Vehicle No      | : SJQ9132K                                                                                                                       | Assignment Date         | : 23/07/2020 |
| Make               | : TOYOTA CAMRY                                                                                                                   | Est. Duration of Repair | : 3          |
| Date of Inspection | : 27/07/2020                                                                                                                     |                         |              |
| Inspection At      | : TICK HAI MOTOR & WELDING SERVICES - KAKI BUKIT (HQ)<br>BLK 1 KAKI BUKIT AVE 6, #01-54 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                         |              |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |          |              |
|-----------------------------|----------|--------------|
| Repairer's Estimate (Gross) | :S\$     | 2,894.49     |
| Revised Amount              | :S\$     | 1,521.17     |
| Check Items (Estimated)     | :S\$     | 0.00         |
| Total                       | :S\$     | 1,521.17     |
| <br>Lump Sum Repair         | <br>:S\$ | <br>1,200.00 |

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical for repair  
 ( ) The vehicle is not economical for repair  
 ( ) Part-by-Part repair  
 ( X ) Lump Sum repair
- ( X ) The above survey was conducted on a 'without prejudice' basis.