

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007616/EPA3Q2

Date: 31/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLH949D	Insured Vehicle No :	SH8761S
Date of Loss: 19/07/2020	Nature of Claim: TP	Claim No: MCT20070300

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH949D		
Make & Model:	HONDA HR-V, 1.5 DX CVT (A)	Engine No:	L15B4530656
Reg. Date:	24/10/2016 (Man. Year: 2016)	Chassis No:	JHMRU1810GX200654
Colour:	White	Odometer:	62293 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,572.17	556.91	2,015.26	78.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	1,810.00	1,930.00	51.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,312.17	2,366.91	3,945.26	62.50
+ GST 7.00/7.00% (S\$)	441.85	165.68	276.17	62.50
Nett Amount (S\$)	6,754.02	2,532.59	4,221.43	62.50
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		2,712.59		

INSPECTION

Date of Assignment:	23/07/2020	
Date Inspected:	27/07/2020	Inspected At:
		Kah Motor Co Sdn Bhd (Ubi)
		15 Ubi Road 4
		Singapore 408610
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Aug 2020)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH949D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLIGHT ASSY,R	Not Necessary	1,401.75 FS	*- FS
2	1		*CLIP BUMPER (14 PCS)	Necessary	24.15 FS	*24.15 FS
3	1		*BEAM COMP FR BUMPER	Not Necessary	171.60 FS	*- FS
4	1		*SPOILERFR BUMPER AIR	Not Necessary	42.22 FS	*- FS
5	1		*FACE ,FR BUMPER	Cut	365.92 FS	*365.92 FS
6	1		*BEAMR.FR.BUMPER UPPER	Broken	20.17 FS	*20.17 FS
7	1		*GARNISH ,FR FOG LIGHT	Not Necessary	16.57 FS	*- FS
8	1		*SPACER.R.FR BUMPER SIDE	Broken	8.47 FS	*8.47 FS
9	1		*PROTECTOR ,R.FR. WHEEL ARCH	Cut	118.20 FS	*118.20 FS
10	1		*PANEL COMP ,R.FR.FENDER	Repair	303.90 FS	*- FS
11	1		*FENDER ASSYR.FR.INNER	Not Necessary	69.22 FS	*- FS
12	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
Total Parts (S\$)					2,572.17	556.91

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	140.00	120.00
2	STRAIGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS	New	1,800.00	650.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,800.00	1,040.00
Gross Labour Cost (S\$)			3,740.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >