

ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396 Email: absolute.app.svcs@gmail.com

Vehicle Inspection Report

To:

Lumens Auto Pte Ltd

C/o:

160 Sin Ming Drive #05-16

Sin Ming AutoCity (S) 575722

Report No: AAS/2020/117

Date of report:

05.05.2020

Date of request:

11.04.2020

Date of inspection:

11.04.2020

Date of accident:

01.04.2020

Claim type: Third Party Claim

Particulars of affected vehicle:

Registration no:

Make/Model:

SME8657Y

Toyota Prius Plus (A)

Year of registration:

2018

Metallic Blue

Odometer:

Engine Capacity:

166350 km 1798 cc

Engine no:

2ZR0C61925

Chassis no:

JTDZS3EU10J034568

Condition of tires:

Front Left:

Colour:

6mm

Make: Rear Left: Firenza 6mm

Make:

Firenza

Front Right:

Make:

Make:

Firenza 6mm

Rear Right:

Firenza

6mm

Type of road wheel:

Alloy

(The above represent the remaining life of the tire thread)

Pre-accident condition (Static tests only)

General Bodywork

Paintwork

Handbrake

Footbrake

Steering Apparent engine modification : Good

: Good

: In order

: In order

: In order

: Nil

The Assignment

The inspection was conduct at M/s.

Toh Motor Enterprise

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

Assessment

Repairer's estimate:

7,488.71

Revised estimate:

5,905.92

Recommended reserve:

4,700.00 (Lump sum)

Estimated normal duration of repairs: 5 Working days



ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722 Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SME8657Y

Report No: AAS/2020/117

W/O PREJUDICE

Point of impact

At the RHS portion.

General description of damages

The RH wing mirror, RHF door, RHR door, RH door centre pillar, etc.

Other parts were also found damaged. (See schedule for details)

Recommendation

The estimate cost of repair submitted by M/s Toh Motor Enterprise as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$5,905.92

Conclusion

The repairer has agreed to undertake the repair at a lumpsum of SGD \$4,700.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of $\underline{5}$ working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a 'Without Prejudice' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes $\underline{44}$ photographs.

Your Faithfully Absolute Appraisal Services Pte Ltd





ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7596 Email: absolute.app.svcs@gmail.com

Voh	icle No: SME8657Y	_			P	L NI AAG	/2000	/4.4.7
	praisement Schedule				Re	port No: AAS	/2020	/117
^ ^	Parts Description	Otro	Condition		D =	noincule For	D	· 15
1	RHF door	Qty 1	Dented			pairer's Est		vised Est
2	RHF door black tape	1			\$	1,426.70	\$	1,426.70
3	RHF door frame garnish	1	Necessary Necessary	Ē	\$	41.60	\$.	41.60
4	RHF door outer handle	1	Dented/Cut		\$	85.90	\$	85.90
5	RHF door key insert	1	Dented/Cut		\$	202.65	\$	202.65
6	RHF door key insert cover	1			\$	200.35	\$	200.35
7	RHF door handle bracket	1	Dented/Cut Cracked		\$	23.70	\$	23.70
8	RHF door lock	1			\$	79.60	\$	79.60
9	RHF door weather-strip	1	Distorted		\$	570.71	\$	570.71
10	RHF door glass regulator	1	Necessary		\$	184.70	\$	184.70
11	RHF door glass regulator motor		Distorted		\$	294.50	\$	294.50
12	RHF door speaker	1	Malfunctioned		\$	593.79	\$	593.79
13	RHF door trim board	1	Loop Broken		\$	155.70	\$	155.70
14	RHR door	1	Serviceable		\$	971.40		
15	RHR door black tape	1	Dented		\$	1,312.45	\$	1,312.45
	RHR door frame garnish	1	Necessary		\$	45.90	\$	45.90
16	9	1	Necessary		\$	85.90	\$	85.90
17	RHR weather-strip	1	Necessary		\$	179.67	\$	179.67
18	RHR door hinge	2	Distorted/Repair	\$ 78.34	\$	156.68		4
19	RHR door checker	1	Serviceable		\$	195.64		-
20	RH wing mirror assy	1	Cracked		\$	577.40	\$	577.40
				Total:	\$	7,384.94	\$	6,061.22
				-25%	\$	1,846.24	\$	1,515.31
				List total:	\$	5,538.71	\$	4,545.92
S/N	Labour Description				Rei	pairer's Est	Rev	vised Est
1 Check lightings & wirings.					\$	50.00	\$	30.00
2	Transfer RHF & RHR door compo	nents.			\$	250.00	\$	200.00
3	Anti rust proofing on affected par				\$	100.00		30.00
4 Renew damaged parts, panel beat reform affected panels, align affected portion.						750.00	\$	
5 Conduct spray painting on affected panels.						\$	500.00	
J	conduct spray painting on ancest	u pane			\$	800.00	\$	600.00
				Labour Total:	\$	1,950.00	\$	1,360.00
				Grand Total:	\$	7,488.71	\$	5,905.92

The final adjusted lump sum amount is \$4,700.00

Under normal circumstances, the repair should be completed within a reasonable period of 5 working days.

44 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.





















