



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

---

**Vehicle Inspection Report**

To: Lumens Auto Pte Ltd  
C/o: 160 Sin Ming Drive #05-16  
Sin Ming AutoCity (S) 575722

Date of report: 05.05.2020  
Date of request: 11.04.2020  
Date of inspection: 11.04.2020  
Date of accident: 01.04.2020  
Claim type: Third Party Claim

Report No: AAS/2020/117

**Particulars of affected vehicle:**

Registration no: SME8657Y  
Make/Model: Toyota Prius Plus (A)  
Year of registration: 2018  
Colour: Metallic Blue

Odometer: 166350 km  
Engine Capacity: 1798 cc  
Engine no: 2ZR0C61925  
Chassis no: JTDZS3EU10J034568

**Condition of tires:**

Front Left: 6mm  
Make: Firenza  
Rear Left: 6mm  
Make: Firenza

Front Right: 6mm  
Make: Firenza  
Rear Right: 6mm  
Make: Firenza

Type of road wheel: Alloy (The above represent the remaining life of the tire thread)

**Pre-accident condition (Static tests only)**

General Bodywork : Good  
Paintwork : Good  
Handbrake : In order  
Footbrake : In order  
Steering : In order  
Apparent engine modification : Nil

**The Assignment**

The inspection was conducted at M/s. Toh Motor Enterprise  
160 Sin Ming Drive #05-16  
Sin Ming AutoCity (S) 575722

(Subsequent inspection was conducted)

**Assessment**

Repairer's estimate: \$ 7,488.71  
Revised estimate: \$ 5,905.92  
Recommended reserve: \$ 4,700.00 (Lump sum)

Estimated normal duration of repairs : 5 Working days



**ABSOLUTE APPRAISAL SERVICES PTE LTD**  
**LOSS ADJUSTERS & MOTOR APPRAISERS**

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SME8657Y

Report No: AAS/2020/117

**W/O PREJUDICE**

**Point of impact**

At the RHS portion.

**General description of damages**

The RH wing mirror, RHF door, RHR door, RH door centre pillar, etc.

Other parts were also found damaged. (See schedule for details)

**Recommendation**

The estimate cost of repair submitted by M/s Toh Motor Enterprise as per schedule attached have been revise and scrutinize. We list the breakdown of our findings and recommendation as per attached.

Our adjusted amount for the cost of repair is SGD \$5,905.92

**Conclusion**

The repairer has agreed to undertake the repair at a lumpsum of SGD \$4,700.00

Under normal circumstances, the repair of the damaged vehicle should be completed within a reasonable period of 5 working days.

We have **Not Authorised** and/or instruction to the repairer to proceed with the repairs. This inspection was conducted entirely on a '**Without Prejudice**' basis.

We are pleased to advise that the inspection was carried out accordingly and hereby submit our appraisal report which includes 44 photographs.

Your Faithfully  
Absolute Appraisal Services Pte Ltd



Nicky Seah  
Automobile Appraiser  
MSAAA / MSMCTA



# ABSOLUTE APPRAISAL SERVICES PTE LTD LOSS ADJUSTERS & MOTOR APPRAISERS

160 Sin Ming Drive #05-16 Sin Ming AutoCity (S) 575722

Mobile: 9688-0413 Fax: 6266-7396

Email: absolute.app.svcs@gmail.com

Vehicle No: SME8657Y

Report No: AAS/2020/117

## Appraisement Schedule

| S/N     | Parts Description              | Qty | Condition        | Repairer's Est | Revised Est     |
|---------|--------------------------------|-----|------------------|----------------|-----------------|
| 1       | RHF door                       | 1   | Dented           | \$ 1,426.70    | 1324.70 ✓       |
| 2       | RHF door black tape            | 1   | Necessary        | \$ 41.60       | \$ 41.60 ✓      |
| 3       | RHF door frame garnish         | 1   | Necessary        | \$ 85.90       | \$ 85.90 ✓      |
| 4       | RHF door outer handle          | 1   | Dented/Cut       | \$ 202.65      | \$ 202.65 ✓     |
| 5       | RHF door key insert            | 1   | Dented           | \$ 200.35      | SVC \$ 200.35 X |
| 6       | RHF door key insert cover      | 1   | Dented/Cut       | \$ 23.70       | \$ 23.70 ✓      |
| 7       | RHF door handle bracket        | 1   | Cracked          | \$ 79.60       | \$ 79.60 ✓      |
| 8       | RHF door lock                  | 1   | Distorted        | \$ 570.71      | \$ 570.71 ✓     |
| 9       | RHF door weather-strip         | 1   | Necessary        | \$ 184.70      | \$ 184.70 ✓     |
| 10      | RHF door glass regulator       | 1   | Distorted        | \$ 294.50      | \$ 294.50 ✓     |
| 11      | RHF door glass regulator motor | 1   | Malfunctioned    | \$ 593.79      | \$ 593.79 ✓     |
| 12      | RHF door speaker               |     | Loop Broken      | \$ 155.70      | \$ 155.70 ✓     |
| 13      | RHF door trim board            | 1   | Serviceable      | \$ 971.40      | -               |
| 14      | RHR door                       | 1   | Dented           | \$ 1,312.45    | 1201.50 ✓       |
| 15      | RHR door black tape            | 1   | Necessary        | \$ 45.90       | \$ 45.90 ✓      |
| 16      | RHR door frame garnish         | 1   | Necessary        | \$ 85.90       | \$ 85.90 ✓      |
| 17      | RHR weather-strip              | 1   | Necessary        | \$ 179.67      | SVC \$ 179.67 X |
| 18      | RHR door hinge                 | 2   | Distorted/Repair | \$ 78.34       | \$ 156.68       |
| 19      | RHR door checker               | 1   | Serviceable      | \$ 195.64      | -               |
| 20      | RH wing mirror assy            | 1   | Cracked          | \$ 577.40      | \$ 577.40 ✓     |
| 5468.25 |                                |     |                  | Total:         | \$ 7,384.94     |
| -25%    |                                |     |                  | -25%           | \$ 1,846.24     |
| 4101.18 |                                |     |                  | List total:    | \$ 5,538.71     |
|         |                                |     |                  |                | \$ 6,061.22     |
|         |                                |     |                  |                | \$ 1,515.31     |
|         |                                |     |                  |                | \$ 4,545.92     |

## S/N Labour Description

| S/N | Labour Description  | Repairer's Est | Revised Est     |
|-----|---|----------------|-----------------|
| 1   | Check lightings & wirings.  | \$ 50.00       | \$ 30.00 ✓      |
| 2   | Transfer RHF & RHR door components.   | \$ 250.00      | 100 ✓ \$ 200.00 |
| 3   | Anti rust proofing on affected panels.  | \$ 100.00      | \$ 30.00 ✓      |
| 4   | Renew damaged parts, panel beat reform affected panels, align affected portion. | \$ 750.00      | \$ 500.00 ✓     |
| 5   | Conduct spray painting on affected panels.                                      | \$ 800.00      | 500 ✓ \$ 600.00 |

1160

Labour Total: \$ 1,950.00 \$ 1,360.00

Grand Total: \$ 7,488.71 \$ 5,905.92

The final adjusted lump sum amount is \$4,700.00

Under normal circumstances, the repair should be completed within a reasonable period of 5 working days.

P - 4101.18

L - 1160

5261.18

L/S - 4208.94

= 4200

4 repair days

44 Photographs were taken at the time of inspection.

Disclaimer: This report is intended for the exclusive use of the address solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by Absolute Appraisal Service Pte Ltd for any reliance on this report by any third party.









































