

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20007624/ECF3E2

Date: 09/09/2021

REFERENCE

Insured/Claimant:	CHUA CHEE HWEE MATTHIAS	Policy No:	1900022368	
Date of Loss:	22/07/2020	Nature of Claim:	OD	Claim No: 8123695881SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJL6813A	Engine No:	CVK073345
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF53KA010195
Reg. Date:	28/02/2019 (Man. Year: 2018)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R19	Rear Tyre Size:	245/35Z R19
Front Left Side:	Continental 5 mm	Rear Left Side:	Continental 5 mm
Front Right Side:	Continental 5 mm	Rear Right Side:	Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	102,794.00	64,955.36	37,838.64	36.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	41,704.00	26,894.00	14,810.00	35.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	144,498.00	91,849.36	52,648.64	36.44
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	143,698.00	91,049.36	52,648.64	36.64
+ GST 7.00/7.00% (S\$)	10,058.86	6,373.46	3,685.40	36.64
Nett Amount (S\$)	153,756.86	97,422.82	56,334.04	36.64

INSPECTION

Date of Assignment:	24/07/2020		
Date Inspected:	24/07/2020	Inspected At:	24 BENOI SECTOR Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	35.0 days		

Adjuster: CHEN TSUE YEE

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Broken	2,251.00 FS	*1,800.80 FS
2	1	*FRONT BUMPER FIXING PARTS	Necessary	402.00 FS	*321.60 FS
3	1	*FRONT BUMPER SECURING STRIP	Necessary	70.00 FS	*27.84 FS
4	1	*FRONT BUMPER GRILLE CENTRE	Broken	194.00 FS	*154.80 FS
5	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Broken	225.00 FS	*180.00 FS
6	1	*FRONT BUMPER SPOILER	Missing	529.00 FS	*423.20 FS
7	1	*FRONT AIR GUIDE - RH	Missing	62.00 FS	*49.52 FS
8	1	*RADIATOR GRILLE	Broken	2,300.00 FS	*1,840.00 FS
9	2	*FRONT SENSOR SUPPORT - LH / RH	Necessary	102.00 FS	*80.80 FS
10	1	*RADIATOR GRILLE COVER - UPPER	Not Necessary	187.00 FS	*- FS
11	1	*FRONT AIR GUIDE GRILLE - RH	Missing	468.00 FS	*374.40 FS
12	1	*FRONT FANFARE - RH	Not Necessary	124.00 FS	*- FS
13	1	*FAN FARE SPRING SHACKLE - RH	Bent	29.00 FS	*22.56 FS
14	1	*FRONT SENSOR - OUTER	Missing	193.20 FS	*193.20 FS
15	1	*FRONT SENSOR - INNER (NPA)	Not Necessary	0.00 FS	*- FS
16	4	*FRONT SENSOR SEAL RING	Necessary	14.00 FS	*10.88 FS
17	1	*FRONT BUMPER WIRING	Broken	505.00 FS	*403.60 FS
18	1	*FRONT BUMPER REINFORCEMENT BAR	Bent	795.00 FS	*635.60 FS
19	1	*FRONT FOAM FILLER PIECE	Broken	123.00 FS	*98.40 FS
20	1	*FRONT BUMPER COVER	Crushed	126.00 FS	*100.40 FS
21	1	*FRONT BUMPER GUIDE SECTION - RH	Broken	36.00 FS	*28.48 FS
22	1	*FRONT BUMPER BRACKET - RH	Broken	212.00 FS	*169.60 FS
23	1	*SIGN CAUTION STICKER	Necessary	14.00 FS	*10.80 FS
24	1	*AIR CONDITIONER STICKER	Necessary	8.00 FS	*5.68 FS
25	1	*FRONT LOCK CARRIER BRACKET	Broken	136.00 FS	*108.40 FS
26	1	*FRONT LOCK CARRIER SUPPORT - LH / RH	Necessary	56.00 FS	*44.48 FS
27	1	*FRONT FENDER - RH	Dented	1,048.00 FS	*838.40 FS
28	1	*FRONT FENDER ATTACHMENT PARTS	Necessary	53.00 FS	*41.68 FS
29	1	*FRONT FENDER CLOSING ELEMENT - RH	Broken	73.00 FS	*58.40 FS
30	1	*FRONT FENDER BRACKET - RH	Bent	35.00 FS	*27.60 FS
31	5	*FRONT FENDER POP RIVET	Necessary	16.00 FS	*12.80 FS
32	1	*FRONT FENDER CENTRE BRACKET - RH	Bent	57.00 FS	*45.52 FS
33	1	*FRONT FENDER UPPER BRACKET - RH	Bent	35.00 FS	*27.60 FS
34	1	*FRONT FENDER BRACE - RH	Bent	117.00 FS	*93.60 FS
35	1	*FRONT FENDER BRACKET DEFORMATION - RH	Bent	49.00 FS	*38.80 FS
36	1	*FRONT FENDER COVER - RH	Cut	18.00 FS	*14.08 FS
37	1	*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	33.00 FS	*- FS
38	1	*FRONT WHEEL HOUSING LINER - RH	Torn	272.00 FS	*217.20 FS
39	1	*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - RH	Necessary	90.00 FS	*71.68 FS
40	1	*FRONT WHEEL SPOILER - RH	Missing	73.00 FS	*57.76 FS
41	1	*FRONT WHEEL SPOILER OUTER - RH	Missing	36.00 FS	*28.24 FS
42	1	*FRONT WHEEL SPOILER BRACKET TRIM - RH	Missing	24.00 FS	*18.56 FS
43	1	*FRONT STONE CHIP GUARD - RH	Necessary	50.00 FS	*39.92 FS
44	1	*BONNET	Dented	2,817.00 FS	*2,253.60 FS
45	1	*BONNET ATTACHMENT PARTS	Not Necessary	121.00 FS	*- FS
46	2	*BONNET HINGE - LH / RH	Bent	830.00 FS	*663.20 FS
47	2	*BONNET IMPACT PROTECTION - LH / RH	Necessary	55.00 FS	*43.36 FS
48	1	*BONNET IMPACT PROTECTION - CENTER	Necessary	27.00 FS	*21.52 FS
49	1	*BONNET NOISE INSULATION	Crushed	339.00 FS	*271.20 FS
50	1	*FRONT FENDER TOP LEDGE COVER - RH INNER	Cracked	72.00 FS	*56.88 FS
51	1	*FRONT FENDER TOP LEDGE COVER - RH UPPER	Broken	35.00 FS	*27.92 FS
52	1	*FRONT FENDER TOP LEDGE COVER - RH LOWER	Missing	16.00 FS	*12.16 FS
53	2	*BONNET GAS FILLED STRUT	Not Necessary	235.00 FS	*- FS
54	1	*BONNET STRICKER - RH	Bent	50.00 FS	*39.44 FS
55	1	*BONNET LID LOCK	Not Necessary	212.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
56	1	*BONNET BOWDEN CABLE - CENTER	Not Necessary	57.00 FS	*- FS
57	1	*BONNET BOWDEN CABLE COVER	Not Necessary	10.00 FS	*- FS
58	1	*CABLE FOR BONNET	Not Necessary	57.00 FS	*- FS
59	1	*BONNET RELEASE LEVER	Not Necessary	13.00 FS	*- FS
60	1	*BONNET LID LOCK CABLE	Not Necessary	73.00 FS	*- FS
61	1	*PLENUM CHAMBER COVER	Not Necessary	96.00 FS	*- FS
62	1	*PLENUM CHAMBER COVER	Not Necessary	96.00 FS	*- FS
63	1	*FRONT FENDER TOP SUPPORT LOWER - RH	Dented	248.00 FS	*198.00 FS
64	1	*FRONT FENDER TOP SUPPORT UPPER - RH	Dented	214.00 FS	*171.20 FS
65	1	*LED HEADLIGHT - RH	Broken	7,812.00 FS	*6,249.60 FS
66	1	*LED HEADLIGHT POWER MODULE - RH	Shorted	749.00 FS	*599.20 FS
67	1	*LED HEADLIGHT CONTROL UNIT - RH	Shorted	742.00 FS	*593.60 FS
68	1	*LED WITH HEAT SINK	Shorted	1,140.00 FS	*912.00 FS
69	1	*HOSE FOR HEADLIGHT	Missing	36.00 FS	*28.08 FS
70	1	*LIFT CYLINDER FOR HEADLIGHT - RH	Broken	196.00 FS	*156.80 FS
71	1	*LIFT CYLINDER BRACKET - RH	Missing	15.00 FS	*11.60 FS
72	1	*HOSE FOR LIFT CYLINDER - RH	Torn	85.00 FS	*68.00 FS
73	1	*FRONT LOCK CARRIER	Bent	1,004.00 FS	*803.20 FS
74	1	*FRONT LOCK CARRIER SUPPORT	Not Necessary	38.00 FS	*- FS
75	1	*A/C CONDENSER	Not Necessary	615.00 FS	*- FS
76	1	*REFRIGERANT LINE FOR A/C COMPRESSOR	Not Necessary	165.00 FS	*- FS
77	1	*REFRIGERANT LINE FOR CUT OFF POINT	Not Necessary	336.00 FS	*- FS
78	1	*REFRIGERANT BRACKET	Necessary	18.00 FS	*14.40 FS
79	1	*EXTERNAL TEMPERATURE SENSOR	Not Necessary	56.00 FS	*- FS
80	1	*CHARGE AIR COOLER	Not Necessary	580.00 FS	*- FS
81	1	*CHARGE AIR COOLER PRESSURE HOSE	Not Necessary	353.00 FS	*- FS
82	1	*EXHAUST GAS TURBOCHARGE	Not Necessary	5,344.00 FS	*- FS
83	1	*RADIATOR	Not Necessary	837.00 FS	*- FS
84	4	*RADIATOR COOLANT	Necessary	177.00 FS	*141.44 FS
85	1	*RADIATOR FAN RING	Not Necessary	242.00 FS	*- FS
86	1	*RADIATOR FAN CONTROL UNIT	Not Necessary	1,896.00 FS	*- FS
87	1	*RADIATOR AIR GUIDE - RH OUTER	Missing	31.00 FS	*24.40 FS
88	1	*RADIATOR AIR GUIDE - RH INNER	Missing	16.00 FS	*12.72 FS
89	1	*RADIATOR AIR GUIDE - RH UPPER	Missing	16.00 FS	*12.72 FS
90	1	*RADIATOR AIR GUIDE - RH LOWER	Missing	22.00 FS	*17.04 FS
91	1	*INTAKE AIR DUCT - RH	Not Necessary	22.00 FS	*- FS
92	1	*INTAKE AIR GUIDE	Not Necessary	53.00 FS	*- FS
93	1	*AIR FILTER	Broken	382.00 FS	*305.20 FS
94	1	*INTAKE HOSE	Not Necessary	94.00 FS	*- FS
95	1	*AIR MASS METER	Not Necessary	551.00 FS	*- FS
96	1	*INTAKE MANIFOLD	Not Necessary	657.00 FS	*- FS
97	1	*THROTTLE VALVE ADAPTER	Not Necessary	1,006.00 FS	*- FS
98	1	*ENGINE UNDER SHIELD	Not Necessary	566.00 FS	*- FS
99	1	*FRONT FENDER TRIM - RH	Broken	157.00 FS	*125.60 FS
100	1	*FRONT DOOR TRIM - RH	Necessary	157.00 FS	*125.60 FS
101	1	*FRONT WINDSCREEN	Broken	1,191.00 FS	*952.80 FS
102	1	*FRONT WINDSCREEN SPRING CLIP	Necessary	21.00 FS	*16.08 FS
103	1	*AIR BAG UNIT FOR STEERING WHEEL	Broken	3,641.00 FS	*2,912.80 FS
104	1	*AIR BAG UNIT	Necessary	4,324.00 FS	*3,459.20 FS
105	2	*HEAD AIR BAG UNIT - LH / RH	Broken	3,684.00 FS	*2,947.20 FS
106	1	*HEAD AIR BAG CONTROL UNIT	Necessary	2,088.00 FS	*1,670.40 FS
107	1	*FRONT SEAT BELT - LH	Jammed	1,056.00 FS	*872.80 FS
108	1	*FRONT SEAT BELT - RH	Jammed	1,091.00 FS	*872.80 FS
109	2	*FRONT SEAT BELT HEIGHT ADJUSTE - LH / RH	Not Necessary	332.00 FS	*- FS
110	2	*A-PILLAR TRIM - LH / RH	Crushed	404.00 FS	*323.20 FS
111	2	*B-PILLAR TRIM - LH / RH	Not Necessary	464.00 FS	*- FS
112	2	*C-PILLAR TRIM - LH / RH	Not Necessary	620.00 FS	*- FS
113	2	*D-PILLAR TRIM - LH / RH	Deformed	404.00 FS	*323.20 FS
114	1	*FRONT GRAB HANDLE - RH	Not Necessary	139.00 FS	*- FS
115	2	*REAR GRAB HANDLE - LH / RH	Not Necessary	280.00 FS	*- FS

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
116	1	*SPORT STEERING WHEEL	Cut	2,347.00 FS	*1,877.60 FS
117	1	*DASH BOARD WITH AIR DUCT	Broken	5,229.00 FS	*4,183.20 FS
118	1	*DASH BOARD TOP LOWER COVER	Cracked	166.00 FS	*132.40 FS
119	1	*DASH BOARD TOP UPPER COVER	Not Necessary	122.00 FS	*- FS
120	1	*FRONT SIDE MEMBER TRIM - RH	Crushed	816.00 FS	*652.80 FS
121	1	*FRONT SIDE MEMBER TRIM - RH	Repeated	816.00 FS	*- FS
122	1	*FRONT SIDE MEMBER TRIM ATTACHMENT PARTS	Necessary	129.00 FS	*102.80 FS
123	1	*1SET OF ADHESIVE TAPE	Necessary	210.00 FS	*167.60 FS
124	1	*FRONT DOOR - RH	Repair	3,091.00 FS	*- FS
125	1	*FRONT OUTER DOOR SEAL - RH	Not Necessary	220.00 FS	*- FS
126	1	*BONDING AGENT	Not Necessary	47.00 FS	*- FS
127	1	*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
128	1	*APPLICATOR	Not Necessary	7.00 FS	*- FS
129	1	*FRONT DOOR CATCH - RH	Not Necessary	119.00 FS	*- FS
130	1	*FRONT RIM - RH	Broken	936.80 FS	*936.80 FS
131	1	*FRONT TYRE - RH	Cut	470.00 FS	*470.00 FS
132	1	*STONE CHIP	Necessary	180.00 FS	*180.00 FS
133	1	*ACRYLIC SEALANT	Necessary	140.00 FS	*140.00 FS
134	1	*CAVITY WAX	Necessary	180.00 FS	*180.00 FS
135	1	*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
136	1	*FRONT NO. PLATE	Necessary	60.00 FS	*60.00 FS
137	1	*SUNDRIES	Necessary	500.00 FS	*368.96 FS
138	1	*A-PILLAR WITH SILL PANEL RHS (Supplementary)	Bent	2,154.00 FS	*1,723.20 FS
139	1	*CHASSIS TAG (Supplementary)	Necessary	457.00 FS	*365.60 FS
140	1	*SILL TRIM STRIP RHS (Supplementary)	Necessary	119.00 FS	*94.80 FS
141	1	*POTENTIAL DISTRIBUTOR (Supplementary)	Broken	527.00 FS	*421.20 FS
142	1	*FRONT DOOR CHROME TRIM LHS (Supplementary)	Necessary	157.00 FS	*125.60 FS
143	1	*ENGINE MOUNTING RHS (Supplementary)	Not Necessary	417.00 FS	*- FS
144	1	*SUBFRAME CONSOLE RHS (Supplementary)	Bent	467.00 FS	*373.20 FS
145	1	*FRONT SUBFRAME (Supplementary)	Bent	1,869.00 FS	*1,495.20 FS
146	1	*FRONT WISHBONE LINK RHS (Supplementary)	Bent	533.00 FS	*426.00 FS
147	1	*FRONT SUSPENSION GUIDE RHS (Supplementary)	Bent	932.00 FS	*745.60 FS
148	1	*FRONT GUIDE UPPER FRONT RHS (Supplementary)	Bent	506.00 FS	*404.40 FS
149	1	*FRONT GUIDE UPPER REAR RHS (Supplementary)	Bent	506.00 FS	*404.40 FS
150	1	*WHEEL BEARING HOUSING RHS (Supplementary)	Bent	957.00 FS	*765.20 FS
151	1	*SWIVEL JOINT (Supplementary)	Bent	191.00 FS	*152.80 FS
152	1	*SUSPENSION FORKS RHS (Supplementary)	Bent	261.00 FS	*208.40 FS
153	1	*COUPLING ROD RHS (Supplementary)	Bent	127.00 FS	*101.20 FS
154	1	*FRONT SHOCK ABSORBER RHS (Supplementary)	Not Necessary	289.00 FS	-
155	1	*STEERING RACK (Supplementary)	Not Working	6,234.00 FS	*4,987.20 FS
156	1	*TIE ROD END RHS (Supplementary)	Bent	195.00 FS	*155.60 FS
157	1	*ROOF LINING (Supplementary)	Deformed	2,025.00 FS	*1,620.00 FS
158	1	*BATTERY CENTRAL PROTECTION (Supplementary)	Shorted	527.00 FS	*421.20 FS
159	1	*STEERING COLUMN (Supplementary)	Broken	2,214.00 FS	*1,771.20 FS
160	1	*WATER RESERVOIR TANK (Supplementary)	Deformed	141.00 FS	*112.40 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
161	1	*ANTI-ROLL BAR (Supplementary)	Bent	428.00 FS	*342.80 FS
162	1	*WHEEL HUB FRONT RHS (Supplementary)	Bent	465.00 FS	*371.60 FS
163	1	*HOSE FOR LIFT CYLINDER TO WATER RESERVOIR (Supplementary)	Deformed	38.00 FS	*30.40 FS
164	1	*FRONT FENDER LOWER BRACKET TRIM RHS (Supplementary)	Cracked	24.00 FS	*18.56 FS
165	1	*DASHBOARD AIRBAG ROUND CONNECTOR HSG WITH CABLE (Supplementary)	Distorted	249.00 FS	*198.80 FS
166	1	*DASHBOARD AIRBAG FLATCONTACT HOUSING WITH CABLE (Supplementary)	Distorted	179.00 FS	*143.20 FS
167	1	*RETAINING FRAME FOR LOUDSPEAKER TRIM LH/RH (Supplementary)	Not Necessary	90.00 FS	*- FS
168	1	*LOUDSPEAKER TRIM LH/RH (Supplementary)	Not Necessary	84.00 FS	*- FS
169	1	*FRONT WINDSCREEN GEL FOIL FOR RAIN SENSOR (Supplementary)	Necessary	132.00 FS	*105.20 FS
170	1	*WHEEL BEARING (Supplementary)	Necessary	239.00 FS	*191.20 FS
171	1	*TREBLE SPEAKER (Supplementary)	Not Necessary	192.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 102,794.00 64,955.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER	New	800.00	800.00
3	TO REMOVE AND TRANSFER / REINSTALL FRONT BUMPER WIRE HARNESS FOR FRONT PARKING AID SYSTEM	New	280.00	280.00
4	TO REMOVE AND RENEW AIRCOND CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,400.00	1,400.00
5	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT. PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS	New	3,600.00	3,600.00
6	TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR-O-LINER REPAIRS	New	2,800.00	0.00
7	TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR-O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY	New	2,400.00	2,400.00
8	TO PLACE VEHICLE ON CAR-O-LINER	New	1,800.00	1,800.00
9	TO RENEW FRONT WINDSCREEN	New	480.00	480.00
10	TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN	New	480.00	480.00
11	TO CARRY OUT WINDSCREEN WATER SEEPAGE TEST	New	200.00	200.00
12	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	280.00	0.00
13	TO DISMANTLE AND REINSTALL RHS AND LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY	New	560.00	560.00
14	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	New	400.00	400.00
15	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER, RHS HEADLIGHT, RHS SILL PANEL TRIM AND RHS FRONT DOOR. CUT OUT AND REWELD RHS FENDER SUPPORT AND CLOSING ELEMENT. ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	9,600.00	5,000.00
16	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS UPPER A-PILLAR, ENGINE COMPARTMENT, RHS FRONT FENDER TOP SUPPORT, RHS SILL PANEL TRIM AND RHS FRONT DOOR. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT	New	7,800.00	3,850.00
17	TO RENEW RHS FRONT RIM AND TYRE. TO CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
18	TO CARRY OUT PRE-REPAIR DIAGNOSTIC CHECK AND POST REPAIR DIAGNOSTIC CHECK	New	384.00	384.00
19	TO REMOVE AND REINSTALL RHS FRONT SEAT, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS (Supplementary)	New	1,400.00	1,400.00
20	TO CUT OUT AND WELD RHS A-PILLAR AND RHS SILL PANEL (Supplementary)	New	3,200.00	1,500.00
21	TO RESPRAY RHS A-PILLAR AND RHS SILL PANEL AND DOOR ENTRANCES (Supplementary)	New	2,300.00	1,100.00
22	TO REPAIR WIRING SET FOR ENGINE COMPONENTS (Supplementary)	New	980.00	980.00

Gross Labour Cost (\$\$)

41,704.00

26,894.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
----	-------------	----------	------------	--------

Report was unsubmitted during this print-out.				
---	--	--	--	--

< END OF ESTIMATES >