

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20007625/ATF3E2

Date: 08/02/2021

REFERENCE

Insured/Claimant:	KOH WAI LAN AUDREY	Policy No:	1900089792		
Date of Loss:	21/07/2020	Nature of Claim:	OD	Claim No:	4168079653SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE290Y	Engine No:	CVK077611
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF55KA035017
Reg. Date:	23/04/2019 (Man. Year: 2019)	Odometer:	7461 km
Colour:	Blue		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$155,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,578.40	4,772.48	4,805.92	50.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,712.00	5,232.00	5,480.00	51.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,290.40	10,004.48	10,285.92	50.69
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	18,690.40	8,404.48	10,285.92	55.03
+ GST 7.00/7.00% (S\$)	1,308.33	588.31	720.02	55.03
Nett Amount (S\$)	19,998.73	8,992.79	11,005.94	55.03

INSPECTION

Date of Assignment:	24/07/2020		
Date Inspected:	24/07/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	8.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	2,504.00 FS	*2,003.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	163.00 FS	*- FS
3	1		*REAR BUMPER SECURING STRIP	Necessary	220.00 FS	*176.00 FS
4	1		*REAR BUMPER CHROME TRIM	Cracked	1,005.00 FS	*804.00 FS
5	1		*REAR BUMPER REFLECTOR - RH	Cracked	41.00 FS	*32.24 FS
6	1		*REAR OUTER TAIL LIGHT - RH	Cracked	1,129.00 FS	*903.20 FS
7	1		*REAR OUTER TAIL LIGHT TRIM - RH	Not Necessary	30.00 FS	*- FS
8	1		*REAR INNER TAIL LIGHT - RH	Not Necessary	1,008.00 FS	*- FS
9	1		*REAR INNER TAIL LIGHT TRIM - RH	Not Necessary	30.00 FS	*- FS
10	1		*REAR BUMPER CARRIER	Not Necessary	886.00 FS	*- FS
11	2		*REAR BUMPER CARRIER SEAL	Not Necessary	28.00 FS	*- FS
12	1		*REAR BUMPER TOP GUIDE SECTION - LH / RH	Not Necessary	44.00 FS	*- FS
13	2		*REAR BUMPER TOP GUIDE SECTION PIN	Not Necessary	6.00 FS	*- FS
14	1		*REAR BUMPER GUIDE SECTION - RH	Not Necessary	44.00 FS	*- FS
15	1		*REAR BUMPER SENSOR (2PCS)	Damaged (1Pc Only)	386.40 FS	*193.20 FS
16	4		*REAR BUMPER SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
17	1		*REAR SILENCER - RH	Not Necessary	873.00 FS	*- FS
18	1		*REAR SILENCER DUAL CLIP	Not Necessary	48.00 FS	*- FS
19	1		*REAR SILENCER BRACKET	Not Necessary	41.00 FS	*- FS
20	1		*REAR EXHAUST CHROME TRIM - RH (NPA)	Not Necessary	0.00 FS	*- FS
21	1		*SUNDRIES	Necessary	400.00 FS	*19.20 FS
22	1		*REAR BUMPER SENSOR BRACKET	Necessary	16.00 FS	*12.24 FS
23	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
25	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
26	1		*RHS TAIL LAMP PANEL	Dented	162.00 FS	*129.20 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 9,578.40 4,772.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,600.00	500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER	New	2,000.00	1,100.00
4	TO RENEW RHS REAR EXHAUST SILENCER AND ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	480.00	480.00
7	TO CUT OUT AND WELD RHS TAIL LAMP PANEL. TO REPAIR RHS REAR INNER CONNECTING PLATE	New	3,200.00	1,500.00
8	TO RESPRAY RHS TAIL LAMP PANEL, RHS REAR INNER CONNECTING PLATE AND REAR END PANELLING. TO CARRY OUT SHOP CHIP TREATMENT AND JOINT SEALANT WORKS	New	2,400.00	1,100.00
Gross Labour Cost (\$\$)			10,712.00	5,232.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >