

ASS. REC. BY:

Steve

REF:

CS/CT120007639/ESF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBF 5545G

Yr Regn:

10/3/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make:

Mitsubishi Canter

c.c

2998

Colour:

White

A/C:

Insured / Std / NI / NA

Sp.Reading

155717

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

FEA 018A20024

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/75R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

17/7/20

D.O.A.

24/7/20

Survey held at

Siang Hai Motor

Des. of Damages: Frt / Rear / Q/S / N/S / U/C / Rooftop or

Front LH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV- 37,900

PV- 10,353

NV- 26,647

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Rep. Formed:

Lump Sum / L.F. / C.

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

EURO SUCCESS SERV PTE. LTD

Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231

FAX: 67411019

H/P: 98289277 (AH HUAT)

Vehicle No: GBF5545G

Model: MITSUBISHI FUSO

QTY	List Items	Price \$
1	FRONT PANEL X R	2521.83
1	FRONT PANEL ' FUSO ' EMBLEM / <i>noc</i>	86.90
<i>2</i> / 1	FRONT L-R CORNER PANEL @673.60 (LH) / <i>BR</i>	1347.20
2	FRONT L-R MIRROR HINGE @223.20 X	446.40
2	FRONT L-R MIRROR HINGE GARNISH @136.50 X	273.00
1	FRONT GRILL X	1053.14
1	FRONT GRILL EMBLEM X	96.80
1	FRONT BUMPER X <i>fit</i>	1010.33
1	FRONT BUMPER REINFORCEMENT X	2350.90
2	FRONT L-R BUMPER BRACKET @189.73 X	379.46
2	FRONT L-R BUMPER CORNER GARNISH @220.96 / <i>cut</i>	441.92
1	FRONT L-R BUMPER SPOT GARNISH X	95.00
1	FRONT CHASSIS FRAME CROSS MEMBER X	982.69
<i>2</i> / 1	FRONT L-R HEADLAMP @635.12 (LH) / <i>BR</i>	1270.24
2	FRONT L-R SIDE LAMP @266.36 / <i>BR</i>	532.72
2	FRONT L-R HEADLAMP BRACKET @253.67 X	507.34
1	POWER STEERING BOX RAD X	5694.51
1	STEERING PIPE X	92.60
2	FRONT L-R TOP ARM @2588.50 X	5177.00
2	FRONT L-R KNUCKLE ARM WHEEL BEARING @790.60 X	1581.20
2	FRONT L-R LOWER ARM @2680.56 X	5361.12
2	FRONT L-R KNUCKLE ARM @2147.51 X	4295.02
2	FRONT L-R DOOR @2071.55 / <i>DD</i>	4143.10
2	FRONT L-R DOOR CHECKER @89.5 X	179.00
2	FRONT L-R DOOR W/ STRIP @189.6 X	379.20
<i>2</i> / 1	FRONT L-R DOOR OUTER HANDLER @98.6 (RH) / <i>cut</i>	197.20
2	FRONT L-R DOOR OUTER HANDLER STOPPER @68.5 X	137.00
2	FRONT L-R DOOR GLASS RUN CHANNEL @163.5 X	327.00
2	FRONT L-R DOOR GLASS OUTER MOULDING @275.6 X	551.20
2	FRONT L-R DOOR CORNER GARNISH @128.6 X	257.20
2	FRONT L-R DOOR HINGE @80.6 / <i>BT</i>	161.20
2	FRONT L-R DOOR PILLAR INNER @1420.33 X R	2840.66
2	FRONT L-R DOOR PILLAR OUTER @1533.24 X R	3066.48
2	FRONT L-R DOOR PILLAR INNER GARNISH @756.98 X	1513.96
2	FRONT L-R DOOR <i>Arch</i> ART PANEL @348.27 X	696.54
<i>2</i> / 1	FRONT L-R DOOR ART PANEL GARNISH @258.50 (LH) / <i>CRU</i>	517.00
2	FRONT L-R DOOR INNER TRIM BOARD @620.5 X	1241.00
2	FRONT L-R DOOR STEP PANEL @613.2 X <i>fit</i>	1226.40
2	FRONT L-R DOOR STEP PANEL GARNISH @289.6 / <i>cut</i>	579.20
2	FRONT L-R DOOR POWER MOTOR @400 X	800.00
2	FRONT L-R DOOR POWER WINDOW GEAR @420 X	840.00
2	FRONT L-R DOOR POWER WINDOW SWITCH @385 X	770.00

2	FRONT L-R DOOR INNER LOWER RUBBER @150 X	300.00
2	FRONT L-R DOOR INNER LOCK @550 X	1100.00
2	FRONT L-R DOOR INNER LOCK MOTOR @360.5 X	721.00
2	FRONT L-R DOOR SPEAKER @250 X	500.00
1	FRONT CABIN HINGE BAR ASSY X	2277.00
2	FRONT CABIN HINGE MOUNTING L-R @750 X	1500.00
1	FRONT FLOOR BOARD PANEL X	1730.89
1 SET	REAR CABIN LOCK BRACKET X	249.80
2	FRONT L-R STEP PANEL GARNISH @263.9 X	527.80
1	FUSE BOX X	1500.00
1 SET	AIR HOSE PIPE X	400.00
1	AIRCON BLOWER UNIT HEATER ASSY X	2584.78
1	AIRCON CONDENSER X / BT	1439.59
1	AIRCON DRYER X	185.00
1	AIRCON CONDENSER BRACKET X	250.00
1	AIRCON FAN MOTOR ASSY X	1100.60
2	AIRCON PIPE @98.5 X	197.00
1	AIRCON CO UNIT X	561.50
1	DASHBOARD ?	2208.05
1	DASHBOARD REINFORCEMENT X	1596.30
1	HEATER ASSY X	2590.60
1	FLOOR BOARD PANEL X	1572.60
1	RADIATOR X	3122.23
1	RADIATOR FAN X	310.43
1	RADIATOR COWING X	385.65
2 /	REAR CABIN BOX SLIDING DOOR @ 2500 X / 00	5000.00
2	REAR CABIN BOX SLIDING DOOR LOCK @ 250 X	500.00

TOTAL	\$90,431.48
LESS 20%	\$18,086.30
TOTAL	\$72,345.18

	<u>Special Nett Items</u>	
20	FRONT DOOR BOARD CLIP @7.5	150.00 30
10	FRONT GRILL CLIP @7.5	75.00 X
2	FRONT L-R DOOR MECHANISM	500.00 X
1	STEERING OIL	80.00 X
1	AIR CON OIL	60.00 X
1	RADIATOR COOLENT	50.00 X
1	BRAKE OIL	60.00 X

TOTAL	\$975.00
-------	----------

Labour Charges

TOWING	180.00 60
TO REMOVE & REFIX FRONT WINDSCREEN GLASS	280.00 X
TO REMOVE & REFIX DASHBOARD WIRING ETC	450.00 200
TOP UP AIRCON GAS & REMOVE, REFIX CONDENSER COIL, BLOWER ETC	300.00 120
TO REMOVE & REFIX ROOF, CUSHION, CARPETS FOR REPAIR	300.00 50
TO REMOVE & REFIX CABIN FOR REPAIR CHASSIS FRAME, CROSS MEMBER	650.00 X

TO REMOVE & REFIX STEERING RAD, UNDERCARRIAGE, ABS PUMP,
RADIATOR ASSY FOR REPAIR
PANEL BEATING, CUT, WELD, REALIGN BODY TO THE ACCIDENT REPAIR
TO RESPRAY PAINTING AND ETC

550.00 X

2800.00 1200

2000.00 1000

\$7,540.00

\$80,860.18

ESTIMATE PARTS AND LABOUR GRAND TOTAL

Steve CLKK)

8322 8813

WZ AL

24/7/20, 3:39pm

L/S

Ry AL Sy

12 dys

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: