

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 04 Aug 2020

Preliminary Advice

Insured Vehicle No : SMD2078M

TP Vehicle No : GBF5545G

Make : MITSUBISHI CANTER

Date of Inspection : 24/07/2020

Inspection At : Siong Hai Motor & Trading (HQ)

NO 1 KAKI BUKIT AVE 6, #02-03 AUTOBAY @ KAKI BUKIT
Singapore 417883

Accident Date : 17/07/2020

Assignment Date : 24/07/2020

Est. Duration of Repair : 12 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front n/s, n/s front portion, o/s body and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 80,860.18 |
| Revised Amount | :S\$ | 11,900.36 |
| Check Items (Estimated) | :S\$ | 1,766.44 |
| Total | :S\$ | 13,666.80 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP