



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

SOMPO INSURANCE SINGAPORE PL  
50 RAFFLES PLACE  
#05-01/06  
SINGAPORE LAND TOWER  
SINGAPORE 048623

INV No. AC2005941  
INV Date 28/08/2020  
Reference CS/SMO20007644/Uvf3n2  
Code SMO



### PROFESSIONAL SERVICE FEE

Vehicle No. SLR 597H  
Insured Veh. GBE 6570G  
Claim No. CMTD2002191/RUC  
Policy No.  
Accident Date 24/07/2020  
Inspection Date 24/07/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>450.00</b>
<b>GST (7%)</b>	<b>31.50</b>
<b>Grand Total</b>	<b>481.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20007644/Uvf3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 28-08-2020



Code : SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	GBE 6570G	<b>Veh. Inspected</b>	SLR 597H
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	CMTD2002191/RUC	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	MELVIN YE	<b>Assign Date</b>	24/07/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	CHEVROLET CRUZE (A)	<b>c.c</b>	1362
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
<b>Chassis No.</b>	KL1JA6989GK354937	<b>Colour</b>	SILVER
<b>Odometer</b>	19116	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	205/60 R16	HANKOOK	6 mm
<b>L/H Front Tyre</b>	205/60 R16	HANKOOK	6 mm
<b>R/H Rear Tyre</b>	205/60 R16	HANKOOK	6 mm
<b>L/H Rear Tyre</b>	205/60 R16	HANKOOK	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	24/07/2020	<b>Inspection Date</b>	24/07/2020
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **10 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 597H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BOOTLID	TO REPAIR SEE LABOUR	1,850.00	-
1	BOOTLID REAR LOGO	NOT NECESSARY	105.00	-
1	BOOTLID "CRUZE" EMBLEM	NECESSARY	102.00	90.00
1	BOOTLID "LS" EMBLEM	NECESSARY	85.00	80.00
1	BOOTLID "TURBO" EMBLEM	NECESSARY	100.00	100.00
1	BOOTLID "CHEVROLET" EMBLEM	NECESSARY	100.00	100.00
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	399.00	-
2	BOOTLID REFLECTORS @\$850.00	N/S CRACKED	1,700.00	480.00
1	BOOTLID INNER LOCK	NOT NECESSARY	215.00	-
1	REAR BUMPER	DISTORTED	1,680.00	1,247.00
1	REAR BUMPER CHROME MOULDING	CRACKED	325.00	305.00
2	REAR BUMPER SIDE RETAINERS @\$105.00	N/S CRACKED	210.00	66.50
1	REAR BUMPER REINFORCEMENT	TWISTED	788.00	705.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER PDC SENSOR N/S	SHORTED	215.00	215.00
1	REAR END PANEL	DENTED / BENT	925.00	806.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	411.00	-
2	TAILLAMPS @\$990.00	N/S BROKEN	1,980.00	725.00
2	TAILLAMP HOUSING PANELS @\$605.00	TO REPAIR SEE LABOUR	1,210.00	-
1	REAR WINDSCREEN MOULDING	NECESSARY	192.00	192.00
1	REAR FENDER N/S	DISTORTED	2,480.00	2,050.20
1	REAR FENDER LOWER SIDE PANEL N/S	DISTORTED	390.00	366.40
1	REAR FENDER UNDER COVER N/S	TORN	315.00	265.30
1	REAR FENDER WHEEL HOUSING PANEL N/S	BADLY DENTED	2,280.00	2,083.00
1	REAR FENDER INNER TRIM N/S	NOT NECESSARY	425.00	-
1	REAR FENDER QUARTER GARNISH N/S	GRAZED	345.00	265.00
1	REAR AIR VENT N/S	TWISTED	110.00	110.00
1	ROOF MOULDING N/S	NOT NECESSARY	329.00	-
1	REAR DOOR N/S	TO REPAIR SEE LABOUR	1,660.00	-

Report Ref No. CS/SMO20007644/Uvf3n2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR DOOR INNER LOCK N/S	NOT NECESSARY	450.00	-
1	REAR DOOR INNER TRIM N/S	NOT NECESSARY	825.00	-
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,450.00	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	615.00	-
1	REAR SHOCK ABSORBER N/S	SERVICEABLE	390.00	-
1	REAR WHEEL HUB BEARING N/S	DAMAGED	690.00	520.00
1	REAR AXLE BEAM	BENT / TWISTED	2,210.00	2,210.00
	LESS 10% DISCOUNT		-	-1,303.14
			27,606.00	11,728.26
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR SPORT RIM N/S (SN)	DENTED / BENT	1,200.00	400.00
1	REAR TYRE N/S (60%)(SN)	CUT	200.00	120.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	180.00	-
1	TAILLAMP BULB N/S (SN)	BROKEN	10.00	5.00
			1,690.00	615.00
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACED REAR PDC SENSOR.		80.00	50.00
	TO TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX FUEL TANK.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR DOOR MECHANISM.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE.		380.00	280.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO SPRAY RUST PROOFING.		150.00	80.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF BOOTLID,TAILLAMP HOUSING PANELS,REAR DOOR N/S AND REAR FLOOR PANEL.		2,500.00	1,800.00

Report Ref No. CS/SMO20007644/Uvf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY & SPRAY PAINTING.		2,000.00	1,100.00
			6,320.00	3,620.00
GRAND TOTAL			35,616.00	15,963.26
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				12,000.00

Report Ref No. CS/SMO20007644/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.