



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EE 2207Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR LAMP - RH	BROKEN	372.80	372.80
1	REAR BUMPER	TO REPAIR SEE LABOUR	985.70	-
1	REAR BUMPER RETAINER - R/H	SERVICEABLE	114.12	-
1	REAR FENDER - RH	TO REPAIR SEE LABOUR	1,288.43	-
	LESS 25% DISCOUNT		-690.26	-93.20
			2,070.79	279.60
	<u>LABOUR</u>			
	TO PULL, KNOCK ON REAR ACCIDENT PORTION & CHANGE THE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER AND REAR FENDER - RH.		380.00	300.00
	TO SPRAY & PAINT ON ACCIDENT PORTION.		680.00	420.00
	TO CHECK WIRING FUNCTIONS.		50.00	20.00
	TO ANTI-RUST REAR AFFECTED AREAS.	NOT NECESSARY	50.00	-
			1,160.00	740.00
GRAND TOTAL			3,230.79	1,019.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				800.00

Report Ref No. CS/GAI20007650/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.