

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007652/UPS3Q2

Date: 10/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLJ4436E	Insured Vehicle No :	SHC8863M
Date of Loss: 22/07/2020	Nature of Claim: TP	Claim No: MCT20070387

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ4436E		
Make & Model:	TOYOTA WISH, 1.8 X (A)	Engine No:	2ZR1648184
Reg. Date:	12/12/2016 (Man. Year: 2015)	Chassis No:	ZGE206026833
Colour:	Black	Odometer:	339237 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,386.00	2,319.87	23,066.13	90.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,050.00	820.00	7,230.00	89.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,436.00	3,139.87	30,296.13	90.61
Approved Total (Overridden) (S\$)		2,500.00		
(S\$)	33,436.00	2,500.00	30,936.00	92.52
+ GST 7.00/7.00% (S\$)	2,340.52	175.00	2,165.52	92.52
Nett Amount (S\$)	35,776.52	2,675.00	33,101.52	92.52
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		36.49		
Nett Liability (S\$)		3,011.49		
Global Sum Settlement (S\$)		3,000.00		

INSPECTION

Date of Assignment: 24/07/2020

Date Inspected: 27/07/2020 Inspected At:

RICO 60 AUTO SERVICES PTE LTD
(HQ)
8, KAKI BUKIT AVENUE 4, #02-24,
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Sep 2020)
Parts:	M1-MPV	TOYOTA WISH 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ4436E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Not Necessary	1,696.00 F	*- FL
2	1		*BONNET LOCK	Not Necessary	321.00 F	*- FL
3	1		*BONNET CATCH	Not Necessary	105.00 F	*- FL
4	1		*BONNET INSULATOR	Not Necessary	420.00 F	*- FL
5	2		*BONNET HINGE (L+R)	Not Necessary	396.00 F	*- FL
6	2		*BONNET STOPPER (L+R)	Not Necessary	82.00 F	*- FL
7	1		*BONNET LOGO (TOYOTA)	Not Necessary	115.00 F	*- FL
8	1		*HEADLAMP (L+R)	N/S Cracked	3,378.00 F	*1,410.50 FL
9	2		*HEADLAMP BRACKET (L+R)	Not Necessary	460.00 F	*- FL
10	1		*FRONT GRILLE	Cracked	692.00 F	*366.10 FL
11	1		*FRONT GRILLE CHROME	Scratched	305.00 F	*180.90 FL
12	1		*FRONT BUMPER	Deformed / Torn	1,078.00 F	*688.10 FL
13	2		*FRONT BUMPER RETAINER (L+R)	Not Necessary	392.00 F	*- FL
14	1		*FRONT BUMPER REINFORCEMENT BAR	Repair	872.00 F	*- FL
15	2		*FRONT BUMPER BRACKET (L+R) (NPA)	Not Necessary	0.00 F	*- FL
16	1		*FRONT BUMPER BEAM (NPA)	Repair	0.00 F	*- FL
17	1		*FRONT BUMPER SPONGE	Torn	311.00 F	*194.80 FL
18	1		*FRONT BUMPER GRILLE	No such part	473.00 F	*- FL
19	1		*FRONT BUMPER TOWING CAP	Not Necessary	105.00 F	*- FL
20	1		*FRONT BUMPER FOG LAMP SIDE GARNISH (L+R)	N/S Torn	498.00 F	*65.00 FL
21	2		*FRONT BUMPER FOG LAMP SIDE GARNISH CHROME (L+R) (NPA)	Not Necessary	0.00 F	*- FL
22	2		*FRONT BUMPER FOG LAMP GARNISH (L+R)	Not Necessary	524.00 F	*- FL
23	1		*FRONT BUMPER UNDERCOVER	Not Necessary	575.00 F	*- FL
24	2		*FRONT FENDER (L+R)	Not Necessary	1,966.00 F	*- FL
25	2		*FRONT FENDER COWLING (L+R)	Not Necessary	486.00 F	*- FL
26	1		*FRONT SUPPORT PANEL	Repair	1,089.00 F	*- FL
27	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	394.00 F	*- FL
28	1		*AIR CON CONDENSOR	Serviceable	1,292.00 F	*- FL
29	1		*HIGH PRESSURE HOSE	Not Necessary	423.00 F	*- FL
30	1		*LOW PRESSURE HOSE	Not Necessary	391.00 F	*- FL
31	1		*RADIATOR	Not Necessary	1,542.00 F	*- FL
32	1		*DISCHARGE PIPE	Not Necessary	273.00 F	*- FL
33	1		*SUCTION PIPE	Not Necessary	281.00 F	*- FL
34	1		*RADIATOR FAN COWLING	Not Necessary	955.00 F	*- FL
35	1		*RADIATOR FAN BLADE	Not Necessary	145.00 F	*- FL
36	1		*RADIATOR FAN MOTOR	Not Necessary	879.00 F	*- FL
37	1		*WIPER WASHER TANK	Not Necessary	154.00 F	*- FL
38	1		*WIPER WASHER MOTOR	Not Necessary	289.00 F	*- FL
39	1		*FRONT BUMPER INNER FOG LAMP GARNISH (LH)	Not Necessary	272.00 F	*- FL
40	1		*FRONT BRACE PANEL	Bent	897.00 F	*121.10 FL
41	10		*BONNET INSULATOR CLIP	Not Necessary	100.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	10		*FRONT BUMPER CLIP	Necessary	100.00 FS	*50.00 FS
43	1		*FRONT CARPLATE	Serviceable	120.00 FS	*- FS
44	1		*FRONT CARPLATE FRAME	Not Necessary	120.00 FS	*- FS
45	10		*FRONT FENDER COWLING CLIP	Not Necessary	100.00 FS	*- FS
46	10		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	100.00 FS	*- FS
47	1		*RADIATOR COOLANT	Not Necessary	120.00 FS	*- FS
48	1		*AIRCON GAS	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	25,386.00	3,076.50
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	756.63

Total Parts (\$\$)	25,386.00	2,319.87
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RNR ACCIDENT DAMAGE PARTS ,CUT /WELD ,KNOCK & REALIGN	New	2,700.00	300.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	2,700.00	400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	400.00	0.00
4	TO RNR UPHOLSTERY GARNISH AND ATTACHMENT PARTS	New	800.00	0.00
5	TO RNR A/C CONDENSOR ASSY	New	300.00	100.00
6	TO RNR RADIATOR ASSY AND HOSES TO ASSIST WORK LOAD	New	300.00	0.00
7	TO CHECK WIRING LAYOUT AND HEADLAMP FOCUS	New	150.00	20.00
8	TO DO DIAGNOSIS AND RESET ,REPROGRAM OR CODING FAULT CODE	New	600.00	0.00
9	TO DO WATER LEAK TEST	New	100.00	0.00
Gross Labour Cost (\$\$)			8,050.00	820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >