

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007654/KDA3Q2
Date: 28/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800013301
Claimant
Vehicle No : GBK1268G **Insured Vehicle No :** SLV4994Y
 Date of Loss: 20/07/2020 Nature of Claim: TP Claim No: 5801742108SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBK1268G**
 Make & Model: ISUZU NHR87AUE4AA, 1.9 D (M) Engine No: RZ4E105C34
 Reg. Date: 02/01/2020 (Man. Year: 2019) Chassis No: JAANHR87EK7100273
 Colour: White/Orange Odometer: 8060 km
 Engine Capacity: 1898 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/75 R12 Rear Tyre Size: 155 R15X8 (D)
 Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9/9 mm
 Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9/9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,753.65	4,459.90	2,293.75	33.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,130.00	1,260.00	870.00	40.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,883.65	5,719.90	3,163.75	35.61
+ GST 7.00/7.00% (S\$)	621.86	400.39	221.47	35.61
Nett Amount (S\$)	9,505.51	6,120.29	3,385.22	35.61
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 23/07/2020
 Date Inspected: 24/07/2020 Inspected At: Chew Goon Motor (AMK)
 Blk 10 Ang Mo Kio Industrial Park 2A,
 #01-15/16 & 17, AMK Autopoint
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: HOW MEI KWAN

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Bent	785.00 FL	*785.00 FL
2	1		*FRONT BUMPER BRACKET LH	Bent	174.00 FL	*174.00 FL
3	1		*FRONT GRILLE	Serviceable	785.00 FL	*- FL
4	1		*HEADLAMP LH	Mtg Cracked	569.00 FL	*569.00 FL
5	1		*HEADLAMP LOWER RUBBER SEAL	Distorted	20.00 FL	*20.00 FL
6	1		*HEADLAMP SIDE BRACKET LH	Distorted	48.00 FL	*48.00 FL
7	1		*FRONT SIGNAL LAMP LH	Broken	162.00 FL	*162.00 FL
8	1		*FRONT SIGNAL LAMP WIRE HARNESS LH	Repair	295.00 FL	*- FL
9	1		*FRONT CORNER PANEL RH	Missing	310.00 FL	*310.00 FL
10	1		*FRONT CORNER PANEL TOP COVER	Missing	60.00 FL	*60.00 FL
11	1		*FRONT WING MIRROR (ROUND)	Missing	145.00 FL	*145.00 FL
12	1		*FRONT WING MIRROR (SQUARE)	Serviceable	195.00 FL	*- FL
13	1		*FRONT WING MIRROR STAND BRACKET	Bent	315.00 FL	*315.00 FL
14	1		*FRONT DOOR LH	Bent	1,420.00 FL	*1,420.00 FL
15	1		*FRONT DOOR LOWER HINGE	Distorted	132.00 FL	*132.00 FL
16	1		*FRONT DOOR WEATHERSTRIP	Cut	240.00 FL	*240.00 FL
17	10		*FRONT DOOR TRIM BOARD CLIPS	Not Necessary	45.00 FL	*- FL
18	1		*FRONT DOOR LOWER ARCH PANEL GARNISH	Cut	172.00 FL	*172.00 FL
19	1		*FRONT DOOR LOWER STEP BOARD	Dented / Cut	345.00 FL	*345.00 FL
20	1		*FRONT DOOR FRAME RUBBER SEAL	Cut	195.00 FL	*195.00 FL
21	1		*FRONT WINDSCREEN LOWER SIDE MOULDING	Missing	102.00 FL	*102.00 FL
22	1		*FRONT WHEEL RIM	Serviceable	285.00 FL	*- FL
23	1		*FRONT WHEEL BEARING	Not Necessary	175.00 FL	*- FL
24	1		*FRONT WHEEL MUD FLAP	Serviceable	195.00 FL	*- FL
25	1		*FRONT NUMBER PLATE	Serviceable	45.00 FS	*- FS
26	1		*FRONT DOOR COMPANY REG LABLE	Necessary	45.00 FS	*25.00 FS
27	1		*FRONT DOOR INNER STICKER (REFLECTIVE)	Necessary	120.00 FS	*20.00 FS
28	1		*FRONT DOOR BODY AD STICKER	*Check	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,829.00	5,239.00
- List Item Discount on L Items 15.00/15.00% (\$)	1,075.35	779.10
Total Parts (\$)	6,753.65	4,459.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT ELECTRICAL CHECK ,FOCUS HEADLAMP	New	30.00	20.00
2	TO DISMANTLE /TRANSFER DOOR FITTINGS /ANCILLARY ACCESSORIES	New	150.00	60.00
3	TO APPLY RUST PROOFING /RESEAL TUFF COATING TREATMENT TO RESPRAY /REPLACED /REPAIR PANEL	New	60.00	30.00
4	TO DISMANTLE /HI PRESSURE PRESS/REPLACE WHEEL BEARING	New	100.00	0.00
5	TO CONDUCT HIGH SPEED BALANCING	New	60.00	0.00
6	TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT TEST	New	80.00	0.00
7	LABOUR CHARGE-PANEL BEATING ,REPAIRING OF FRONT DOOR PILLAR ,INNER PANEL ,STEP PANEL ,DOOR ARCH PANEL AND PARTS REPLACEMENT	New	750.00	550.00
8	TO RESPRAY AFFECTED AREAS (2K- 2 TONE)	New	900.00	600.00
Gross Labour Cost (\$\$)			2,130.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >