

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20007663/R1BA3Q2

Date: 29/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SLQ1611Z	Insured Vehicle No :	GBA195S
Date of Loss:	24/07/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001432

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ1611Z	Engine No:	11719876B48B20B
Make & Model:	BMW 530I, 2.0 LED NAV (A)	Chassis No:	WBAJA52060G884753
Reg. Date:	29/06/2017 (Man. Year: 2017)	Odometer:	82108 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	895.50	609.70	285.80	31.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,638.00	3,952.00	686.00	14.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,533.50	4,561.70	971.80	17.56
+ GST 7.00/7.00% (S\$)	387.35	319.32	68.03	17.56
Nett Amount (S\$)	5,920.85	4,881.02	1,039.83	17.56
+ Car Rental (3.0 x S\$150.00/day + 7.00% GST) (S\$)		481.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,369.97		

INSPECTION

Date of Assignment:	17/08/2020	
Date Inspected:	17/08/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2020)
Parts:	143	BMW 530I 2.0 LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ1611Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT EMBOSS NUMBER PLATE	Necessary	165.00 FS	*165.00 FS
2	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
3	1		*FRT LH GRILLE (LUXURY)	Cracked	145.70 FS	*145.70 FS
4	1		*FRT RH GRILLE (LUXURY)	Scratched	145.70 FS	*145.70 FS
5	1		*AIR FLAPS TOP	Not Necessary	285.80 FS	*- FS
6	2		*EMBLEM GROMMET	Necessary	1.70 FS	*1.70 FS
7	1		*PLAQUE 82MM	Necessary	71.60 FS	*71.60 FS
					Total Parts (S\$)	895.50 609.70

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO MAKE GOOD FRONT BUMPER AND BONNET	New	2,125.00	1,700.00
2	TO RESPRAY FRONT BUMPER AND BONNET	New	2,336.00	2,102.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
Gross Labour Cost (\$\$)			4,638.00	3,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >