Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007665/R1PA3Q2

**Date:** 05/01/2021

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant SMT5325X Insured Vehicle No: SHC8085LL

Vehicle No: SMT5325X Insured Vehicle No: SHC8985U

Date of Loss: 22/07/2020 Nature of Claim: TP Claim No: MCT20070302

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMT5325X

Make & Model: HONDA JAZZ, 1.3 CVT (A) Engine No: L13B15000731

Reg. Date: 26/06/2020 (Man. Year: 2020) Chassis No: JHMGK3850LS217953

Colour: Grey Odometer: 781 km

Engine Capacity: 1318 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15
Front Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm
Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,021.49	1,884.44	137.05	6.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,410.00	5,890.00	1,520.00	20.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,431.49	7,774.44	1,657.05	17.57
+ GST 7.00/7.00% (S\$)	660.20	544.21	115.99	17.57
Nett Amount (S\$)	10,091.69	8,318.65	1,773.04	17.57
+ Loss of Use (10.0 x	S\$60.00/day) (S\$)	600.00		
	Nett Liability (S\$)	8,918.65		

**INSPECTION** 

Date of Assignment: 24/07/2020

Date Inspected: 03/08/2020 Inspected At: Kah Motor Co Sdn Bhd

(ALEXANDRA)

255 ALEXANDRA ROAD

Singapore -

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL Manager: CHEW HSIAO TONG

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 24 Aug 2020)

Parts: 144 HONDA JAZZ 1.3 CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SMT5325X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Candition

Donairer's

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No Oty Port No

Qty Part No.	Part No. Particulars	Condition	Repairer's	Amount
1	*PANEL SETR.RR.OUTSIDE	Bent	438.97 FS	*438.97 FS
1	*FENDER ,R.RR.INNER	Serviceable	60.75 FS	*-FS
1	*GROMMETCOWL TOP (4 PCS)	Serviceable	6.30 FS	*-FS
3	*CLIP,INNER FENDER	Necessary	16.80 FS	*16.80 FS
1	*FACE RR.BUMPER	Scratched	520.27 FS	*520.27 FS
1	*SPACER.R.RR BUMPER SIDE	Necessary	12.97 FS	*12.97 FS
1	*CLIP BUMPER (7 PCS)	Necessary	12.07 FS	*12.07 FS
1	*WHEEL,DISK AL 15X7	Scratched	342.90 FS	*342.90 FS
1	*GLASS QUARTER	Necessary	118.20 FS	*118.20 FS
1	*RUBBERR QTR W/SHIELD (2 PCS)	Necessary	14.85 FS	*14.85 FS
1	*CLIPQUARTER WINDSHIELA	Necessary	2.77 FS	*2.77 FS
1	*CLIPQUARTER WINDSHIEL B	Necessary	2.77 FS	*2.77 FS
1	*CLIPQUARTER WINDSHIEL C	Necessary	1.87 FS	*1.87 FS
2	*WINDSCREEN SEALANT	Necessary	120.00 FS	*120.00 FS
1	*SOLAR FILM ON REAR QTR GLASS	Necessary	250.00 FS	*250.00 FS
1	*SUNDRIES	Necessary	100.00 FS	*30.00 FS
chise part. S=Spo	art. S=SpcNett.	_		
		Total Parts (S\$)	2,021.49	1,884.44
criise p	Jè	ран. 3-эромен.	•	$\cdot$

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	WHEEL ALIGNMENT	New	180.00	180.00					
2	REMOVE & REINSTALL REVERSE SENSORS	New	180.00	150.00					
3	SEALANT FOR RHR FENDER	New	100.00	100.00					
4	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	150.00					
5	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	New	650.00	650.00					
6	CUT OFF & RENEW RR PANEL	New	3,250.00	3,250.00					
7	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,500.00	1,040.00					
8	REMOVE & RENEW RHR WHEEL	New	50.00	50.00					
9	REMOVE & INSTALL RR R QTR GLASS	New	320.00	320.00					
	Gross Labour Cost (S\$)		7,410.00	5,890.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >