Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20007666/KPS3Q2

Date: 18/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SHC5860R Insured Vehicle No: SKR5710B

Date of Loss: 23/07/2020 Nature of Claim: TP Claim No: 4396710397SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5860R

Make & Model:

RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR Engine No: M9R8839C002511

()

Reg. Date: 06/03/2015 (Man. Year: 2015) Chassis No: VF1ABL15AUC281455

Colour: Metallic White/Red Odometer: 700166 km

Engine Capacity: 1995 cc
Market Value/New Car
N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Sailun 8 mm Rear Left Side: Sailun 8 mm
Front Right Side: Sailun 8 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,443.81	6,271.09	13,172.72	67.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,340.00	2,180.00	10,160.00	82.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	31,783.81	8,451.09	23,332.72	73.41
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	31,783.81	6,750.00	25,033.81	78.76
+ GST 7.00/7.00% (S\$)	2,224.87	472.50	1,752.37	78.76
Nett Amount (S\$)	34,008.68	7,222.50	26,786.18	78.76
+ Loss of Use (7.0 x S\$	50.00/day) (S\$)	350.00		
+ Car Rental (7.0 x S\$	95.04/day) (S\$)	665.28		
+ Doc/S	earch Fee (S\$)	7.45		
Ne	Nett Liability (S\$)			
Global Sum Settlement (S\$)		8,200.00		

INSPECTION

Date of Assignment: 24/07/2020

Date Inspected: 24/07/2020 Inspected At: Trans-cab Auto Services Pte Ltd (Ang

Mo Kio)

Adjuster Report Page 2 of 5

2, Ang Mo Kio Street 63 Singapore 569111

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Distorted	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Cracked	98.10 FL	*98.10 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Cracked	16.60 FL	*16.60 FL
10	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	114.50 FL	*114.50 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Bent	114.50 FL	*114.50 FL
13	1		*BUMPER BLOCK LH REAR	Serviceable	76.50 FL	*-FL
14	1		*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	*-FL
15	1			Serviceable	301.10 FL	*-FL
	-		*BUMPER HARNESS REAR			
16	1		*BOOT REAR	Bent	1,677.20 FL	
17	1		*BOOT FINISHER	Serviceable	344.70 FL	*-FL
18	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*-FL
19	1		*BOOT REFLECTOR LAMP LH	Cracked	277.70 FL	*277.70 FL
20	1		*BOOT REFLECTOR LAMP RH	Cracked	277.70 FL	*277.70 FL
21	1		*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 FL
22	1		*BOOT BADGE	Necessary	95.80 FL	*95.80 FL
23	1		*BOOT STRUT LH	Serviceable	145.10 FL	*-FL
24	1		*BOOT STRUT RH	Serviceable	145.10 FL	*-FL
25	1		*BOOT HINGE LH	Repair	254.20 FL	*-FL
26	1		*BOOT HINGE RH	Repair	253.80 FL	*-FL
27	1		*BOOT TRIM BOARD	Serviceable	611.00 FL	*- FL
28	1		*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- FL
29	1		*BOOT LOCK	Repair	246.60 FL	*-FL
30	2		*BOOT RUBBER PLUG	Serviceable	139.30 FL	*-FL
31	1		*BOOT SWITCH	Serviceable	113.00 FL	*-FL
32	2		*LICENCE PLATE LAMP	Serviceable	26.30 FL	*-FL
33	1		*TAILLAMP RH	Cracked	401.40 FL	*401.40 FL
34	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL
35	1		*TAILLAMP LH	Cracked	401.40 FL	*401.40 FL
36	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL
37	1		*OUTER PANEL REAR (END PANEL)	Bent	745.80 FL	*745.80 FL
38	1		*OUTER PANEL REAR (END PANEL) TRIM	Distorted	404.56 FL	*404.56 FL
39	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	1,229.40 FL	*- FL
40	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
41	1		*SPARE WHEEL PANEL BRACKET LH L70Y	Repair	70.60 FL	*- FL
42	1		*SPARE WHEEL PANEL BRACKET RH L70Y	Repair	69.20 FL	*- FL
43	1		*SPARE TYRE BOARD	Serviceable	680.90 FL	*- FL
44	1		*EXHAUST REAR	Repair	5,263.60 FL	*- FL
45	1		*EXHAUST CAP REAR	Repair	125.40 FL	*-FL
46	1		*SET PARKING AID	Shorted	700.00 FS	*400.00 FS
47	1					
47 48	-		*SET REAR BUMPER CLIP *SET RUMPED REACKET CTP CLIP	Necessary	75.00 FS	*75.00 FS *- FS
	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	55.00 FS	
49 50	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary		*-FS
50	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	65.00 FS	*-FS
51	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary		*-FS
52	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	65.00 FS	*-FS
53	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	65.00 FS	*-FS
			Report was unsubmitted during this pri	nt-out.		

Adjuster Report Page 4 of 5

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
54	1		*SET BUMPER LOWER REAR CLIP	Necessary	75.00 FS	*75.00 FS
55	2		*END PANEL SEAM SEALANT	Necessary	180.00 FS	*30.00 FS
56	1		*SET BOOT FINISHER CLIP	Not Necessary	55.00 FS	*-FS
57	1		*BOOT STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
58	1		*EXHAUST MOUNTING REAR	Serviceable	60.00 FS	*-FS
59	1		*BOOT STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
60	1		*BOOT TRIM BOARD CLIP	Not Necessary	60.00 FS	*-FS
61	1		*RENAULT TYRE RIM (ROUE 7J 16H)	Serviceable	385.00 FS	*-FS
62	1		*RENAULT TYRE 215/60/16	Serviceable	330.00 FS	*-FS
63	1		*TAILLAMP CLIP RH	Necessary	40.00 FS	*5.00 FS
64	1		*TAILLAMP CLIP LH	Necessary	40.00 FS	*5.00 FS
65	1		*REAR BUMPER PROTECTOR	Serviceable	170.00 FS	*-FS
66	1		*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	140.00 FS	*-FS
67	1		*SET REAR END PANEL INNER TRIM CLIP	Serviceable	55.00 FS	*-FS
F=Fra	ınchise	part. S=Spo	cNett. L=ListItemDisc.			
				Sub Total (S\$)	21,282.57	6,895.66
- List Item Discount on L Items 10.00/10.00% (S\$) 1,838.76 624.57						
				Total Parts (S\$)	19,443.81	6,271.09
			Report was unsubmitted during this p	rint-out.		

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	4,500.00	800.00
2	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
3	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
4	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
5	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
6	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
7	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	60.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	1,100.00
10	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	i New	170.00	0.00
11	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	40.00
13	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	60.00
14	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
15	TO PULL AND JACK OUT REAR BODY PANEL AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
	Gross Labour	r Cost (S\$)	12,340.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >