

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20007672/KDS3Q2

**Date:** 19/08/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800070061

**Claimant**  
**Vehicle No :** SLU5870U **Insured Vehicle No :** SMC4911A

Date of Loss: 21/07/2020 Nature of Claim: TP Claim No: 6206329343SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLU5870U</b>		
Make & Model:	TOYOTA SIENTA, 1.5 G CVT (A)	Engine No:	2NR8728224
Reg. Date:	07/12/2017 (Man. Year: 2016)	Chassis No:	NSP1707077402
Colour:	Metallic Silver	Odometer:	41098 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 3 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 3 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	24.75	24.75	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	550.00	330.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>904.75</b>	<b>574.75</b>	<b>330.00</b>	<b>36.47</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>450.00</b>		
<b>(\$\$)</b>	904.75	450.00	454.75	50.26
<b>+ GST 7.00/7.00% (\$\$)</b>	63.33	31.50	31.83	50.26
<b>Nett Amount (\$\$)</b>	<b>968.08</b>	<b>481.50</b>	<b>486.58</b>	<b>50.26</b>
<b>Global Sum Settlement (\$\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 27/07/2020

Date Inspected: 29/07/2020 Inspected At: Optima Werkz Pte Ltd (HQ)  
6 Kung Chong Road  
Singapore 159143

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	6		*REAR QUARTER PANEL LINER CLIPS RH	Necessary	33.00 FL	*33.00 FL
2	1		*REAR QUARTER PANEL RH (NPA)	Repair	0.00 FL	*- FL
3	1		*REAR SLIDING DOOR RH (NPA)	Repair	0.00 FL	*- FL
					<b>Sub Total (\$\$)</b>	<b>33.00 33.00</b>
					<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>8.25 8.25</b>
					<b>Total Parts (\$\$)</b>	<b>24.75 24.75</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	LABOUR CHARGES TO REMOVE,REPLACE,REPAIR,REFIX & READJUST ACCIDENT AREAS & ETC	New	300.00	150.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR QUARTER PANEL RH,REAR SLIDING DOOR RH & ETC	New	500.00	400.00
3	LABOUR CHARGES TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	80.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>880.00</b>	<b>550.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**