

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007682/R1RS3Q2
Date: 18/10/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	FBL1477P	Insured Vehicle No :	SMP6619M
Date of Loss:	16/07/2020	Nature of Claim:	TP
		Claim No:	9451755676SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL1477P		
Make & Model:	YAMAHA MT-09, 847cc	Engine No:	N701E062426
Reg. Date:	23/06/2016 (Man. Year: 2016)	Chassis No:	JYARN29S000004022
Colour:	White	Odometer:	107399 km
Engine Capacity:	847 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	120/70Z R17	Rear Tyre Size:	180/55Z R17
Front Left Side:	Michelin 4 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,450.00	1,205.00	1,245.00	50.82
Miscellaneous Items	0.00	0.00	0.00	
Labour	200.00	150.00	50.00	25.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,650.00	1,355.00	1,295.00	48.87
+ GST 7.00/7.00% (S\$)	185.50	94.85	90.65	48.87

Nett Amount (S\$)	2,835.50	1,449.85	1,385.65	48.87
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 27/07/2020

Date Inspected: 28/07/2020

Estimated Period of Repair: 1.0 days

Inspected At:

48 TOH GUAN RD EAST #02-140
Repairer: ComfortDelGro Engineering Pte Ltd (Ubi)

Adjuster: MOHD RASUL

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIREN ASSY	Distorted	1,600.00 FS	*780.00 FS
2	1		*FRONT CRASH BAR -LEFT	Scratched	425.00 FS	*425.00 FS
3	1		*FRONT CRASH BAR -RIGHT	Not Necessary	425.00 FS	*- FS
Total Parts (\$\$)					2,450.00	1,205.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FROM ACCIDENT SCENE	New	50.00	50.00
2	WORKMANSHIP	New	150.00	100.00
			Gross Labour Cost (S\$)	200.00
				150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >