

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
 Singapore 408933  
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20007690/UGS3Q2  
**Date:** 05/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 1900114787	
Claimant Vehicle No : SME7086B	Insured Vehicle No : SMM4107C	
Date of Loss: 23/07/2020	Nature of Claim: TP	Claim No: 3044539366SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>SME7086B</b>		
Make & Model: TOYOTA CAMRY, 2.0 ABS AIRBAG (A)	Engine No: 1AZE117315	
Reg. Date: 29/10/2008 (Man. Year: 2008)	Chassis No: MR053BK4107035950	
Colour: Black	Odometer: 161086 km	
Engine Capacity: 1998 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): <b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/55 R17	Rear Tyre Size: 215/55 R17	
Front Left Side: Dunlop 6 mm	Rear Left Side: Dunlop 6 mm	
Front Right Side: Dunlop 6 mm	Rear Right Side: Dunlop 6 mm	

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,912.60	0.00	1,912.60	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	800.00	580.00	42.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,292.60</b>	<b>800.00</b>	<b>2,492.60</b>	<b>75.70</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>230.48</b>	<b>56.00</b>	<b>174.48</b>	<b>75.70</b>
<b>Nett Amount (S\$)</b>	<b>3,523.08</b>	<b>856.00</b>	<b>2,667.08</b>	<b>75.70</b>
<b>+ Car Rental (3.0 x S\$120.00/day) (S\$)</b>		<b>360.00</b>		
<b>+ Doc/Search Fee (S\$)</b>		<b>2.00</b>		
<b>Nett Liability (S\$)</b>		<b>1,218.00</b>		

### INSPECTION

Date of Assignment: 27/07/2020		
Date Inspected: 27/07/2020	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair: 3.0 days		

**Adjuster:** MARCUS CHUA

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	545.10 F	*- FL
2	1		*REAR BUMPER REINFORCEMENT	Repair	365.20 F	*- FL
3	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	68.10 F	*- FL
4	1		*SET REAR BUMPER CLIPS	Not Necessary	50.00 F	*- FL
5	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	265.00 F	*- FL
6	1		*REAR END PANEL	Repair	619.20 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,912.60	0.00
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	0.00
Total Parts (S\$)	1,912.60	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO SPRAY RUST PROOFING	New	50.00	0.00
3	TO DISMANLE & REFIX CUSHION UPHOLSTERY	New	80.00	80.00
4	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	600.00	300.00
5	TO PUTTY & SPRAY PAINTING	New	600.00	400.00
Gross Labour Cost (S\$)			1,380.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >