

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20007692/QVF3E2

**Date:** 04/08/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900102318
Claimant Vehicle No : SGS184U	Insured Vehicle No :	SML7319T
Date of Loss: 25/07/2020	Nature of Claim:	TP Claim No: 4970816264SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGS184U	Engine No:	CDN203976
Make & Model:	AUDI A5 SPORTBACK, 2.0 TFSI QUATTRO (A)	Chassis No:	WAUZZZ8T2BA088656
Reg. Date:	28/07/2011 (Man. Year: 2011)	Odometer:	157650 km
Colour:	Black	Engine Capacity:	1984 cc
Market Value/New Car Price:	N/A	Sum Insured (S\$):	<b>Market Value/New Car Price</b>

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

#### CONDITION OF TYRES

Front Tyre Size:	255/35 R19	Rear Tyre Size:	255/35 R19
Front Left Side:	Kinforest 6 mm	Rear Left Side:	Kinforest 6 mm
Front Right Side:	Kinforest 6 mm	Rear Right Side:	Kinforest 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

#### INSPECTION

Date of Assignment:	27/07/2020	Inspected At:	Majesty Autowerks (HQ) 39 Woodlands Close, #01-36 Singapore 737856
Date Inspected:	28/07/2020	Estimated Period of Repair:	7.0 days

**Adjuster:** OI SUN PIN

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT LH DOOR	Crumpled	0.00 F	*- F
2	1		*FRT LH DOOR GARNISH INNER	Crumpled	0.00 F	*- F
3	1		*FRT LH DOOR GLASS REGULATOR	Bent	0.00 F	*- F
4	1		*FRT LH DOOR LOCK	Jammed	0.00 F	*- F
5	1		*FRT BUMPER	Repair	0.00 F	*- F
6	1		*FRT LH FENDER	Crumpled	0.00 F	*- F
7	1		*FRT INNER SHIELD	Crumpled	0.00 F	*- F
8	1		*REAR LH DOOR	Crumpled	0.00 F	*- F
9	1		*REAR LH FENDER	Crumpled	0.00 F	*- F
10	1		*FRT LEFT WHEEL BEARING	Jammed	0.00 F	*- F
11	1		*FRT LH TYRE	Cut	0.00 F	*- F
12	1		*REAR LH TYRE	Cut	0.00 F	*- F
13	1		*FRT LH WHEEL RIM	Cut	0.00 F	*- F
14	1		*REAR LH WHEEL RIM	Cut	0.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**      **0.00**      **0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

**< END OF ESTIMATES >**