源摩哆廠 **GUAN MOTOR WORKS**

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SMA5005U

No.	Qty				
	<u>List Items</u>		~ _		
1	1 Rear bumper 12/8-15	\$	n_1	,250.00	
2	1 Rear bumper LH reflector	in s	R	285.00	R
3	1 2 Rear bumper reverse sensor 0421.95	\$	Sin	957.80	4
4	1 set Rear bumper clips	\$	m	40.00	ت ا
5	2 Rear bumper side retainer	\$	PL	171.80	X
6	1 Rear bumper inner foam	\$	Su	189.50	R
7	1 Rear bumper inner reinforcement .	\$	n	695.90	x
8	1 LH taillamp $\int \!\! \mathcal{L}$	R\$	La	580.40	L
		\$	4	,170.40	
	Less 10	% \$		417.04	
	Total:	\$	3	,753.36	
	<u>Labour</u>				0 -
1	Labour Charges for remove/refit, panel beating, cutting	\$		900.00	2501
	welding and replacement of damages.			1	
2	To putty and spray Spray Paintings charges.	\$		800.00	400
3	To remove, refix and reset reverse sensors.	\$		80.00	601
4	To check wirings & lightings.	\$		30.00	15%
5	To supply and apply anti rust treatment	\$	nn	80.00	X
	Total:	\$	1	,890.00	
		J. Thu	- Crysley (

Total Parts and Labour: \$ 5,643.36

Not Notharn Rusing Bépains 3days 112mp 82400/2

LKK Auto Consultants hence notify

the Repairer of the following: To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: