

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20007715/QEA3Q2

**Date:** 15/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800125748

**Claimant**  
**Vehicle No :** SG1692J **Insured Vehicle No :** SMF2598T

Date of Loss: 16/07/2020 Nature of Claim: TP Claim No: 7757012035SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SG1692J</b>		
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO ABS (A)	Engine No:	902926C1096493
Reg. Date:	11/02/2016 (Man. Year: 2015)	Chassis No:	WEB62808323129409
Colour:	Multi-colour	Odometer:	357951 km
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5 (D)
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6/6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,096.70	0.00	8,096.70	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,638.00	1,673.00	965.00	36.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>10,734.70</b>	<b>1,673.00</b>	<b>9,061.70</b>	<b>84.42</b>
<b>+ Loss of Use (4.0 x S\$250.00/day) (S\$)</b>		1,000.00		
<b>(S\$)</b>		2,673.00		
<b>Liabe Amount (50.00%) (S\$)</b>		<b>1,336.50</b>		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>1,343.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,300.00</b>		

### INSPECTION

Date of Assignment: 23/07/2020

Date Inspected: 23/07/2020 Inspected At:

SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 3.0 days

---

**Adjuster:** OI SUN PIN**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*LAMP, SIDE MARKER:FOR MB CITARO O530 BUS	Serviceable	189.00 F	*- F
2	1		*LAMP, TAIL:REAR LH, FOR MB CITARO O530	Serviceable	1,261.71 F	*- F
3	1		*LAMP, EXTERIOR, REAR FOGLAMP, FOR MB CITARO	Serviceable	63.15 F	*- F
4	1		*BUMPER:REAR RH, FOR MB CITARO O530	Repair	837.84 F	*- F
5	1		*FLAP, RADIATOR FOR MB CITARO O530	Repair	5,445.00 F	*- F
6	1		*FLAP BATTERY	Repair	300.00 F	*- F

F=Franchise part.

**Total Parts (S\$)**    **8,096.70**    **0.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,590.00	795.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	1,048.00	878.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,638.00</b>	<b>1,673.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >