

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007727/T1GA3Q2

Date: 03/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100260845
Claimant
Vehicle No : SHD1379K **Insured Vehicle No :** SJD277D
Date of Loss: 25/07/2020 **Nature of Claim:** TP **Claim No:** 5914300373SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD1379K**
 Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M) Engine No: D4FBGZ122871
 Reg. Date: 14/06/2017 (Man. Year: 2016) Chassis No: TMAD281UVHJ127998
 Colour: Silver Odometer: 179865 km
 Engine Capacity: 1582 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
 Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	150.00	100.00	50.00	33.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	830.00	340.00	29.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,320.00	930.00	390.00	29.55
+ GST 7.00/7.00% (S\$)	92.40	65.10	27.30	29.55
Nett Amount (S\$)	1,412.40	995.10	417.30	29.55
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 27/07/2020
 Date Inspected: 27/07/2020 Inspected At: Premier Automotive Services Pte Ltd (HQ)
 23 Changi South Ave 2, #01-02
 Singapore 486443
 Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET N/S DOOR STICKER	Cut	100.00 FS	*100.00 FS
2	1		*SUNDRY	Not Necessary	50.00 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					150.00	100.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK -OUT ,STRAIGHTEN ,REPAIR ,RESHAPE AND ADJUST OF THE REAR N/S DOOR ETC	New	450.00	300.00
2	TO PUTTY AND SPRAY PAINTING ON REAR N/S DOOR ,REAR N/S FENDER,N/S ROCKER PANEL	New	600.00	500.00
3	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS	New	120.00	30.00
Gross Labour Cost (\$\$)			1,170.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >