

ASS. REC. BY:

Steve

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 3335 G

Yr Regn:

14/11/18

Type: ☒ M.C. ☐ M.Cycle ☐ Bus ☐ Van ☐ Lorry ☐ Taxi ☐ Prime Mover ☐

Truck / Tractor or

Make:

Volkswagen Golf

c.c

1395

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

39834

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZAY2RW 015563

Gen. Cond: ☒ Good ☐ Fair ☐ Poor ☐ BurntSteering: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orBrakes: ☒ In order ☐ Jammed ☐ Leaked ☐ Burnt orModl: ☒ NII ☐ S/Rim ☐ STD A/Rim or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

23/7/20

D.O.I.

27/7/20

Survey held at

Volkswagen, Alcedon Road

Des. of Damages: ☐ Frt ☐ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

Frd RM

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MK-85K

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, SI

Phone

Others

TOTAL

Rep. Forms:

Lump Sum / L.E.I. C: