

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007731/UDA3Q2

Date: 10/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800044440

Claimant
Vehicle No : SGL928C **Insured Vehicle No :** SMA2118Y

Date of Loss: 22/07/2020 Nature of Claim: TP Claim No: 6904402307SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGL928C	Engine No:	R18A11039451
Make & Model:	HONDA CIVIC, 1.8 L (A)	Chassis No:	JHMF16306S211990
Reg. Date:	06/09/2006 (Man. Year: 2006)	Odometer:	234505 km
Colour:	Black		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,742.08	1,902.00	840.08	30.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,040.00	1,680.00	360.00	17.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,782.08	3,582.00	1,200.08	25.10
Approved Total (Overridden) (\$\$)		2,500.00		
(\$\$)	4,782.08	2,500.00	2,282.08	47.72
+ GST 7.00/7.00% (\$\$)	334.75	175.00	159.75	47.72
Nett Amount (\$\$)	5,116.83	2,675.00	2,441.83	47.72
+ Car Rental (5.0 x S\$120.00/day) (\$\$)		600.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		3,277.00		

INSPECTION

Date of Assignment: 12/08/2020

Date Inspected: 12/08/2020 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)
Blk 3011, Bedok Industrial Park E.,
#01-2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	638.70 FL	*638.00 FL
2	1		*REAR BUMPER RETAINER RH	Not Necessary	20.40 FL	*- FL
3	1		*REAR BUMPER RETAINER LH	Not Necessary	20.40 FL	*- FL
4	1		*TAIL LAMP LH	Scratched	409.80 FL	*280.40 FL
5	1		*REAR INNER BOOTLAMP LH	Scratched	164.20 FL	*164.20 FL
6	1		*BOOTLID HINGE LH	Not Necessary	55.80 FL	*- FL
7	1		*BOOTLID HINGE RH	Not Necessary	55.80 FL	*- FL
8	1		*BOOTLID LOGO -CIVIC	Necessary	20.70 FL	*20.70 FL
9	1		*BOOTLID LOGO -1.8 I-VTEC	Necessary	78.00 FL	*78.00 FL
10	1		*BOOTLID EMBLEM LOGO	Necessary	85.00 FL	*35.00 FL
11	1		*BOOTLID CHROME (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*BOOTLID	Dented / Bent	892.20 FL	*610.70 FL
13	1		*END PANEL	Badly Dented	300.50 FL	*300.50 FL
14	1		*END PANEL TOP GARNISH	Not Necessary	66.60 FL	*- FL
15	1		*REAR BUMPER LOWER MUDFLAP LH	Not Necessary	75.00 FL	*- FL
16	1		*BOOTLID LOCK ASSEMBLY	Not Necessary	194.50 FL	*- FL
17	1		*TAIL LAMP INNER PANEL LH (NPA)	Repair	0.00 FS	*- FS
18	1		*SPARE TYRE PANEL (NPA)	Repair	0.00 FS	*- FS
19	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS
20	1		*SET REVERSE SENSOR	Cracked / Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,357.60	2,327.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	615.52	425.50
Total Parts (\$\$)	2,742.08	1,902.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	800.00	700.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	900.00	850.00
3	ANTI RUST COATING	New	150.00	60.00
4	WIRING	New	40.00	20.00
5	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	50.00
Gross Labour Cost (\$\$)			2,040.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >