

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20007733/AVF3E2

**Date:** 02/11/2020

### REFERENCE

Insured/Claimant:	FERNANDO ALEJANDRO ESTRADA	Policy No:	2100470252
Date of Loss:	24/07/2020	Nature of Claim:	OD Claim No: 3154521638SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD2854B	Engine No:	CVN008291
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF45GA063303
Reg. Date:	10/06/2016 (Man. Year: 2016)	Odometer:	14708 km
Colour:	Black		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$33,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,097.00	4,502.64	8,594.36	65.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,932.00	3,402.00	6,530.00	65.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>23,029.00</b>	<b>7,904.64</b>	<b>15,124.36</b>	<b>65.68</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	22,429.00	7,304.64	15,124.36	67.43
<b>+ GST 7.00/7.00% (S\$)</b>	1,570.03	511.32	1,058.71	67.43
<b>Nett Amount (S\$)</b>	<b>23,999.03</b>	<b>7,815.96</b>	<b>16,183.07</b>	<b>67.43</b>

### INSPECTION

Date of Assignment:	27/07/2020		
Date Inspected:	27/07/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Repair	758.00 FS	*- FS
2	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	200.00 FS	*- FS
3	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	49.00 FS	*- FS
4	1		*FRONT FENDER BRACKET - LH	Not Necessary	35.00 FS	*- FS
5	1		*FRONT FENDER BRACKET	Not Necessary	31.00 FS	*- FS
6	1		*FRONT FENDER BRACE	Not Necessary	117.00 FS	*- FS
7	1		*WHEEL HOUSING LINER - LH	Not Necessary	237.00 FS	*- FS
8	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	90.00 FS	*- FS
9	1		*WHEEL SPOILER	Not Necessary	73.00 FS	*- FS
10	1		*STONE CHIP GUARD	Necessary	50.00 FS	*39.92 FS
11	1		*FRONT DOOR - LH	Dented	2,354.00 FS	*1,883.20 FS
12	1		*FRONT DOOR OUTER SEAL - LH	Necessary	203.00 FS	*162.00 FS
13	1		*BONDING AGENT	Necessary	47.00 FS	*37.12 FS
14	1		*CLEANING SOLUTION	Necessary	65.00 FS	*51.76 FS
15	1		*FRONT DOOR CATCH	Not Necessary	104.00 FS	*- FS
16	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	870.00 FS	*- FS
17	1		*DOOR HANDLE TRIM PLATE	Not Necessary	87.00 FS	*- FS
18	1		*EXTERIOR MIRROR MOUNTING - LH	Damaged	1,077.00 FS	*861.60 FS
19	1		*MIRROR CAP - LH	Not Necessary	261.00 FS	*- FS
20	1		*MIRROR GLASS - LH	Cut	1,196.00 FS	*956.80 FS
21	1		*CORNER TRIM - LH	Cut	45.00 FS	*35.84 FS
22	1		*WINDOW GUIDE TRIM STRIP	Not Necessary	254.00 FS	*- FS
23	1		*WINDOW SLOT SEAL	Not Necessary	303.00 FS	*- FS
24	1		*FRONT DOOR WINDOW - LH	Not Necessary	286.00 FS	*- FS
25	1		*REAR DOOR - LH	Repair	2,354.00 FS	*- FS
26	1		*REAR DOOR OUTER SEAL - LH	Not Necessary	203.00 FS	*- FS
27	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
28	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
29	1		*SEALING STRIP	Not Necessary	16.00 FS	*- FS
30	1		*REAR DOOR CATCH	Not Necessary	119.00 FS	*- FS
31	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	563.00 FS	*- FS
32	1		*FRONT ALUMINIUM RIM - LH	Cut	589.00 FS	*471.20 FS
33	1		*SUNDRIES	Necessary	300.00 FS	*3.20 FS
34	1		*DEFORMATION ELEMENT BRACKET - LH	Not Necessary	49.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**    **13,097.00**    **4,502.64**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	280.00
2	TO DISMANTLE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY AND LHS FRONT DOOR WINDOW GLASS	New	350.00	350.00
3	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS	New	400.00	0.00
4	TO DISMANTLE FRONT BUMPER. TO RENEW LHS FRONT FENDER, LHS FRONT DOOR AND LHS REAR DOOR. TO REPAIR LHS UPPER A-PILLAR. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,850.00	500.00
5	TO RESPRAY LHS FRONT FENDER, LHS UPPER A-PILLAR, LHS FRONT DOOR, DOOR HANDLE AND LHS REAR DOOR	New	4,000.00	1,650.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
8	TO RESPRAY LHS WING MIRROR COVER	New	300.00	150.00
<b>Gross Labour Cost (S\$)</b>			<b>9,932.00</b>	<b>3,402.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >