

ASS. REC. BY:

Steve

REF:

CC/AIG20007735/Eka3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

G88 4579L

Yr Regn:

26/3/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna

c.c

2982

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

366.327

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT FAT 35430-K200409

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

RISC

R:

h

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

25/7/00

D.O.I.

27/7/00

Survey held at

Ryder Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Pending GIA report
4/8/00 Finalise \$2950, 5 days (O/S in)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Rep. Formed:

Lump Sum / U.C. /

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

Store (LKK)

WH PPL

27/7/20, 11.30am

ESTIMATE OF REPAIR

Veh# GBB4579L 5 dys

Accident Date : 25/7/2020

L/S, My AL M

Location : PIE TOWARDS TUAS BEFORE THOMSON FLYOVER

Model:

TOYOTA DYNA
(26/3/2009)

3P:

SLP8671J (AIG)

Owe GIA Report

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tail-gate / DD	1,800.00	1500	-
2	1 pc	Rear tail-gate DYNA emblem / MK	58.60	/	-
3	4 pcs	Rear tail-gate hinges pin / BT	70.00	/	-
4	4 pcs	Rear tail-gate hinges / BT	140.00	/	-
5	1 pc	Rear tail-gate n/s lock / BT	85.60	/	-
6	1 pc	Rear tail-gate lower panel / DD	881.20	/	-
7	2 pcs	Rear n/s & o/s tail-lamp (LH) ? / ECR4	378.70	296.80	-
8	2 pcs	Rear n/s & o/s tail-lamp bracket (LH) / BT	163.90	81.95	-
9	1 pc	Rear reg. no. plate bracket / BT	89.15	/	-
10	1 pc	Rear tail-gate 70KMPH emblem / MK	-	20.00	-
11	1 pc	Rear reg. no. plate / BT	-	28.00	-
12	1 pc	Rear n/s stopper / NA	-	86.20	X
13	2 pcs	Rear o/s & n/s reverse sensor / SU	-	560.00	299
Sub-Total:			3,667.15	694.20	0.00
			25%	0%	0%
After Less %:			2,750.36	694.20	0.00
Labour					
1		To dismantle damaged, straighten and welding.	1,000.00	600	
2		To spray painting	700.00	499	
3		To check wiring.	50.00	30	
4		To re-seal anti-rust.	50.00	30	
Sub-Total:			1,800.00		
Total:			5,244.56		

P-3203-10

N-248

L-1060

-25%
2492.32

= 3710-32

L/S - 2968.25

= 2950

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental Part(s) must be resurveyed and is subject to final approval from Insurance Company

8778 1999

Acknowledged by Repairer
Signature: GBB4579L ESTIMATEPg1
Date:

Mobil 1



PAYNOW