

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007744/T1PS3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900232142

Claimant Vehicle No : SHD3350D **Insured Vehicle No :** GBK3335H

Date of Loss: 27/07/2020 Nature of Claim: TP Claim No: 0052411549SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD3350D**

Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A) Engine No: D4DFU529169

Reg. Date: 21/07/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU092192

Colour: Blue Odometer: 619147 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16

Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm

Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,587.92	2,502.24	85.68	3.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,070.00	880.00	190.00	17.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,657.92	3,382.24	275.68	7.54
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	3,657.92	2,700.00	957.92	26.19
+ GST 7.00/7.00% (S\$)	256.05	189.00	67.05	26.19
Nett Amount (S\$)	3,913.97	2,889.00	1,024.97	26.19
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$110.67/day) (S\$)		332.01		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,378.50		
Global Sum Settlement (S\$)		3,300.00		

INSPECTION

Date of Assignment: 28/07/2020

Date Inspected: 28/07/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)

59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER COVER	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*FRONT LH FENDER	Bent	663.00 FL	*663.00 FL
3	1		*FRONT BUMPER SIDE BRACKET LH	Necessary	24.60 FL	*24.60 FL
4	1		*HEAD LAMP LH	Cut	1,388.00 FL	*1,388.00 FL
5	1		*LH WHEEL HUB COVER	Not Necessary	107.10 FL	* - FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,234.90	3,127.80
- List Item Discount on L Items 20.00/20.00% (\$)	646.98	625.56

Total Parts (\$)	2,587.92	2,502.24
-------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	450.00	420.00
2	SPRAY PAINTING CHARGE	New	500.00	400.00
3	CHECK LIGHTING	New	60.00	30.00
4	TUFF KOTE	New	60.00	30.00
Gross Labour Cost (\$\$)			1,070.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >