Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20007752/ESF3E2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100453015

Claimant Vehicle SMR9555H Insured Vehicle No: SGE5533L

No:

Date of Loss: 24/07/2020 Nature of Claim: TP Claim No: 7838071032SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SMR9555H

Make & Model: SUZUKI SWIFT, 1.3 (A) Engine No: M13A2203469

Reg. Date: 27/07/2010 (Man. Year: 2009) Chassis No: JSAEZC11S00551047

Colour: Black Odometer: 166436 km

Engine Capacity: 1328 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195/50 R15 Rear Tyre Size: 195/50 R15
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

**INSPECTION** 

Date of Assignment: 28/07/2020

Date Inspected: 28/07/2020 Inspected At: 3023A Ubi Road 1, #01-63

Repairer: Sin Seng Hong Spray Painting &

Service (HQ)

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

# **Recommended Parts**

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
1	1	*REAR NUMBER PLATE	Broken	0.00 F	*- F
2	1	*REAR NUMBER PLATE BASE	Cut	0.00 F	*- F
3	1	*REAR BUMPER	Broken	0.00 F	*- F
4	1	*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
5	2	*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
6	1	*REAR END PANEL	Repair	0.00 F	*- F
7	1	*REAR LH TAILLAMP	Broken	0.00 F	*- F
8	1	*REAR RH TAILLAMP	Broken	0.00 F	*- F
F=Fra	anchise part.				
			Total Parts (S\$)	0.00	0.00

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >