

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007760/T1GA3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700005264
Claimant
Vehicle No : SKW1219D **Insured Vehicle No :** SFC1860R
Date of Loss: 26/07/2020 Nature of Claim: TP Claim No: 2791254407SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW1219D**
Make & Model: MERCEDES-BENZ 316CDI/3665, 2.1 (A) Engine No: 65195532755943
Reg. Date: 19/10/2015 (Man. Year: 2015) Chassis No: WDB9066332P129310
Colour: White Odometer: 0 km
Engine Capacity: 2143 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/65 R15 Rear Tyre Size: 235/65 R15
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	755.19	755.19	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	730.00	530.00	42.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,015.19	1,485.19	530.00	26.30
+ GST 7.00/7.00% (S\$)	141.06	103.96	37.10	26.30
Nett Amount (S\$)	2,156.25	1,589.15	567.10	26.30
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,891.15		

INSPECTION

Date of Assignment: 28/07/2020
Date Inspected: 31/08/2020 Inspected At: Woon Meng Motor Pte Ltd (Bukit Batok)
50 Bukit Batok Street 23,, #01-06
Midview Building
Singapore 659578
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FENDER N/S	Bent	473.75 FL	*473.75 FL	
2	1		*FRONT FENDER LAMP N/S	Cracked	103.88 FL	*103.88 FL	
3	1		*FRONT FENDER LOWER PROTECTOR N/S	Cut	255.63 FL	*255.63 FL	
4	2		*NUT	Necessary	5.84 FL	*5.84 FL	
					Sub Total (\$)	839.10	839.10
					- List Item Discount on L Items 10.00/10.00% (\$)	83.91	83.91
					Total Parts (\$)	755.19	755.19

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REPAIR ,REPLACE & INSTALL DAMAGED PARTS	New	450.00	250.00
2	TO R&R WIRING	New	60.00	30.00
3	TO NUMBERING LOGO	New	350.00	200.00
4	TO PUTTY & SPRAY PAINTING	New	400.00	250.00
			Gross Labour Cost (\$\$)	730.00
			1,260.00	

Report was unsubmitted during this print-out.

< END OF ESTIMATES >