

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110  
Mobile : 9855 6879 Email : automaxsurvey@gmail.com  
Registration No. 53110062J

Billing To: Chai Siew Yin  
c/o Hup Ley Huat Motor Spray Painting Services  
Blk 1, #01- 35  
Kaki Bukit Ave 6  
Singapore 417883

Invoice no.: TP20020012

Date: 03 JUL 2020


Vehicle no: SLN4958U

Model : TOYOTA HARRIER

ITEM	DESCRIPTION	AMOUNT
1	Date of Inspection : 19 FEB 2020 Copies of the inspection / survey report Correspondence, postages and etc.	\$ 680.00
2	Photography Services Develop photographs Storage of digital photographs	
3.	To submit report by hand.	
4.	Charges on photocopies, posting, faxes and others incidental works entrusted.	
5	Transportation Charges	
6	Reinspection Charges	
	TOTAL :	\$ 680.00

**Notes :**

1. All cheque payment should be "crossed" and made payable to "Automax Survey".
2. Please contact us if there are further enquiries on the invoice.



Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110  
Mobile : 9855 6879      Email : [automaxsurvey@gmail.com](mailto:automaxsurvey@gmail.com)  
Registration No. 53110062J

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	215/50/R16	Bridgestone	9.00 mm	Sport
REAR O/S :	215/50/R16	Bridgestone	9.00 mm	Sport
FRONT N/S :	215/50/R16	Bridgestone	9.00 mm	Sport
REAR N/S :	215/50/R16	Bridgestone	9.00 mm	Sport

## AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 07 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

#### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SLN4958U

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Tailgate ✓	bent/distorted	\$ 1,418.85	\$ 1,418.85 ✓
1 pc	Tailgate lock ✕ SVC	bend/distorted	\$ 561.60	\$ 561.60
1 pc	Tailgate lock striker ✕ SVC	damaged	\$ 43.70	\$ 43.70
1 pc	Tailgate weather strip ✕ SVC	wrapped/deformed	\$ 271.75	\$ 271.75
1 pc	Tailgate badge ✕ SVC	necessary	\$ 27.25	\$ 27.25
1 pc	Tailgate emblum "HARRIER" ✓	necessary	\$ 28.90	\$ 28.90 ✓
1 pc	Tailgate reflector ✕ SVC	bend/distorted	\$ 479.95	\$ 479.95
4 pcs	Tailgate reflector clips ✕ SVC	necessary	\$ 51.60	\$ 51.60
2 pcs	Tailgate relactor sealant ✕ SVC	wrapped/deformed	\$ 100.00	\$ 100.00
2 pcs	Rear number plate lamp ✕ SVC	electronically shocked	\$ 262.70	\$ 262.70
1 pc	Tail lamp ✓	electronically shocked	\$ 525.73	\$ 525.73 ✓
1 pc	Tail lamp sealant ✕ SVC	necessary	\$ 65.00	\$ 65.00
2 pcs	Tail lamp clips ✕ SVC	necessary	\$ 30.00	\$ 30.00
1 pc	Rear bumper ✓	bend/deformed	\$ 1,218.25	\$ 1,218.25 955.1
2 pcs	Rear bumper side retainer ✕ SVC	distorted	\$ 244.20	\$ 244.20
2 pcs	Rear bumper side attachment ✕ SVC	bent/distorted	\$ 264.70	\$ 264.70
1 pc	Rear bumper lower cover ✕ SVC	deformed	\$ 328.90	\$ 328.90
1 pc	Rear bumper sponge ✓	deformed	\$ 222.70	\$ 222.70 188.5
2 pcs	Rear bumper reflectors ✕ SVC	deformed	\$ 120.00	\$ 120.00
10 pcs	Rear bumper clips ✓	necessary	\$ 50.00	\$ 50.00 ✓
1 pc	Rear end panel ✕ SVC	dent/distorted	\$ 591.80	\$ 591.80
1 pc	Rear floor panel ✕ SVC	distorted - repair	\$ 472.70	\$ -
				25 3167.08
				-20%: 2375.31
Parts Sub-Total			\$ 7,380.28	\$ 6,907.58
Discount 25.00%			\$ 1,845.07	\$ 1,726.90
			\$ 5,535.21	\$ 5,180.69

Vehicle Number : SLN4958U

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 pc	Rear number plate ✕ SVC	distorted	\$ 65.00	\$ 65.00
1 pc	Rear number plate casing ✕ SVC	distorted	\$ 45.00	\$ 45.00
1 set	Rear bumper parking sensor ✓	electronically shocked	\$ 280.00	\$ 250.00 200
1 pc	Rear bumper parking sensor wire ✕ SVC	open circuit	\$ 180.00	\$ 180.00
Special Nett Sub-Total			\$ 570.00	\$ 540.00
Spare Parts Total			\$ 6,105.21	\$ 5,720.69

## LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 6,105.21	\$ 5,720.69
1	Towing	\$ 120.00	\$ 120.00 X
2	To tuff coat affected areas	\$ 180.00	\$ 150.00 X
3	To remove and refix interior upholstery	\$ 180.00	\$ 150.00 60
4	To remove & transfer tailgate mechanism	\$ 180.00	\$ 150.00 60
5	To respray affected areas	\$ 1,600.00	\$ 1,400.00 600
6	To renew damaged parts, straighten and repair rear fender inner, front and rear chassis member and aligned all parts	\$ 1,600.00	\$ 1,400.00 400
7	To remove and replace reverse sensor.	\$ 180.00	\$ 150.00 40
8	To polish and coating for new paint	\$ 1,200.00	\$ 1,200.00 X
			1160
	Total	\$ 11,345.21	\$ 10,440.69

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 9,000.00

Fong Kok Heng  
Qualified Appraiser



3735.31

-20%: 3000

4 days











AUTOMAX



AUTOMAX



AUTOMAX



AUTOM





URVEY







AUTOMAX



IRVEY

AUTOMA



AUTOMA





