

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20007761/BGA3Q2

**Date:** 15/03/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100468176  
**Claimant**  
**Vehicle No :** SDY6269Z **Insured Vehicle No :** SLC9010D  
Date of Loss: 27/07/2020 Nature of Claim: TP Claim No: 7777723209SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDY6269Z**  
Make & Model: NISSAN SUNNY, 1.6 EX (A) Engine No: QG16426179  
Reg. Date: 17/03/2008 (Man. Year: 2007) Chassis No: JN1CFAN16Z0109805  
Colour: Beige Odometer: 324151 km  
Engine Capacity: 1597 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,623.93	5,048.56	7,575.37	60.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,050.00	2,400.00	2,650.00	52.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>17,673.93</b>	<b>7,448.56</b>	<b>10,225.37</b>	<b>57.86</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,950.00</b>		
<b>(S\$)</b>	17,673.93	5,950.00	11,723.93	66.33
<b>+ GST 7.00/7.00% (S\$)</b>	1,237.18	416.50	820.68	66.33
<b>Nett Amount (S\$)</b>	<b>18,911.11</b>	<b>6,366.50</b>	<b>12,544.61</b>	<b>66.33</b>
<b>+ Car Rental (11.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		1,177.00		
<b>+ Doc/Search Fee (S\$)</b>		36.45		
<b>Nett Liability (S\$)</b>		<b>7,579.95</b>		

#### INSPECTION

Date of Assignment: 28/07/2020  
Date Inspected: 28/07/2020 Inspected At: 160 SIN MING DR  
#01-14 SIN MING  
Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)  
Estimated Period of Repair: 9.0 days

---

**Adjuster:** Lim Teow Guan

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	782.60 FL	*655.00 FL
2	1		*BOOTLID LOGO	Necessary	108.90 FL	*56.90 FL
3	1		*BOOTLID EMBLEM SUNNY	Necessary	118.60 FL	*56.20 FL
4	1		*BOOTLID EMBLEM EX SALOON	Necessary	103.60 FL	*56.20 FL
5	1		*BOOTLID EMBLEM CVTC	Necessary	97.00 FL	*54.80 FL
6	1		*BOOTLID EMBLEM E-THROTTLE	Necessary	69.00 FL	*46.50 FL
7	2		*BOOTLID OUTER CHROME GARNISH	Broken	972.40 FL	*369.10 FL
8	1		*BOOTLID INNER TRIMBOARD	Not Damaged	198.30 FL	*- FL
9	2		*BOOTLID NUMBER PLATE LAMP	Not Damaged	172.80 FL	*- FL
10	1		*BOOTLID WEATHERSTRIP	Distorted	286.30 FL	*109.30 FL
11	1		*BOOTLID HINGE	O/S Bent	373.80 FL	*170.00 FL
12	1		*BOOTLID LOCK	Jammed	214.50 FL	*117.00 FL
13	1		*BOOTLID STRIKER	Not Damaged	96.40 FL	*- FL
14	1		*REAR BUMPER	Dented	595.20 FL	*595.20 FL
15	1		*REAR BUMPER OUTER CHROME MOULDING	Dented	184.60 FL	*184.60 FL
16	2		*REAR BUMPER SIDE RETAINER	Necessary	174.80 FL	*116.00 FL
17	2		*REAR BUMPER REINFORCEMENT STOPPER	Not Damaged	336.00 FL	*- FL
18	1		*REAR END PANEL	Dented	583.60 FL	*376.20 FL
19	1		*REAR END PANELTOP GARNISH	Broken	196.50 FL	*196.50 FL
20	2		*REAR FENDER	Repair	1,577.20 FL	*- FL
21	2		*REAR FENDER INNER TRIM BOARD	Not Damaged	429.80 FL	*- FL
22	1		*REAR FENDER AIR VENT	Not Damaged	181.50 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Not Necessary	184.20 FL	*- FL
24	1		*SPARE TYRE PANEL	Dented	898.60 FL	*774.10 FL
25	1		*SPARE TYRE TOP BOARD	Not Damaged	241.80 FL	*- FL
26	2		*TAILLAMP	Broken	864.80 FL	*864.80 FL
27	2		*TAILLAMP LOWER BRACKET	No such part	130.80 FL	*- FL
28	2		*TAILLAMP BASE PANEL	Repair	429.60 FL	*- FL
29	1		*EXHAUST PIPE	Not Damaged	855.00 FL	*- FL
30	1		*EXHAUST MOUNTING	Not Damaged	79.50 FL	*- FL
31	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
32	1		*BOOTLID SEALANT	Necessary	100.00 FS	*30.00 FS
33	2		*BOOTLID OUTER CHROME GARNISH CLIPS	Necessary	100.00 FS	*30.00 FS
34	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
35	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
36	1		*REAR END PANEL SEALANT	Repeated	100.00 FS	*- FS
37	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
38	2		*REAR FENDER SEALANT	Necessary	200.00 FS	*30.00 FS
39	2		*REAR FENDER INNR TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
40	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*60.00 FS
41	1		*REAR WINDSCREEN SEALANT	Necessary	100.00 FS	*100.00 FS
42	1		*REAR WINDSCREEN PRIMER AND CLEANER	Necessary	80.00 FS	*80.00 FS
43	1		*SPARE TYRE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
44	2		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS
45	2		*TAILLAMP SEAL	Not Necessary	120.00 FS	*- FS
46	1		*TAILLAMP BASE PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
47	1		*REAR NUMBER PLATE W/COWLING	Bent	80.00 FS	*50.00 FS
48	2		*REVERSE SENSOR WITH MODULE	Scratched	500.00 FS	*200.00 FS
49	1		*BRAKEDOWN SIGN	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 13,777.70 5,528.40**  
**- List Item Discount on L Items 10.00/10.00% (\$\$) 1,153.77 479.84**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					<b>Total Parts (S\$)</b>	<b>12,623.93</b>	<b>5,048.56</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	R&R BOOTLID COMPONENT	New	100.00	50.00
2	R&R REVERSE SENSOR AND SPRAY PAINT	New	100.00	60.00
3	R&R EXHAUST PIPE	New	250.00	0.00
4	R&R FUEL PIPE	New	180.00	0.00
5	R&R REAR WINDSCREEN	New	180.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	CHECK WIRING	New	80.00	30.00
8	CONDUCT WATER LEAKAGE TEST	New	60.00	0.00
9	RUST PROOFING	New	200.00	60.00
10	SPRAY PAINTING	New	1,800.00	1,200.00
11	PANEL BEAT	New	1,800.00	1,000.00
			<b>Gross Labour Cost (\$\$)</b>	<b>2,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >