

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20007763/KCF3E2

**Date:** 03/03/2022

### REFERENCE

Insured/Claimant: RH2S DECO CURTAINS Policy No: 2070064703  
Date of Loss: 24/06/2020 Nature of Claim: OD Claim No: 3879146433SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBH3943T**  
Make & Model: TOYOTA HIACE, 2.0 (M) Engine No: 1KD2803526  
Reg. Date: 23/05/2018 (Man. Year: 2018) Chassis No: JTFHT02P300242812  
Colour: Silver Odometer: 0 km  
Engine Capacity: 2982 cc  
Market Value/New Car Price: S\$56,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195R15X8 Rear Tyre Size: 195R15X8  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 2 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 2 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	41,328.35	28,553.00	12,775.35	30.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,810.00	4,950.00	1,860.00	27.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>48,138.35</b>	<b>33,503.00</b>	<b>14,635.35</b>	<b>30.40</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>26,000.00</b>		
<b>- Excess (S\$)</b>	800.00	800.00	0.00	0.00
<b>(S\$)</b>	47,338.35	25,200.00	22,138.35	46.77
<b>+ GST 7.00/7.00% (S\$)</b>	3,313.68	1,764.00	1,549.68	46.77
<b>Nett Amount (S\$)</b>	<b>50,652.03</b>	<b>26,964.00</b>	<b>23,688.03</b>	<b>46.77</b>

### INSPECTION

Date of Assignment: 28/07/2020

Date Inspected: 28/07/2020 Inspected At:

Tai Cheng Motor Vehicle Spray Painting (HQ)  
Block 10 Ang Mo Kio Industrial Park 2A, #01-03  
AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 24.0 days

**Adjuster:** KENNETH KONG

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN GLASS	Cracked	1,379.50 FL	*1,379.50 FL
2	1		*WINDSCREEN SIDE MOULDING	Necessary	62.30 FL	*62.30 FL
3	1		*FRONT WIPER PANEL GARNISH	Dented	495.10 FL	*495.10 FL
4	1		*WIPER PANEL CORNER GARNISH O/S	Missing	26.80 FL	*26.80 FL
5	1		*CORNER PANEL TOP INNER RUBBER	Cut	33.50 FL	*33.50 FL
6	1		*FRONT BONNET	Bent	756.60 FL	*756.60 FL
7	1		*BONNET EMBLEM	Necessary	66.20 FL	*66.20 FL
8	2		*BONNET HINGE	Bent/Distorted	97.80 FL	*97.80 FL
9	1		*BONNET INNER LOWER CORNER RUBBER O/S	Missing	41.70 FL	*41.70 FL
10	1		*FRONT GRILLE TOP	Missing	191.50 FL	*191.50 FL
11	1		*FRONT GRILLE LOWER	Missing	330.80 FL	*330.80 FL
12	1		*FRONT GRILLE BASE	Missing	491.10 FL	*491.10 FL
13	1		*FRONT BUMPER	Cracked	496.40 FL	*496.40 FL
14	1		*FRONT BUMPER GRILLE CENTRE	Missing	154.30 FL	*154.30 FL
15	1		*FRONT BUMPER FOG LAMP GARNISH O/S	Dented	58.10 FL	*58.10 FL
16	1		*FRONT BUMPER LOWER REINFORCEMENT	Bent	304.40 FL	*304.40 FL
17	1		*FRONT BUMPER TOP REINFORCEMENT BEAM	Bent	159.10 FL	*159.10 FL
18	1		*BUMPER VERTICAL REINFORCEMENT BRACKET O/S	Distorted	54.50 FL	*54.50 FL
19	1		*FRONT HEADLAMP	Broken	848.70 FL	*848.70 FL
20	1		*FRONT SUPPORT PANEL	Bent	333.60 FL	*333.60 FL
21	1		*FRONT BRACE PANEL	Repair	43.40 FL	*- FL
22	1		*FRONT CHASIS FRONT BRACKET O/S	Bent	422.10 FL	*422.10 FL
23	1		*BUMPER TOW HOOK COVER	Missing	26.70 FL	*26.70 FL
24	1		*AIR CON CONDENSOR	Punctured	1,216.10 FL	*1,216.10 FL
25	1		*RADIATOR	Punctured	2,317.20 FL	*2,317.20 FL
26	1		*RADIATOR FAN COWLING	Cracked	266.30 FL	*266.30 FL
27	1		*CHASIS FRONT SIDE MEMBER O/S	Serviceable	1,293.70 FL	*- FL
28	1		*AIR CON SUCTION PIPE FRONT	Dented	464.60 FL	*464.60 FL
29	1		*AIR CON SUCTION PIPE REAR	Serviceable	662.70 FL	*- FL
30	1		*AIR CON LIQUID PIPE	Serviceable	262.70 FL	*- FL
31	1		*AIR CON DELIVERY PIPE	Serviceable	298.40 FL	*- FL
32	1		*AIR CON DISCHARGE PIPE FRONT	Punctured	344.80 FL	*344.80 FL
33	1		*AIR CON DISCHARGE PIPE REAR	Serviceable	582.60 FL	*- FL
34	1		*AIR INTERCOOLER	Serviceable	1,358.20 FL	*- FL
35	1		*WASHER TANK	Serviceable	159.10 FL	*- FL
36	1		*BRAKE MASTER PUMP	Jammed	841.70 FL	*841.70 FL
37	1		*BRAKE SERVO UNIT	Dented	1,256.90 FL	*1,256.90 FL
38	1		*FRONT CORNER PANEL	Bent	193.90 FL	*193.90 FL
39	1		*FRONT BUMPER SIDE RETAINER O/S	Cracked	193.10 FL	*193.10 FL
40	1		*AIR CLEANER BOX	Missing	637.40 FL	*637.40 FL
41	1		*AIR INTAKE AIR DUCT	Missing	85.20 FL	*85.20 FL
42	1		*FRONT DOOR HARNESS WIRE	Torn	1,587.90 FL	*1,587.90 FL
43	1		*FIRE WALL WIRE HARNESS TO INNER DASHBOARD	Torn	2,750.10 FL	*2,750.10 FL
44	1		*HARNESS WIRE CONNECTOR BOX	Serviceable	84.60 FL	*- FL
45	1		*FRONT OUTER PILLAR O/S	Buckled	377.10 FL	*377.10 FL
46	1		*FRONT INNER PILLAR O/S	Buckled	360.60 FL	*360.60 FL
47	1		*FRONT STEP PANEL INNER PANEL O/S	Bent	422.80 FL	*422.80 FL
48	1		*FRONT STEP PANEL TOP GARNISH O/S	Distorted	152.70 FL	*152.70 FL
49	1		*WHEEL ARCH PANEL O/S	Buckled	260.30 FL	*260.30 FL
50	1		*WHEEL ARCH PANEL TOP GARNISH O/S	Buckled	275.30 FL	*275.30 FL
51	1		*FRONT PILLAR INNER COVER TRIM GARNISH O/S	Dented	168.80 FL	*168.80 FL
52	1		*WHEEL ARCH PANEL EDGE RUBBER O/S	Cut	61.40 FL	*61.40 FL
53	1		*FUEL ACCELERATOR PEDAL	Bent	369.70 FL	*369.70 FL
54	1		*FRONT DOOR O/S	Buckled	1,794.10 FL	*1,794.10 FL
55	1		*FRONT DOOR SIDE MIRROR O/S	Cut	1,015.80 FL	*1,015.80 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*DOOR OUTER TOP MOULDING O/S	Buckled	79.10 FL	*79.10 FL
57	1		*DOOR WINDOW GLASS O/S	Shattered	432.60 FL	*432.60 FL
58	1		*DOOR GLASS CHANNEL RUBBER O/S	Distorted	215.50 FL	*215.50 FL
59	1		*DOOR INNER LOCK O/S	Jammed	492.10 FL	*492.10 FL
60	1		*DOOR LOCK STRIKER O/S	Repair	48.40 FL	*- FL
61	1		*DOOR CHANNEL O/S	Distorted	172.90 FL	*172.90 FL
62	1		*DOOR HINGE UPPER O/S	Bent	78.20 FL	*78.20 FL
63	1		*DOOR HINGE LOWER O/S	Bent	78.20 FL	*78.20 FL
64	1		*DOOR WEATHERSTRIP O/S	Cut	185.80 FL	*185.80 FL
65	1		*DOOR CHECKER O/S	Bent	138.60 FL	*138.60 FL
66	1		*DOOR TRIM BOARD O/S	Buckled	751.10 FL	*751.10 FL
67	1		*DOOR WINDOW REGULATOR GEAR, MOTOR O/S	Bent/Jammed	646.70 FL	*646.70 FL
68	1		*DOOR LOWER SIDE SPEAKER O/S	Dented	282.20 FL	*282.20 FL
69	1		*DOOR INNER TOP MOULDING O/S	Buckled	85.30 FL	*85.30 FL
70	1		*DOOR WINDOW SWITCH O/S	Dented	138.80 FL	*138.80 FL
71	1		*DOOR REAR OUTER CENTRE PANEL O/S	Bent	444.90 FL	*444.90 FL
72	1		*DOOR REAR INNER CENTRE PANEL O/S	Repair	322.70 FL	*- FL
73	1		*DOOR REAR CENTRE PANEL INNER GARNISH O/S	Distorted	313.30 FL	*313.30 FL
74	1		*FRONT DOOR N/S	Repair	1,794.10 FL	*- FL
75	1		*DOOR WINDOW SWITCH N/S	Serviceable	138.80 FL	*- FL
76	1		*DASHBOARD	Mtg Cracked	774.40 FL	*774.40 FL
77	1		*GLOVE BOX	Cracked	297.80 FL	*297.80 FL
78	1		*DASHBOARD TOP SIDE LOWER COVER GARNISH	Mtg Cracked	221.60 FL	*221.60 FL
79	1		*DASHBOARD LOWER CENTRE GARNISH	Mtg Cracked	481.60 FL	*481.60 FL
80	1		*GEAR LEVER COVER GARNISH	Mtg Cracked	289.30 FL	*289.30 FL
81	1		*METER TOP COVER GARNISH	Mtg Cracked	323.40 FL	*323.40 FL
82	1		*AIR CON VENTILATION CASING ASSY	Cracked	3,070.10 FL	*3,070.10 FL
83	1		*AIR CON BLOWER CASING	Housing Cracked	1,025.30 FL	*1,025.30 FL
84	1		*DASHBOARD LOWER COVER GARNISH	Distorted	397.70 FL	*397.70 FL
85	1		*WIPER MOTOR, LINKAGE	Not Necessary	895.70 FL	*- FL
86	1		*BRAKE PEDAL	Repair	373.20 FL	*- FL
87	1		*BRAKE SWITCH	Serviceable	168.40 FL	*- FL
88	1		*DASHBOARD LOWER GARNISH O/S	Dented	222.10 FL	*222.10 FL
89	1		*REAR BUMPER	Repair	373.10 FL	*- FL
90	2		*REAR BUMPER SIDE RETAINER	Distorted	60.00 FL	*60.00 FL
91	1		*REAR TAIL LAMP O/S	Serviceable	256.90 FL	*- FL
92	1		*FRONT STEEL RIM O/S	Serviceable	454.70 FL	*- FL
93	1		*FRONT KNUCKLE ARM O/S	Serviceable	451.70 FL	*- FL
94	1		*FRONT KNUCKLE ARM BEARING O/S	Serviceable	270.50 FL	*- FL
95	1		*FRONT LOWER ARM O/S	Serviceable	375.10 FL	*- FL
96	1		*FRONT LOWER ARM BALL JOINT O/S	Serviceable	235.90 FL	*- FL
97	1		*FRONT UPPER ARM O/S	Serviceable	825.50 FL	*- FL
98	1		*FRONT TYRE O/S	Serviceable	320.00 FL	*- FL
99	2		*REAR INNER WHEEL BEARING	Not Necessary	238.80 FL	*- FL
100	2		*REAR OUTER WHEEL BEARING	Not Necessary	378.60 FL	*- FL
101	1		*FRONT WINDSCREEN GLASS SEALANT GUM	Necessary	60.00 FS	*40.00 FS
102	1		*FRONT WINDSCREEN GLASS INNER SEAL	Necessary	40.00 FS	*30.00 FS
103	1		*FRONT NO. PLATE	Serviceable	25.00 FS	*- FS
104	1		*CLIPS	Necessary	60.00 FS	*60.00 FS
105	1		*8 LITER RADIATOR COOLANT	Necessary	60.00 FS	*25.00 FS
106	1		*BRAKE FLUID	Necessary	25.00 FS	*25.00 FS
107	2		*DOORS SIDE MARKER STICKER	Necessary	50.00 FS	*50.00 FS
108	1		*FRONT PILLAR INNER EDGE RUBBER O/S	Distorted	157.20 FL	*157.20 FL
109	1		*FUEL LID CABLE (Supplementary)	Jammed	94.60 FL	*94.60 FL
110	1		*BONNET CABLE (Supplementary)	Jammed	87.90 FL	*87.90 FL
111	1		*DASHBOARD GUAGE METER ASSY (Supplementary)	Serviceable	1,128.70 FL	*- FL
112	1		*FLOOR PANEL TRIM CARPET (Supplementary)	Cracked	446.40 FL	*446.40 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
113	1		<b>*CLUTCH PEDAL BRACKET</b> (Supplementary)	Distorted	386.40 FL	*386.40 FL
114	1		<b>*DASHBOARD SUPPORT BEAM MEMBER</b> (Supplementary)	Bent	648.30 FL	*648.30 FL
115	1		<b>*RADIATOR COWLING</b> (Supplementary)	Repeated	266.40 FL	*- FL
116	1		<b>*FIRE WALL PANEL</b> (Supplementary)	Repair	968.70 FL	*- FL
117	1		<b>*FLOOR PANEL</b> (Supplementary)	Repair	1,882.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>54,997.80</b>	<b>37,994.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	13,669.45	9,441.00
<b>Total Parts (\$\$)</b>	<b>41,328.35</b>	<b>28,553.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TOWING OF VEHICLE TO WORKSHOP	New	130.00	100.00
2	REPAIR OF DRIVER SEAT	New	180.00	100.00
3	TO REMOVE DAMAGED WINDSCREEN AND FIXING OF SAME	New	120.00	120.00
4	TO CUT, REMOVE DAMAGED PANELS, KNOCKING, STRAIGHTENING, JACKING OF CHASIS MEMBER, DOOR PILLARS AND FLATTENING OF DENTED PORTION, WELDING OF PANELS, FIXING AND ALIGN OF PARTS OF VEHICLE. FRONT AND REAR PORTION	New	2,800.00	2,200.00
5	TO REMOVE OF DASHBOARD, METER, HARNESS WIRE, AIR CON VENTILATION CASING, BLOWER UNIT AND AIR CON SYSTEM. (HEATER AND COOLING COIL CASING UNIT) REPLACE OF PARTS, CHECK AND TO RECHARGE OF AIR CON GAS ETC	New	600.00	280.00
6	TO REMOVE TURBO INTERCOOLER, INTERCOOLER PIPES TO FACILITATE REPLACEMENT OF RADIATOR, FAN CLUTCH, FAN BLADE, FAN COWLING AND CHANGING OF AIR CON LIQUID AND SUCTION HOSE. FIXING OF SAME	New	280.00	150.00
7	REMOVE OF FRONT UNDERCARRIAGE, STEERING COLOUM AND STEERING COULPING BOX, AIR CON PIPES, FACILITATE REPAIR ON CUTTING, KNOCKING, STRAIGHTENING FLATTENING AND WELDING OF CHASIS SIDE MEMBER. CHANGE, REPLACE OF PARTS AND FIXING OF SAME	New	400.00	280.00
8	TO WHEEL ALIGNMENT AFTER REPAIR	New	60.00	60.00
9	TO TRANSFER OF DOOR LOCK, WINDOW GEAR REGULATOR, GEAR MOTOR, HARNESS WIRE TO NEW DOOR	New	140.00	60.00
10	TO RESPRAY OF FRONT, REAR AND INTERIOR DAMAGED AFFECTED PORTION	New	2,100.00	1,600.00
			<b>Gross Labour Cost (\$\$)</b>	<b>6,810.00</b>
				<b>4,950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >