

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Friday, 14 August 2020 2:40 pm
To: shchua@taichengmotor.com
Cc: SUR
Subject: GBH 3943T OD / 3879146433SG DOA - 24/06/2020
Attachments: GBH 3943T - ESTIMATE.pdf

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **GBH 3943T (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

AIG in-house surveyor reviewed, please refer to the below.

*BUMPER VERTICAL REINFORCEMENT BRACKET O/S –To check
FRONT SUPPORT PANEL – Repair
BRAKE MASTER PUMP- not damage to take out
BRAKE SERVO UNIT – not damage to take out
FRONT DOOR N/S – to repair
REAR BUMPER – Not consistent.
Labour 6 - to check (LABOUR NO.3 IN ESTIMATE)
Labour 9 - \$60.00 (LABOUR NO.7 IN ESTIMATE)
Labour 10 - \$1600.00 (LABOUR NO.8 IN ESTIMATE)

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

