

Not Authorized
 11 Sep 87
 Resurvey After Paint

TAI CHENG MOTOR VEHICLE SPRAY PAINTING
 10 ANG MO KIO INDUSTRIAL PARK 2A #01-03
 ANG MO KIO AUTOPOINT SINGAPORE 568047
 TEL: 64835595, H/P:96365090 FAX: 64835895
 Business Registration No: 234718/00E
 GST Registration No: 23-471800-E
 Email: shchua@taichengmotor.com

YOUR REF:
OUR REF:

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY #09-16
SINGAPORE 079120

ATTN: THE MOTOR CLAIM DEPT
POLICY NO: 2070064703
REG. NO: GBH3943T
OWNER: RH2S DECO CURTAINS
TYPE: TOYOTA HIACE

DATE: 28.07.20

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate cost of repair to damaged vehicle accident on 24.06.20

Description	quantity	Price	
front windscreen glass	1	\$ CM 1,379.50	✓
windscreen side moulding	1	\$ No 62.30	✓
front wiper panel garnish	1	\$ No 495.10	✓
wiper panel corner garnish o/s	1	\$ Mit 26.80	✓
corner panel top inner rubber	1	\$ Gt 33.50	✓
front bonnet	1	\$ R 756.60	✓
bonnet emblem	1	\$ No 66.20	✓
bonnet hinge	2	\$. 97.80	✓
bonnet inner lower corner rubber o/s	1	\$ Mit 41.70	✓
front grille top	1	\$ Mit 191.50	✓
front grille lower	1	\$ Mit 330.80	✓
front grille base	1	\$ Mit 491.10	✓
front bumper	1	\$ CM 496.40	✓
front bumper grille centre	1	\$ Mit 154.30	✓
front bumper fog lamp granish o/s	1	\$ No 58.10	✓
front bumper lower reinforcement	1	\$ R 304.40	✓
front bumper top reinforcement beam	1	\$ R 159.10	✓
bumper vertical reinforcement bracket o/s	1	\$ Dit 54.50	TO CHECK
front headlamp	1	\$ Br 848.70	✓
front support panel	1	\$ R 333.60	REPAIR
front brace panel	1	\$ R 43.40	X
front chassis front bracket o/s	1	\$ 422.10	?
bumper tow hook cover	1	\$ Mit 26.70	✓
air con condensor	1	\$ 1,216.10	?
radiator	1	\$ 2,317.20	?
radiator fan cowling	1	\$ 266.30	?
chassis front side member o/s	1	\$ R 1,293.70	?
air con suction pipe front	1	\$ 464.60	?
air con suction pipe rear	1	\$ 662.70	?
air con liquid pipe	1	\$ 262.70	?
air con delivery pipe	1	\$ 298.40	?
air con discharge pipe front	1	\$ 344.80	?
air con discharge pipe rear	1	\$ 582.60	?
air intercooler	1	\$ 1,358.20	X
washer tank	1	\$ 159.10	X
brake master pump	1	\$ 841.70	✓
brake servo unit	1	\$ No 1,256.90	not damage to take out
front corner panel	1	\$ R 193.90	✓
front bumper side retainer o/s	1	\$ CM 193.10	✓
air cleaner box	1	\$ Mit 637.40	✓

air intake air duct	1		\$	Ant	85.20	✓
front door harness wire	1		\$		1,587.90	?
fire wall wire harness to inner dashboard	1		\$		2,750.10	?
harness wire connector bar	1		\$	CM	84.60	✓
front outer pillar o/s	1		\$	Bu	377.10	✓
front inner pillar o/s	1		\$	Bu	360.60	✓
front step panel inner panel o/s	1		\$		422.80	?
front step panel top garnish o/s	1		\$		152.70	?
wheel arch panel o/s	1		\$	Bu	260.30	✓
wheel arch panel top garnish o/s	1		\$	Bu	275.30	✓
front pillar inner cover trim garnish o/s	1		\$		168.80	?
front pillar inner edge rubber o/s	1		\$		157.20	?
wheel arch panel edge rubber o/s	1		\$	Gr	61.40	✓
fuel accelerator pedal	1		\$		369.70	?
front door o/s	1		\$	Bu	1,794.10	✓
front door side mirror o/s	1		\$	Gr	1,015.80	✓
door outer top moulding o/s	1		\$	Bu	79.10	✓
door window glass o/s	1	Shotton	\$		432.60	✓
door glass channel rubber o/s	1		\$	Di	215.50	✓
door inner lock o/s	1		\$	Ju	492.10	✓
door lock striker o/s	1		\$	R	48.40	X
door channel o/s	1		\$		172.90	?
door hinge upper o/s	1		\$	B ₁	78.20	✓
door hinge lower o/s	1		\$	B ₂	78.20	✓
door weatherstrip o/s	1		\$	Gr	185.80	✓
door checker o/s	1		\$		138.60	?
door trim board o/s	1		\$	Bu	751.10	✓
door window regulator gear, motor o/s	1	Bill	\$		646.70	✓
door lower side speaker o/s	1		\$		282.20	?
door inner top moulding o/s	1		\$	Bu	85.30	✓
door window switch o/s	1		\$		138.80	?
door rear outer centre panel o/s	1		\$	B ₁	444.90	✓
door rear inner centre panel o/s	1		\$	R	322.70	X
door rear centre panel inner garnish o/s	1		\$		313.30	?
front door n/s	1		\$	Bu	1,794.10	✓ TO REPAIR
door window switch n/s	1		\$		138.80	?
dashboard	1		\$		774.40	?
glove box	1		\$		297.80	?
dashboard top side louver cover garnish	1		\$		221.60	?
dashboard lower centre garnish	1		\$		481.60	?
gear lever cover garnish	1		\$		289.30	?
meter top cover garnish	1		\$		323.40	?
air con ventilation casing assy	1		\$		3,070.10	?
air con blower casing	1		\$		1,025.30	?
dashboard lower cover garnish	1		\$		397.70	?
wiper motor, linkage	1		\$		895.70	?
brake pedal	1		\$		373.20	?
brake switch	1		\$		168.40	?
dashboard lower garnish o/s	1		\$		222.10	?
rear bumper	1		\$	MS	373.10	✓ NOT CONSISTENT
rear bumper side retainer	2		\$	O/S	60.00	✓
rear tail lamp o/s	1		\$		256.90	?
front steel rim o/s	1		\$		454.70	?
front knuckle arm o/s	1		\$		451.70	?
front knuckle arm bearing o/s	1		\$		270.50	?
front lower arm o/s	1		\$		375.10	?
front lower arm ball joint o/s	1		\$		235.90	?
front upper arm o/s	1		\$		825.50	?
front tyre o/s	1		\$		320.00	?
rear inner wheel bearing	2		\$		238.80	?
rear outer wheel bearing	2		\$		378.60	?
			\$		48,767.90	
parts less 25%			\$		12,191.97	
			\$		36,575.93	

Miscellaneous

front windscreen glass sealant gum
 front windscreen glass inner seal
 front no. plate
 supply of clips
 supply of 8 liter radiator coolant
 towing of vehicle to workshop
 supply of brake fluid
 repair of driver seat
 doors side marker sticker 2pc

(Bill)
 \$ M 60.00 40.00
 \$ M 40.00 30.00
 \$ M 25.00 X
 \$ M 60.00
 \$ M 60.00 25.00
 \$ M 130.00 7
 \$ M 25.00
 \$ M 180.00 7
 \$ M 50.00

labour

to remove damaged windscreen and fixing of same

 to cut, remove damaged panels, knocking, straightening, jacking of chassis member, door pillars and flattening of dented portion, welding of panels, fixing and align of parts of vehicle. Front and rear portion.

 to remove of dashboard, meter, harness wire, air con ventilation casing, blower unit and air con system (heater and cooling coil casing unit) replace of parts, check and to recharge of air con gas etc

 to remove turbo intercooler, intercooler pipes to facilitate replacement of radiator, fan clutch, fan blade, fan cowling and changing of air con liquid and suction hose. Fixing of same.

 remove of front undercarriage, steering column and steering coupling box, air con pipes, facilitate repair on cutting, knocking, straightening flattening and welding of chassis side member. Change, replace of parts and fixing of same.

 to wheel alignment after repair

 to transfer of door lock, window gear regulator, gear motor, harness wire to new door.

 to respray of front, rear and interior damaged affected portion

\$ 120.00 ✓

 \$ 2,800.00 2200

 \$ 600.00 280 TO CHECK

 \$ 280.00 150

 \$ 400.00 280

 \$ 60.00 ✓

 \$ 140.00 120 60.00

 \$ 2,100.00 1800 1600.00
 \$ 43,705.93

Total Estimated Dollars: Forty Three Thousand Seven Hundred Five And Cent Ninety Three Only.

大進汽車噴漆廠
 Tai Cheng Motor Vehicle Spray Painting
 Blk 10 Ang Mo Kio Industrial Park 2A
 #01-03 Ang Mo Kio Auto Point
 Singapore 568047
 Tel: 6483 5515 Fax: 6483 5895

CONTACT MR CHUA . AT A/P 96265090