

Survey on 28/7/20  
 Not Authorized  
 61 Simp 87  
 Recovery After Paint

**TAI CHENG MOTOR VEHICLE SPRAY PAINTING**  
 10 ANG MO KIO INDUSTRIAL PARK 2A #01-03  
 ANG MO KIO AUTOPOINT SINGAPORE 568047  
 TEL: 64835595, H/P:96365090 FAX: 64835895  
 Business Registration No: 234718/00E  
 GST Registration No: 23-471800-E  
 Email: shchua@taichengmotor.com

**YOUR REF:**  
**OUR REF:**

**DATE: 28.07.20**

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
**AIG BUILDING**  
 78 SHENTON WAY #09-16  
 SINGAPORE 079120

**ATTN: THE MOTOR CLAIM DEPT**  
**POLICY NO: 2070064703**  
**REG. NO: GBH3943T**  
**OWNER: RH2S DECO CURTAINS**  
**TYPE: TOYOTA HIACE**

Estimate cost of repair to damaged vehicle accident on 24.06.20

<u>Description</u>	<u>quantity</u>		<u>Price</u>	
front windscreen glass	1	CMA	\$ 1,379.50	✓
windscreen side moulding	1		\$ M 62.30	✓
front wiper panel garnish	1		\$ D 495.10	✓
wiper panel corner garnish o/s	1		\$ M 26.80	✓
corner panel top inner rubber	1		\$ G 33.50	✓
front bonnet	1		\$ R 756.60	✓
bonnet emblem	1		\$ M 66.20	✓
bonnet hinge	2	A/D/D	\$ 97.80	✓
bonnet inner lower corner rubber o/s	1		\$ M 41.70	✓
front grille top	1		\$ M 191.50	✓
front grille lower	1		\$ M 330.80	✓
front grille base	1		\$ M 491.10	✓
front bumper	1		\$ C 496.40	✓
front bumper grille centre	1		\$ M 154.30	✓
front bumper fog lamp garnish o/s	1		\$ D 58.10	✓
front bumper lower reinforcement	1		\$ B 304.40	✓
front bumper top reinforcement beam	1		\$ R 159.10	✓
bumper vertical reinforcement bracket o/s	1		\$ D 54.50	✓
front headlamp	1		\$ B 848.70	✓
front support panel	1		\$ B 333.60	✓
front brace panel	1		\$ R 43.40	X
front chassis front bracket o/s	1		\$ R 422.10	✓
bumper tow hook cover	1		\$ M 26.70	✓
air con condensor	1		\$ R 1,216.10	✓
radiator	1		\$ R 2,317.20	✓
radiator fan cowling	1		\$ C 266.30	✓
chassis front side member o/s	1		\$ R 1,293.70	✓
air con suction pipe front	1		\$ D 464.60	✓
air con suction pipe rear	1		\$ D 662.70	✓
air con liquid pipe	1		\$ R 262.70	✓
air con delivery pipe	1		\$ S 298.40	X
air con discharge pipe front	1		\$ P 344.80	✓
air con discharge pipe rear	1		\$ S 582.60	X
air intercooler	1		\$ S 1,358.20	X
washer tank	1		\$ P 159.10	X
brake master pump	1		\$ T 841.70	✓
brake servo unit	1		\$ D 1,256.90	✓
front corner panel	1		\$ R 193.90	✓
front bumper side retainer o/s	1		\$ C 193.10	✓
air cleaner box	1		\$ M 637.40	✓

air intake air duct	1	\$ Amt	85.20	✓
front door harness wire	1	\$ Tr	1,587.90	✓
fire wall wire harness to inner dashboard	1	\$ R	2,750.10	✓
harness wire connector box	1	\$ CM	84.60	✓
front outer pillar o/s	1	\$ Bu	377.10	✓
front inner pillar o/s	1	\$ Bu	360.60	✓
front step panel inner panel o/s	1	\$ Bp	422.80	✓
front step panel top garnish o/s	1	\$ Di	152.70	✓
wheel arch panel o/s	1	\$ Bu	260.30	✓
wheel arch panel top garnish o/s	1	\$ Bu	275.30	✓
front pillar inner cover trim garnish o/s	1	\$ Hd	168.80	✓
front pillar inner edge rubber o/s	1	\$ Di	157.20	✓
wheel arch panel edge rubber o/s	1	\$ Lt	61.40	✓
fuel accelerator pedal	1	\$ R	369.70	✓
front door o/s	1	\$ Bu	1,794.10	✓
front door side mirror o/s	1	\$ Bu	1,015.80	✓
door outer top moulding o/s	1	\$ Bu	79.10	✓
door window glass o/s	1	\$ Shatter	432.60	✓
door glass channel rubber o/s	1	\$ Di	215.50	✓
door inner lock o/s	1	\$ Tr	492.10	✓
door lock striker o/s	1	\$ R	48.40	X
door channel o/s	1	\$ Di	172.90	✓
door hinge upper o/s	1	\$ Bp	78.20	✓
door hinge lower o/s	1	\$ Bp	78.20	✓
door weatherstrip o/s	1	\$ Lt	185.80	✓
door checker o/s	1	\$ Bp	138.60	✓
door trim board o/s	1	\$ Bu	751.10	✓
door window regulator gear, motor o/s	1	\$ Bp Tr	646.70	✓
door lower side speaker o/s	1	\$ Hd	282.20	✓
door inner top moulding o/s	1	\$ Bu	85.30	✓
door window switch o/s	1	\$ Hd	138.80	✓
door rear outer centre panel o/s	1	\$ Bp	444.90	✓
door rear inner centre panel o/s	1	\$ R	322.70	X
door rear centre panel inner garnish o/s	1	\$ Di	313.30	✓
front door n/s	1	\$ Bu	1,794.10	✓
door window switch n/s	1	\$ CM	138.80	✓
dashboard	1	\$ mg CM	774.40	✓
glove box	1	\$ CR	297.80	✓
dashboard top side louver cover garnish	1	\$ CM	221.60	✓
dashboard lower centre garnish	1	\$ S	481.60	✓
gear lever cover garnish	1	\$ S	289.30	✓
meter top cover garnish	1	\$ S	323.40	✓
air con ventilation casing assy	1	\$ CM	3,070.10	✓
air con blower casing	1	\$ hu	1,025.30	✓
dashboard lower cover garnish	1	\$ Di	397.70	✓
wiper motor, linkage	1	\$ Sn	895.70	✓
brake pedal	1	\$ R	373.20	✓
brake switch	1	\$ Sn	168.40	✓
dashboard lower garnish o/s	1	\$ Red	222.10	✓
rear bumper	1	\$ R mg	373.10	✓
rear bumper side retainer	2	\$ Di	60.00	✓
rear tail lamp o/s	1	\$ Sn	256.90	✓
front steel rim o/s	1	\$ Sn	454.70	✓
front knuckle arm o/s	1	\$ Bp	451.70	✓
front knuckle arm bearing o/s	1	\$ Rn	270.50	✓
front lower arm o/s	1	\$ Di	375.10	✓
front lower arm ball joint o/s	1	\$ Sn	235.90	✓
front upper arm o/s	1	\$ Sn	825.50	✓
front tyre o/s	1	\$ Sn	320.00	✓
rear inner wheel bearing	2	\$ Rn	238.80	✓
rear outer wheel bearing	2	\$ Rn	378.60	✓
		\$	48,767.90	
parts less 25%		\$	12,191.97	
		\$	36,575.93	

Miscellaneous

front windscreen glass sealant gum  
front windscreen glass inner seal  
front no. plate  
supply of clips  
supply of 8 liter radiator coolant  
towing of vehicle to workshop  
supply of brake fluid  
repair of driver seat  
doors side marker sticker 2pc

	\$	M	60.00	405m
	\$	M	40.00	305m
	\$	S	25.00	X
	\$	M	60.00	✓
	\$	M	60.00	255m
(Bill)	\$		130.00	700l
	\$	M	25.00	✓
	\$		180.00	900m
	\$	M	50.00	✓

labour

to remove damaged windscreen and fixing of same	\$		120.00	✓
to cut, remove damaged panels, knocking, straightening, jacking of chassis member, door pillars and flattening of dented portion, welding of panels, fixing and align of parts of vehicle. Front and rear portion.	\$		2,800.00	2200
to remove of dashboard, meter, harness wire, air con ventilation casing, blower unit and air con system (heater and cooling coil casing unit) replace of parts, check and to recharge of air con gas etc	\$		600.00	280l
to remove turbo intercooler, intercooler pipes to facilitate replacement of radiator, fan clutch, fan blade, fan cowling and changing of air con liquid and suction hose. Fixing of same.	\$		280.00	150l
remove of front undercarriage, steering column and steering coupling box, air con pipes, facilitate repair on cutting, knocking, straightening flattening and welding of chassis side member. Change, replace of parts and fixing of same.	\$		400.00	280l
to wheel alignment after repair	\$		60.00	✓
to transfer of door lock, window gear regulator, gear motor, harness wire to new door.	\$		140.00	120l
to respray of front, rear and interior damaged affected portion	\$		2,100.00	1800l
	\$		<u>43,705.93</u>	

Total Estimated Dollars: Forty Three Thousand Seven Hundred Five And Cent Ninety Three Only.

大進汽車噴漆廠  
Tai Cheng Motor Vehicle Spray Painting  
Blk 10 Ang Mo Kio Industrial Park 2A  
#01-03 Ang Mo Kio Auto Point  
Singapore 568047  
Tel: 6483 5515 Fax: 6483 5895

CONTACT MR CHUA . AT A/P 96265090