

SURVY on 28/7/20
 Not Authorized
 61 Imp B?
 Return After Paint

TAI CHENG MOTOR VEHICLE SPRAY PAINTING

10 ANG MO KIO INDUSTRIAL PARK 2A #01-03
 ANG MO KIO AUTOPOINT SINGAPORE 568047
 TEL: 64835595, H/P: 96365090 FAX: 64835895

Business Registration No: 234718/00E
 GST Registration No: 23-471800-E
 Email: shchua@taichengmotor.com

YOUR REF:
 OUR REF:

DATE: 28.07.20

AIG ASIA PACIFIC INSURANCE PTE LTD
 AIG BUILDING
 78 SHENTON WAY #09-16
 SINGAPORE 079120

ATTN: THE MOTOR CLAIM DEPT
 POLICY NO: 2070064703
 REG. NO: GBH3943T
 OWNER: RH2S DECO CURTAINS
 TYPE: TOYOTA HIACE

Estimate cost of repair to damaged vehicle accident on 24.06.20

Description	quantity	Price	
front windscreen glass	1	\$ CM 1,379.50	✓
windscreen side moulding	1	\$ AC 62.30	✓
front wiper panel garnish	1	\$ PD 495.10	✓
wiper panel corner garnish o/s	1	\$ MI 26.80	✓
corner panel top inner rubber	1	\$ GT 33.50	✓
front bonnet	1	\$ B 756.60	✓
bonnet emblem	1	\$ AC 66.20	✓
bonnet hinge	2	\$ MI 97.80	✓
bonnet inner lower corner rubber o/s	1	\$ MI 41.70	✓
front grille top	1	\$ MI 191.50	✓
front grille lower	1	\$ MI 330.80	✓
front grille base	1	\$ MI 491.10	✓
front bumper	1	\$ CM 496.40	✓
front bumper grille centre	1	\$ MI 154.30	✓
front bumper fog lamp garnish o/s	1	\$ PD 58.10	✓
front bumper lower reinforcement	1	\$ B 304.40	✓
front bumper top reinforcement beam	1	\$ B 159.10	✓
bumper vertical reinforcement bracket o/s	1	\$ DI 54.50	✓
front headlamp	1	\$ B 848.70	✓
front support panel	1	\$ B 333.60	✓
front brace panel	1	\$ R 43.40	X
front chassis front bracket o/s	1	\$ B 422.10	7
bumper tow hook cover	1	\$ MI 26.70	✓
air con condensor	1	\$ P 1,216.10	7
radiator	1	\$ P 2,317.20	7
radiator fan cowling	1	\$ CM 266.30	7
chassis front side member o/s	1	\$ B 1,293.70	7
air con suction pipe front	1	\$ D 464.60	7
air con suction pipe rear	1	\$ B 662.70	7
air con liquid pipe	1	\$ B 262.70	7
air con delivery pipe	1	\$ S 298.40	X
air con discharge pipe front	1	\$ P 344.80	7
air con discharge pipe rear	1	\$ S 582.60	X
air intercooler	1	\$ S 1,358.20	X
washer tank	1	\$ S 159.10	X
brake master pump	1	\$ T 841.70	✓
brake servo unit	1	\$ PD 1,256.90	✓
front corner panel	1	\$ B 193.90	✓
front bumper side retainer o/s	1	\$ CM 193.10	✓
air cleaner box	1	\$ MI 637.40	✓

air intake air duct 1
 front door harness wire 1
 fire wall wire harness to inner dashboard 1
 harness wire connector box 1
 front outer pillar o/s 1
 front inner pillar o/s 1
 front step panel inner panel o/s 1
 front step panel top garnish o/s 1
 wheel arch panel o/s 1
 wheel arch panel top garnish o/s 1
 front pillar inner cover trim garnish o/s 1
 front pillar inner edge rubber o/s 1
 wheel arch panel edge rubber o/s 1
 fuel accelerator pedal 1
 front door o/s 1
 front door side mirror o/s 1
 door outer top moulding o/s 1
 door window glass o/s 1
 door glass channel rubber o/s 1
 door inner lock o/s 1
 door lock striker o/s 1
 door channel o/s 1
 door hinge upper o/s 1
 door hinge lower o/s 1
 door weatherstrip o/s 1
 door checker o/s 1
 door trim board o/s 1
 door window regulator gear, motor o/s 1
 door lower side speaker o/s 1
 door inner top moulding o/s 1
 door window switch o/s 1
 door rear outer centre panel o/s 1
 door rear inner centre panel o/s 1
 door rear centre panel inner garnish o/s 1
 front door n/s 1
 door window switch n/s 1
 dashboard 1
 glove box 1
 dashboard top side louver cover garnish 1
 dashboard lower centre garnish 1
 gear lever cover garnish 1
 meter top cover garnish 1
 air con ventilation casing assy 1
 air con blower casing 1
 dashboard lower cover garnish 1
 wiper motor, linkage 1
 brake pedal 1
 brake switch 1
 dashboard lower garnish o/s 1
 rear bumper 1
 rear bumper side retainer 2
 rear tail lamp o/s 1
 front steel rim o/s 1
 front knuckle arm o/s 1
 front knuckle arm bearing o/s 1
 front lower arm o/s 1
 front lower arm ball joint o/s 1
 front upper arm o/s 1
 front tyre o/s 1
 rear inner wheel bearing 2
 rear outer wheel bearing 2

\$ Am	85.20	✓
\$ Tn	1,587.90	✓
TN \$ 2,750.10	2,750.10	✓
SVC \$ 84.60	84.60	✓
\$ Buz	377.10	✓
\$ Bu	360.60	✓
\$ Rg	422.80	✓
\$ o/s	152.70	✓
\$ Bu	260.30	✓
\$ Bu	275.30	✓
\$ Hd	168.80	✓
\$ o/s	157.20	✓
\$ Cut	61.40	✓
\$ Rg	369.70	✓
\$ Bu	1,794.10	✓
Cut \$	1,015.80	✓
Shatter \$ Bu	79.10	✓
\$	432.60	✓
\$ D/s	215.50	✓
\$ Tu	492.10	✓
\$ R	48.40	X
\$ D/s	172.90	✓
\$ Rg	78.20	✓
\$ Rg	78.20	✓
\$ Cut	185.80	✓
\$ Rg	138.60	✓
\$ Bu	751.10	✓
Bel Tu \$	646.70	✓
\$ Hd	282.20	✓
\$ Bu	85.30	✓
\$ Hd	138.80	✓
\$ Bt	444.90	✓
\$ R	322.70	X
\$ o/s	313.30	✓
R \$ Bu	1,794.10	✓
SVC \$ 138.80	138.80	✓
mg \$ M	774.40	✓
mg \$ CM	297.80	✓
mg \$ CM	221.60	✓
\$ S	481.60	✓
\$ S	289.30	✓
\$ S	323.40	✓
\$ CM	3,070.10	✓
huus \$ CM	1,025.30	✓
\$ o/s	397.70	✓
NN \$ 895.70	895.70	X
\$ R	373.20	X
\$ Tu	168.40	X
\$ Rd	222.10	✓
R mg \$ 373.10	373.10	X
\$ o/s	60.00	✓
\$ Tu	256.90	X
\$ S	454.70	X
SVC \$ Rg	451.70	X
SVC \$ 270.50	270.50	X
SVC \$ 375.10	375.10	X
\$ Tu	235.90	X
\$ Tu	825.50	X
\$ Tu	320.00	X
\$ NN	238.80	X
\$ NN	378.60	X
\$	48,767.90	
parts less 25% \$	12,191.97	
\$	36,575.93	

Miscellaneous

front windscreen glass sealant gum
front windscreen glass inner seal
front no. plate
supply of clips
supply of 8 liter radiator coolant
towing of vehicle to workshop
supply of brake fluid
repair of driver seat
doors side marker sticker 2pc

\$ M 60.00 405m
\$ M 40.00 305m
\$ M 25.00 X
\$ M 60.00 ✓
\$ M 60.00 255m
\$ 130.00 700l
\$ M 25.00 ✓
\$ 180.00 900m
\$ M 50.00 ✓

(Bill)

labour

to remove damaged windscreen and fixing of same

\$ 120.00 ✓

to cut, remove damaged panels, knocking, straightening, jacking of chassis member, door pillars and flattening of dented portion, welding of panels, fixing and align of parts of vehicle. Front and rear portion.

\$ 2,800.00 2200l

to remove of dashboard, meter, harness wire, air con ventilation casing, blower unit and air con system (heater and cooling coil casing unit) replace of parts, check and to recharge of air con gas etc

\$ 600.00 280l

to remove turbo intercooler, intercooler pipes to facilitate replacement of radiator, fan clutch, fan blade, fan cowling and changing of air con liquid and suction hose. Fixing of same.

\$ 280.00 150l

remove of front undercarriage, steering coloum and steering coupling box, air con pipes, facilitate repair on cutting, knocking, straightening flattening and welding of chassis side member. Change, replace of parts and fixing of same.

\$ 400.00 280l

to wheel alignment after repair

\$ 60.00 ✓

to transfer of door lock, window gear regulator, gear motor, harness wire to new door.

\$ 140.00 ~~120~~ 60l

to respray of front, rear and interior damaged affected portion

\$ 2,100.00 ~~1800~~ 1600l
\$ 43,705.93

Total Estimated Dollars: Forty Three Thousand Seven Hundred Five And Cent Ninety Three Only.

大進汽車噴漆廠
Tai Cheng Motor Vehicle Spray Painting
Blk 10 Ang Mo Kio Industrial Park 2A
#01-03 Ang Mo Kio Auto Point
Singapore 568047
Tel: 6483 5515 Fax: 6483 5895

CONTACT MR CHUA . AT A/P 96265090

TAI CHENG MOTOR VEHICLE SPRAY PAINTING

10 ANG MO KIO INDUSTRIAL PARK 2A #01-03

ANG MO KIO AUTOPOINT SINGAPORE 568047

TEL: 64835595, H/P: 96365090 FAX: 64835895

Business Registration No: 234718/00E

GST Registration No: 23-471800-E

Email: shchun@taichengmotor.com

YOUR REF:

DATE: 07.09.20

OUR REF:

AIG ASIA PACIFIC INSURANCE PTE LTD

AIG BUILDING

78 SHENTON WAY #09-16

SINGAPORE 079120

ATTN: THE MOTOR CLAIM DEPT

POLICY NO: 2070064703

REG. NO: GBH3943T

OWNER: RH2S DECO CURTAINS

TYPE: TOYOTA HIACE

Supplementary items for damaged vehicle.

<u>Description</u>	<u>quantity</u>	<u>Price</u>	
fuel lid cable	1	In \$ 94.60	
bonnet cable	1	\$ In 87.90	
dashboard guage meter assy	1	SVC repair \$ 1,128.70	
floor panel trim carpet	1	\$ CM 446.40	
clutch pedal bracket	1	\$ Di 386.40	
dashboard support beam member	1	\$ B 648.30	
radiator cowling	1	Repair \$ 266.40	
		\$ 3,058.70	
		parts less 25%	
		\$ 764.67	
		\$ 2,294.03	

Total supplementary estimated Dollars: Two thousand Two Hundred Ninety Four And Cent Three Only.

大進汽車噴漆廠
 Tai Cheng Motor Vehicle Spray Painting
 Blk 10 Ang Mo Kio Industrial Park 2A
 #01-03 Ang Mo Kio Auto Point
 Singapore 568047
 Tel: 6483 5515 Fax: 6483 5895

MR CALLA. 96365090

TAI CHENG MOTOR VEHICLE SPRAY PAINTING

10 ANG MO KIO INDUSTRIAL PARK 2A #01-03
ANG MO KIO AUTOPOINT, SINGAPORE 668047
TEL: 64835895, HT: 96368090 FAX: 64835895
Business Registration No. 234718/005
GST Registration No. 23-471800-E
Email: taicheng@taichengmotor.com

YOUR REF:

DATE: 15.09.20

OUR REF:

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG BUILDING
78 SHENTON WAY #09-16
SINGAPORE 079120

ATTN: THE MOTOR CLAIM DEPT
POLICY NO: 2070064703
REG. NO: GBH3943T
OWNER: RH2S DECO CURTAINS
TYPE: TOYOTA HIACE

Supplementary items for damaged vehicle

Description	quantity	R	S	Price
fire wall panel	1	R	S	\$ 968.70
floor panel	1	R	S	\$ 1,882.50
				\$ 2,851.20
				parts less 25%
				\$ 712.80
				\$ 2,138.40

Total supplementary estimated Dollars. Two thousand one hundred thirty eight and cents forty only.

天進汽車噴漆廠
Tai Cheng Motor Vehicle Spray Painting
Blk 10 Ang Mo Kio Industrial Park 2A
#01-03 Ang Mo Kio Auto Point
Singapore 668047
Tel 6483 5515 Fax 6483 5895

we. CASH
9626 Sep 0