

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ben Tang

Date: 29 Jul 2020

Preliminary Advice

Vehicle No	: XD6080Z	Accident Date	: 24/07/2020
Make	: NISSAN GKB45CLBHN	Policy No.	: DMCVSNA00061472000
Assignment Date	: 28/07/2020	Excess	: S\$3,000.00
Date of Inspection	: 28/07/2020	Est. Duration of Repair	: 10
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10 TUAS AVE 18 SINGAPORE 638894		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	59,671.50
Revised Amount	:S\$	49,638.70
Check Items (Estimated)	:S\$	6,828.30
Total	:S\$	54,467.00

Lump Sum Repair	:S\$	43,600.00
-----------------	------	-----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	10,786.00
Salvage Value	:S\$	
Margin for Repair	:S\$	55,214.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :