

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007777/ETF3E2

Date: 13/08/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17542619022
Claimant Vehicle No :	SJX1690G	Insured Vehicle No :	GBG4220U
Date of Loss:	26/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202606/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJX1690G		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2244293A
Reg. Date:	31/03/2016 (Man. Year: 2016)	Chassis No:	SJNFEAJ11U1599494
Colour:	Red	Odometer:	57830 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,912.80	1,594.64	318.16	16.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,028.00	1,438.00	590.00	29.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,940.80	3,032.64	908.16	23.05
+ GST 7.00/7.00% (S\$)	275.86	212.28	63.58	23.05
Nett Amount (S\$)	4,216.66	3,244.92	971.74	23.05

INSPECTION

Date of Assignment:	28/07/2020		
Date Inspected:	30/07/2020	Inspected At:	Autolution Industrial Pte Ltd (HQ) 19 UBI ROAD 4 Singapore 408623
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2020)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJX1690G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH STAY RR BUMPER	Bent	141.00 FN	*141.00 FN
2	1		*LH STAY REAR BUMPER	Not Necessary	141.00 FN	*- FN
3	1		*REINFORCEMENT REAR BUMPER	Bent	691.50 FN	*691.50 FN
4	1		*ENERGY ABSORBER RR BUMPER	Not Necessary	141.40 FN	*- FN
5	1		*LH SIDE BRACKET RETAINER REAR BUMPER	Not Necessary	38.90 FN	*- FN
6	1		*RH SIDE BRACKET RETAINER RR BUMPER	Not Necessary	38.90 FN	*- FN
7	6		*CLIP RR BUMPER	Necessary	7.80 FN	*7.80 FN
8	1		*TOW HOOK COVER REAR BUMPER	Cut	18.80 FN	*18.80 FN
9	1		*REAR BUMPER	Dented	796.70 FN	*796.70 FN
10	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
11	1		*SENSOR-REVERSE	Shorted	250.00 FS	*250.00 FS
					Sub Total (\$\$)	2,316.00 1,925.80
					- Nett Item Discount on N Items 20.00/20.00% (\$\$)	403.20 331.16
					Total Parts (\$\$)	1,912.80 1,594.64

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR REAR END PANEL, RENEW REAR BUMPER	New	1,170.00	780.00
2	CHARGES TO SPRAY PAINTING SAME	New	700.00	500.00
3	RENEW REVERSE SENSOR	New	110.00	110.00
4	REMOVE AND INSTALL BOTH REAR COMBINATION LAMP TO FACILITATE REAR BUMPER REPLACEMENT	New	48.00	48.00
Gross Labour Cost (S\$)			2,028.00	1,438.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >